



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE **NEW DELHI- 110 001**

No. F.6/DFS/MS/School/2025/NDZ/ 1324

Dated: 19/11/2025

FIRE SAFETY CERTIFICATE

Certified that the City Convent Sec. School located at C-19, New Modern, Shahdara, Delhi-110032, comprised of ground plus two upper floors only (two separate Blocks) owned/occupied City Convent Sec. School was issued FSC vide letter No. F.6/DFS/MS/School/2022/NDZ/1258 dated 24/11/2022. The premises was re-inspected by the officer concerned of this department on dated 30/10/2025 in the presence of Sh. Aman Choudhary, Manager and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with Circular No. Circular 262-362 dated 17/01/2005 issued by the Director of Education and observed that the building/premises is fit for occupancy class 'Educational (Group-B)' with effect from ..!9.11.2.25... for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010 & also conditions printed below.

Issued on 19 11 2025 at New Delhi by

(Dr. S. K. TOMAR) DY. CHIEF FIRE OFFICER (NDZ) **DELHI FIRE SERVICE**

To:-

The Manager,

City Convent Sec. School at C-19, New Modern, Shahdara, Delhi-110032.

Copy to:-

The Dy. Director of Education, B-Block, Yamuna Vihar, Delhi- 110032

Conditions for the validity of Fire Safety Certificate

1. All the means of escape shall be kept free of all type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipment's and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipment shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.

4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.

5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.

6. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry.

7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

	7.7	ISPECTION RE		NY		
	. Name & address of the building	: City Con	vent Sec. School, C-19,	new		
		Modern, Shahdara, Delhi-110032				
2	Building is comprised of	: Ground plus two upper floors				
		(Two separate Blocks -A & B)				
- 2	5. Type of Occupancy	: Educational				
4	. Type of Case	: Renewal				
5	5. Details of Previous NOC letter	: F.6/DFS/	MS/School/2022/NDZ/12	258		
		dated- 24/	dated- 24/11/2022			
(5. Fire Safety direction letter No	 : Circular No. 262-362 dated 17/01/05 : 30/10/2025 : Deepak Kumar, ADO (Tahirpur) 				
	7. Date of Inspection					
	3. Name of the Inspecting officers					
	Name and designation of Officer	· · · · · · · · · · · · · · · · · · ·	***************************************			
	from the building side	: Sh. Amar	Choudhary, Administra	tor		
	10. Year of Construction	: 1995	/			
	11. Applicant's letter no		css@gmail.com dated	16/09/2025		
Sr.	Minimum Standards on fire	DoE Circular	Provided at Site	Remarks		
No	prevention and fire safety U/R33	2005		MR/NMI		
		Requirement				
1	Access to building.	U.S. Markey - Co.	Carlo Ca			
		town II is falled	20	1.00		
	Road width	06 m	08 m	MR		
	Gate width	N/A	N/A	N/A		
12	Width of internal road	N/A	N/A	N/A		
)2	Number, Width, Type and Arrangen	nent of Exits.				
	a. Number of Staircases					
	Upper floor block-A	01 no.	02 nos.	MR		
	Upper floor block-B	01 no.	02 nos.	MR		
	Basement	N/A	N/A	N/A		
	b. Width of Staircases					
	Upper Floor Block-A	1.50 m	1.50 m & 0.90	MR		
	a Umman Floor Dlook D	1.50m / less than	1.05 m, 0.78 m &	MR		
	Upper Floor Block-B	1.50m an	0.90 m (upto 1st			
	Basement	additional 0.75m	11001)			
	c. Protection of exits	N/A	N/A	N/A		
	SWEDNESS OF A B OLD DAVIS					
	Fire check door	N/A	N/A	N/A		
	Pressurization d. No. of continuous staircases	N/A	N/A	N/A		
	d. No. of continuous staircases to terrace	01 no.	02 nos.	MR		
	e. Width of Corridor	1.50 m	1.50 m	MD		
	f. Door Size	01 m	01 m	MR		
)3	Compartmentation.	JI M	OT III	MR		
,,,	Fire check door	N/A	N/A	N/A		
	Sealing of electrical shafts	N/A	N/A N/A	N/A N/A		
	Fire rating of shaft door	wax	AMAX	IVA		
	Water curtain	N/A	N/A	N/A		
	Fire Dampers	N/A	N/A	N/A		
	1 7 7 7	N/A	N/A	N/A		
)4	Smoke Management System.		7 - V - 34			
	Basement	N/A	N/A	N/A		
	Upper floor	N/A	N/A	N/A N/A		
)5	Fire Extinguishers.		4 W 6.4	IVA		
	C 42.4 (2.2.4). • (1.2.4)	12	10			
	Total numbers Types	12 nos.	18 nos.	MR		
	TypesIS marking	ABC /CO ₂ ISI marked	ABC /CO ₂	MR MR		
	• Lymarking	LNI marked	ISI marked	MAR		

6	First-aid-Hose Reels.								
	Total numbers on each block at								
	per 1100r	01 no.	01 no.	MR					
	Length of hose reel hose Nozzle diameter	30 m	30 m	MR					
)7	Automatic fire detection and alarming system.	05 mm	05 mm	MR					
	actection and alarming system.								
	Type of detectors	N/A	N/A	27/4					
	Location of main panel	N/A	270 1747077	N/A					
	Location of repeater panel	N/A	N/A N/A	N/A					
	Alternate source of power Hooter's	N/A	N/A	N/A N/A					
-	location	N/A	N/A						
08	MOEFA		N/A	N/A					
09	Public address System.	N/A	N/A	N/A					
10	Automatic Sprinkler System.	N/A	Provided	N/A					
	Basement	X							
	Upper floor	N/A	N/A	N/A					
	Sprinkler above false ceiling Internal Living	N/A	N/A	N/A					
11	Internal Hydrants	N/A	N/A	N/A					
	Size of riser/down-comer Number of built	100 mm	100 mm	MR					
	Number of hydrants per floor Hose Box	01 no.	01 no.	MR					
12	Yard Hydrants.	01 no.	01 no.	MR					
		1,75 - 20							
	Total number of hydrants	N/A	N/A	N/A					
13	Hose Box Pumping A	N/A	N/A	N/A					
-	Pumping Arrangements.	1	IVA						
100	Ground Level	N/A	N/A	NI/A					
	Discharge of main Pump	N/A	N/A	N/A N/A					
	Head of Main Pump Number of main pumps	N/A	N/A	N/A					
	Number of main pumpsJockey pump out put	N/A	N/A	N/A					
	> Jockey pump head	N/A	N/A	N/A					
	> Standby pump out put	N/A N/A	N/A	N/A					
	> Standby pump Head	N/A	N/A N/A	N/A					
1	Auto Starting /Manual stopping	N/A	N/A	N/A N/A					
	Pump House Access	N/A	N/A	N/A					
	Terrace Level								
	 Discharge of pump Head of the Pump 	450 LPM	450 lpm	MR					
	Head of the PumpPower supply	40 m Required	40 m	MR					
	> Auto Starting of pump	N/A	Provided N/A	MR N/A					
14				1044					
A.7.1	Underground tank capacity	N/A	N/A	N/A					
	> Draw-off connection	N/A	N/A	N/A					
- 1	> Fire service inlet	N/A	N/A	N/A					
-	> Access to tank	N/A	N/A	N/A					
	Overhead Tank capacity	5,000 Ltrs.	10,000 ltr	MR					
15	Exit Signage.	Required.	Provided	MR					
16	Provision of Lifts.	x x							
	Pressurization of Lift Shaft	N/A	N/A	N/A					
	 Pressurization of Lift lobby 	N/A	N/A	N/A					
	Communication in lift car	N/A	N/A	N/A					
	Firemen's grounding switch	N/A	N/A	N/.					
	Lift Signage	N/A	· N/A	IN/					

			N/A	N/A			
17	Standby power supply	N/A	N/A				
18	Refuge Area.						
		NI/A	N/A	N/A			
	Total area	N/A	N/A	N/A			
	Location	N/A	1977				
19	Fire Control Room						
		N/A	N/A	N/A			
	Detector system panel	N/A	N/A	N/A			
	 Flow switch panel 	100000000000000000000000000000000000000	N/A	N/A			
	PA system panel	N/A	F-24 (A114 (A114))	N/A			
		N/A	N/A	10000000			
	Battery backup	N/A	N/A				
	Building Floor Plans	N/A	N/A	N/A			
20	Special Fire Protection systems for protection of special Risks, if any:	IN/A					

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection.

he time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety required under the rule. The FSC issued vide letter no. F.6/DFS/MS/School/2022/NDZ/1258 dated safety required under the rule. The FSC issued vide letter no. F.6/DFS/MS/School/2022/NDZ/1258 dated safety required under rule 37 of the Delhi Fire Service Rule, 2010 is recommended.

Signature of the Inspecting Officer
Name :- Deepak Kumar
Designation :- A.D.O (Shd)

DO(ED) Mules/11/11/20

Dy. (60(0)02)

13/4/2r

Principal Director

by. CFS to Sessore

M, CF2/(NDZ)

m/

ADOCSKA) Sir,

F.T. selfer is pur up for your kind

signature pl.

N/D 2)

Jan 18/11/2025

City Convent Sec. School at C-19, New Modern, Shahdara, Delhi-110032