

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

No. F.6/DFS/MS/EH/2025/NDZ/ 348

Dated:

10/10/2025

## FIRE SAFETY CERTIFICATE

Certified that the M/s Daaru Wala A unit of Nivaan Infralab Private Limited, running at ground floor of DLF Galleria Mall located at Shop Np. 22, 23, 26 & 27A, DLF Galleria Mall, Mayur Vihar Phase- 1, New Delhi-110091, running at ground floor only in a building comprised of basement, ground plus two upper floors, owned/occupied by Nivaan Infralab Private Limited, have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010. and verified by the officer concerned of this department on dated 26.09.2025 in the presence of the Manager, and found that the building is fit for occupancy Class "D" "Assembly Building" (for ground floor only) w.e.f. 101025 for a period of three years, in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on 10 10 20 25 at New Delhi.

(Dr. S.K. Tomer) Dy. Chief Fire Officer New Delhi Zone

Online application Id 2025091613495 dated 19.09.2025.

Copy to: - The Executive Engineer (Building), MCD, Civic Centre, Minto Road, New Delhi.: - for information regarding use of basement and a request to ensure the occupancy as detailed above and deviation, if any.

## Conditions for validity of Fire Safety Certificate:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement shall be used as per BBL/UBBL.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

## INSPECTION REPORT

 Name & address of the building: M/s Darru Wala a unit of Nivaan Infralab Pvt. Ltd. at GF, Shop No. 22,23,26 & 27, DLF Galleria Mall, New Delhi- 110091.

2. Building is comprised of

:Basement, ground plus two upper floors

3. Type of Occupancy

: Group D (Assembly)Restaurant running at ground floor only.

4. Type of Case

:New Case (Eating House)

5. Details of Previous NOC :N/A

6. Fire Safety directives letter No :N/A

7. Date of inspection

\* :26.09.2025

8. Name of Inspecting Officers

:A.D.O. R.K.Yadav (JKP)

9. Name and designation of officers

From the building side

:Manager

10. Year of Construction

:2008

11. Applicant's letter No.

:MHA Portal ID 2025091613495 dated 19.09.2025

S. No.		um Standards on fire tion and fire safety U/R 33	BBL/NBC Requirement	Provided at site	Remarks MR/NMR			
1.	Access to building DLF Galleria Mall having separate FSC vide letter No.							
	F.6/D	FS/MS/NDZ/2023/375 dated 08	3.08.2023	Provided	MR			
		Road width	06 m	Provided	61 WANGOOD			
	•	Gate width	4.5 m	120.00				
	•	Width of internal road	N/A	N/A	IN/A			
2.	Number, Width, Type & Arrangement of Exits							
	a. Nun	nber of staircases	Res	taurant at Ground floor on				
	•	Upper Floors	N/A	N/A	The second control of			
	•	Basements	N/A	N/A	N/A			
	Access to F.6/DFS/  Rooman Roo	th of staircases						
	•	Upper Floor	N/A	N/A	GF only			
	•	Basements	N/A	N/A	N/A			
	a Dece	action of exits	00,7000000		MR MR N/A  y  GF onl N/A  N/A  N/A  N/A  N/A  N/A  N/A  N/A			
	C. Proi	Fire check door	N/A	N/A	N/A			
		Pressurization	N/A	N/A	N/A			
	1		14/14	100000				
	d. No	of continuous staircases to	N/A	N/A	N/A			
	100.000		N/A	N/A	N/A			
	e. Width of Corridor				MD			
	f. Do	or Size	1.50 m × 2	1.50 m × 2	IVIIX			
3.	Compartmentation				1 500			
	•	Fire check door	N/A	N/A				
		Sealing of electrical shafts	N/A	N/A	N/A			
		Fire Rating of shaft door	N/A	N/A	N/A			
		Water Curtain	N/A	N/A	N/A			
	1	Fire Dampers	N/A	N/A	N/A			
4.	Smoke	Management System						
555		Basements	N/A	N/A	N/A			
-		Upper floors	Required	Provided	MR			
5.		(A)						
٥.			08 no.'s	Provided	M/R			
	•	Total numbers in restaurant	ABC/CO <sub>2</sub>	ABC- 04 & Co2- 04				
	•	Types	ISI marked	Provided				
	•	IS marking			M/R			
6.	First-Aid Hose Reels Common with the DLF Galleria Mall							
		Total numbers at each floor	05 Nos.	Provided	M/R			
		Length of hose reel hose	30 mtrs	Provided	M/R			
		Nozzle diameter	5 mm	Provided	M/D			

N72

	Automatic fire detection and alarming s	vstem in restaurant					
	Automatic fire detection and alarming 5	Required	Provided	MR 🧼			
	Type of detectors Smoke/Heat     SMoin Panel	Required	Provided	MR			
	Location of Main Panel     Location of Repeater Panel	N/A	N/A	N/A			
	Alternate source of power	Required	Provided	MR			
	Hooters' Location	Required	Provided	MR			
		Required	Provided	M/R			
	MOEFA	N/A	N/A	N/A			
	Public Address System	olic Address System  Common with the DLF Gal					
	Automatic Sprinkler System	Required	Provided	MR			
-	Basement	Required	Provided	MR			
- 1	Upper floors	Required	Provided	MR			
	Sprinkler above false ceiling	Common with the DLF	Calleria Mall				
	Internal Hydrants	Provided	M/R				
l.	s: C.:/down-comer	150 mm	Provided	M/R			
	Number of hydrants	05 no's	Provided	M/R			
	Hose Box	05 no's	Floyided	4			
			217.	N/A			
2.	Yard Hydrants	N/A	N/A	N/A			
	Total number of hydrants     Uses Box	N/A	N/A	IVA			
	Hose Box     Common with the DLF Galleria Mall						
3.	Pumping Arrangements	~*************************************					
-	Ground Level	4500 LPM	Provided	MR			
	Discharge of main Pump	60 m	Provided	MR			
	Head of Main pump		Provided	MR			
	> Number of main pumps	02 450 LPM	Provided	MR			
1	> Jockey Pump out put		Provided	MR			
	Jockey pump head	60 m	Provided	MR			
	Standby Pump out put	4500 LPM	Provided	MR			
	<ul> <li>Standby Pump Head</li> <li>Auto Starting/Manual</li> </ul>	60 m	Provided	MR			
	Stopping	Required		MR			
		Required	Provided	IVIIC			
	> Pump House Access			M/R			
	Terrace level	900 LPM	900 LPM	M/R M/R			
	> Discharge of pump	60 m	40 m	M/R			
	<ul><li>➢ Head of the pump</li><li>➢ Power Supply</li></ul>	Required	Provided	0.0000000			
	➤ Power Supply  ➤ Auto Starting of pump	Required	Provided	M/R			
		Common with t	he DLF Galleria Mall				
14.	Captive water Storage for me again.						
	Underground tank capacity	4,50,000 ltrs	Provided	MR			
	Draw-off connection	Required	Provided	MR			
	<ul> <li>Fire service inlet</li> <li>Access to tank</li> </ul>	Required	Provided	MR			
	Overhead Tank capacity	Required 20,000 ltrs	25,000 ltrs	MR			
			Provided	M/R			
15.	Exit Signage.	Required	Flovided	THE STATE OF THE S			
16.	Provision of Lifts						
-	Pressurization of Lift Shaft	N/A	N/A	N/A			
1	Pressurization of Lift lobby	N/A	N/A	N/A			
	Communication In lift Car	N/A	N/A	N/A			
1	<ul> <li>Fireman's Grounding Switch</li> </ul>	N/A	N/A	N/A			
	Lift Signage	N/A	N/A	N/A			
17.	Standby power supply	Required	Provided	M/R			

+

Transaction of the same	N/A	N/A	N/A
<ul><li>Total Area</li><li>Location</li></ul>	N/A	N/A	N/A
ire Control RoomCommon with		Provided	M/R
<ul> <li>Detector System Panel</li> </ul>	Required		M/R
<ul> <li>Flow Switch Panel</li> </ul>	Required	Provided	20/11/20/0
Danel	Required	Provided	M/R
Battery backup	Required	Provided	M/R
Building Floor Plans	N/A	N/A	N/A
pecial Fire Protection System for rotection of special Risks, if any:	Required	Manually Operated CO2 Fire extinguishers Provided	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Note: - The restaurant running at ground floor of DLF Galleria Mall building comprised of basement, ground plus two upper floors. Earlier, DLF Galleria Mall building having separate FSC issued by this department vide letter No. F.6/DFS/MS/NDZ/2023/375 dated 08.08.2023.

Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under Rule 35 of the Delhi Fire Service Rule 2010.

Signature of the Inspecting Officer
Name- R.K. Yadav
Designation: - ADO (JKP)

DYCFO(1002)

02 10 mm

Principal Director

Cos to

80 (348) 1844

10/10/21

hetter .

put cup

sign plea

DYCFO(NOS)

10/10/52

10 40 2cm

led