



Dated 15/01/2025

No. F6/DFS/MS/INDUSTRIAL/NDZ/2025/ 26

To,

Mr. Sanjay Kumar (Secretary),  
Dalit Prahari  
D - 39/40, Kondli Colony,  
Kondli, Delhi - 110096

**Subject: - Regarding grant of Fire Safety Certificate in r/o M/s Dalit Prahari located at H - 57, Sapera Basti, Village- Gharoli, Delhi - 110096.**

Sir,

This has a reference to Outdoor Diary No. 10691 dated 24/12/2024, on the subject cited above. In this connection, it is to inform you that premises was inspected by the officer concerned of this department on 03/01/2025 in the presence of Mr. Sandeep Kumar (Manager) and observed that building comprised of ground floor.

**Following shortcomings were observed during time of inspection:**

1. A single door of 2.10 meter width is provided against the requirement of two doors of width 1.50 meter each.
2. Fire Extinguisher not provided.
3. First-Aid-Hose Reel at each floors not provided.
4. MOEFA are not provided.
5. Terrace level fire pump capacity of 450 LPM not provided.
6. Overhead tank of capacity 10,000 liters not provided.
7. Exit & floors Signage's not provided in strategic location in the building.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(ATUL GARG)  
DIRECTOR

o/c DELHI FIRE SERVICE

**Copy to:-**

1. Mr. Sanjay Kumar (Secretary), Dalit Prahari at D - 39/40, Kondli Colony, Kondli, Delhi - 110096.
2. Mr. Sandeep Kumar (Manager), Dalit Prahari located at H - 57, Sapera Basti, Village- Gharoli, Delhi - 110096.
3. The Exective Engineer (Bldg), Municipal Corporation of Delhi, Plot no. 419, Patparganj Industrial Area, Delhi - 110092.