

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F.6/DFS/MS/EH/2025/SZ/ 54

Dated:14/02/2025

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name and style of M/s Delhi Barbeque located at Upper Ground Floor, A Block, Khasra No 383/2/1, 384/1, 384/3, NH-8, Mahipalpur Extension, New Delhi-110037, was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/EH/2022/SZ/24 dated 02.02.2022. The restaurant premise was inspected by the officer concerned of this department on 06.02.2025 in the presence of Sh. Gaurav Sharma and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class D "Assembly Building (Restaurant) for Upper Ground floor only with effect from .14./.02.2.2025 and valid upto 31.03.2028 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 14 / 62. /2025 at New Delhi by

DIRECTOR DIRECTOR Delhi Fire Service

Copy to:-

1. The Commissioner, North, MCD, Civic Centre, New Delhi

 The Addl. Commissioner of Police (Lic), 1st floor, PS Defence Colony, New Delhi Online ID no. 2025012701059 dated 27.01.2025.

3. M/s Delhi Barbeque Located at Upper Ground Floor, A Block, Khasra No 383/2/1, 384/1, 384/3, NH-8, Mahipalpur Extn, New Delhi-110037.

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

1		Wanne	TION PERCE	nti rotidi -			
		307030000000000000000000000000000000000	TION REPORT	140 1 1 10	,		
1	Name	& Address of the Building	M/s Delhi Barbeque at Ground floor, A Block Khasra No 383/2/1, 384/1, 384/3, NH-8, Mahipalpur Extn, New Delhi-37. Group-D Assembly Building. (Restaurant is running at Upper G F only)				
2	Туре	of Occupancy					
3	Build	ng Comprised of		G F, Upper GF, & 03 U			
4		of Case	Renewal				
5		s of Previous NOC	Restt F6/DFS/MS/EH/2022/SZ/24 dated 02.02.2022				
1	2000	37710413437730	(Hotel - F.6/DFS/MS/GH/2021/SZ/455 Dt. 30/09/2021)				
6	Fire S	afety Directives Letter No	Nil				
7		f Inspection	06.02.2025				
8		of the Inspecting Officers	ADO (RN)				
9		& Designation of Officers	Sh. Gauray Sharma				
		he building side	on Guara on and				
10		of construction	2009		117		
11		ant letter No.	Online ID No 2025012701059 dated 27.01.2025				
S. No.	Minir	num standards on Fire Prevention ire Safety U/R 33	Requirement/ Existing Fire Protection	Provided at Site	Remarks MR/NMR		
1	Acces	s to Building.	(Hotel - F.6/DFS/M	IS/GH/2021/SZ/455 Dt.	30/09/2021)		
	•	Road width	Restt. within Hotel	Provided	MR		
	•	Gate width		N/A	N/A		
	•	Width of internal road	-	N/A	N/A		
2		er, width, type & arrangement of ex	its.)/ ' · '	TTesal		
		imber of Staircase	Restt within Hotel	Maintained by Taurus As above	MR		
		Upper floors. Basement floor.	N/A	N/A	N/A		
		idth of Staircase		Maintained by Taurus			
		Upper floors	NA NA	As above	NA		
		Basement floor	NA	As above	NA		
	c) Pr	otection of exits	Provided &	Maintained by Taurus			
	>		NA	As above	NA		
		Pressurization	NA	As above	NA NA		
		o of continuous staircase to terrace	NA N/A	As above N/A	NA N/A		
		idth of corridor or size	02 required	2.0 m& 1.5 m	MR		
,	-/	artmentation.		Maintained by Taurus			
3	Comp	Fire check door.	NA NA	As above	NA		
		Sealing of electrical shafts.	NA	As above	NA		
		Fire rating of shaft door.	NA	As above	NA		
		Water curtain	NA	As above	NA		
	•	Fire dampers.	NA	As above	NA		
4	Smoke	Management system.		Maintained by Taurus			
	•	Basement	NA D	NA	N/A		
	•	Upper floors	Required	Exhaust Fans Provided	MR		
5	Fire L	xtinguishers.	Required	10 Nos	MR		
	•	Total numbers	ABC/CO ₂	ABC & CO ₂	MR		
	•	Types ISI Marking	Required	Provided	MR		
•	First A	id Hose Reels.		Maintained by Taurus			
6	FIRST	Total numbers on each floor.	One near Restt	As above	MR		
		Length of hose-reel hose.	30m	As above	MR		
		Nozzle Diameter	5mm	As above	MR		
7	Autom	atic fire detection & alarming systen	n. (Provided & Ma	intained by Taurus Ho	tel		
	•	Type of detectors	NA	As above	NA		
	•	Location of Main Panel	NA NA	As above	NA		
	•	Location of Repeater Panel	NA NA	As above	NA		
	•	Alternate source of power	NA NA	As above	NA		
	•	Hooter's location	NA NA	As above	NA		
		Had					
8	MOEF	A Address System	Required N/A	Provided As above	MR MR		

	V	h
_	-	+

0	Automatic Sprinkler System	Provided	& Maintained by Tauri	is Hotel	
	Basement	NA	As above	Y.A	
	Ground floor.	NA	As above	NA	
	AND	NA	As above	NA	
	Sprinkler above false ceiling	Provided & Maintained by Taurus Hotel			
1	Internal Hydrants.		As above	NA NA	
	Size of Riser/Down-comer	NA NA	As above	NA	
	 Number of Hydrant per floor 	NA	As above	NA	
	Hose box.	NA	TAKE MARKET	332	
12	Yard Hydrants.	Provided & Maintained by Taurus Hotel			
_	Total number of hydrants.	N/A	As above	N/A	
	Hose box.	N/A	As above	0.000	
12	Pumping arrangements.	Provided &	Maintained by Taurus	Hotel	
13		Common pumping arrangements for entire bidg			
		1620 LPM	1620 LPM	MR	
	Discharge of main pump.Head of main pump.	60m	60m	MR	
	The letter of the second control of the seco	02 Nos.	02 Nos.	MR	
		180 LPM	180 LPM	MR	
		60m	60m	MR	
	The same of the sa	1620 LPM	1620 LPM	MR	
	a mileti reca	60m	60m	MR	
	A demund Stonning	Required	Provided	MR	
	AND THE STORY OF T	Required	Provided	IVII	
				MR	
	Terrace Level	225lpm	225lpm	MR	
	> Discharge of pump.	40m	40m	MR	
	Head of pump.Power supply.	Required	Provided	MR	
		10220	Provided	2011/01/25	
	Auto starting of pump.	Provided & Maintained by Taurus Floter			
14	Captive water storage for fire fighting.	NA	1,00,000 ltrs	NA	
	 Underground tank capacity. Draw-off connection. 	NA	As above As above	NA	
	> Fire Service Inlet.	NA NA	As above	NA	
	> Access to tank.	NA	Provided	MR	
	Overhead tank capacity.	2,500 ltrs	Details and the second of the	MR	
		Required	Provided	155	
15	Exit Signage. Provision of Lifts.	Provided & Maintained by Taurus Hotel As above NA			
16	Pressurization of lift shaft.	NA	As above	NA NA	
	Pressurization of lift lobby.	NA NA	As above As above	NA	
	Communication in lift car.	NA NA	As above	NA	
	• Fireman's switch.		, and	NA	
	Lift signage.	NA	As above		
17	Standby Power Supply	Required	Provided	MR	
18	Refuge Area			recession and	
.0	Total area	N/A	N/A	N/A	
	• Location	N/A	N/A	N/A	
9	Fire Control Room.	Provided & N	Maintained by Taurus F	lotel	
_	Detector system panel.	N/A	As above	N/A	
	Flow switch panel.	N/A	As above	N/A	
	PA system panel.	N/A	As above	N/A	
	Battery backup.	N/A	As above	N/A	
	Building floor plan.	N/A	As above	N/A	
0	Special Fire Protection System for the	N/A	As above		
U	Protection of special Risk, if any.		1 13 audve	N/A	

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no. F6/DFS/MS/EH/2022/SZ/24 dated 02.02.2022, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Signature of the Inspecting Officer

Name: Sh. C.L. Meena Designation: ADO (RN)

DO (South)

fo/(rus)

1 20 20 25

Develop

Ant to

As approved F.T. Letter is Put up for your signature Pl.

Director (18) M/7/8

Whoodes 14/02/25 13|02|2025

A DO(RM)