

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001



No. F6/DFS/MS/School/WZ/2025/ 40 | To.

Dated: 15/05/2025

The Principal, Delhi International Junior School, Pocket- H-3, Sector-11, Rohini, Delhi-110085.

Sub:Issue of FSC in r/o Delhi International Junior School, Pocket- H-3, Sector-11, Rohini, Delhi-110085.

Sir,

Kindly refer to letter received in this department through outdoor diary no. 14065 dated 04.03.2025 on the subject cited above. The premise was inspected by the concern nominated authority of this department on 06.05.2025, in presence of Mrs. Anita to ascertain the availability and operability of the fire prevention and fire safety measures. The following shortcomings were observed:

- 1. The width of alternate Staircase is 1.05 mtr against the required width of 1.50 mtr.
- 2. FCD found removed in staircase of basement.
- 3. Alternate staircase in basement found removed.
- 4. The required exit signage are not provided.
- 5. Fire Pump auto-start was not working.
- 6. 3,000 ltrs Over Head water captive tank provided against the required capacity of 20,000 ltrs
- Building is not matching with approved building plans.

In this regard as stipulated in sub Rule (5) of Rule 35 of DFS Act-2007 & Rules 2010 it is advised the applicant to apply with a fresh application for grant of fire safety certificate under sub-rule (2) on Form "I" and it shall be accompanied with a certificate from the architect and owner or occupier that all the fire prevention and fire safety measures are duly complying with the requirements as communicated under sub-rule (4) above, for further consideration in this regard. The web links for DFS Act-2007/ Rules 2010 & Form "I" are as under:

http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms

Yours faithfully

DIRECTOR Ph; 011-23414000

> OK OK