

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUATERS: DELHI FIRE SERVICE: NEW DELHI-110001



No. F.6/DFS/MS/GH/2025/SZ/ 1733

Dated: 25 /9 /202

To

Sh. S.S. Gondane, Chief Administrative Officer, Vikram Sarabhai Bhawan, 2nd Floor, North Wing, Anushakti Nagar, Mumbai–400094

Sub: Regarding issuance of Fire Safety Certificate in r/o "Dhruva Atomic Energy Guest House"

situated at Kidwai Nagar West, New Delhi.

Sir,

This has a reference to your letter No. DCSEM/CAO/Misc./2025/77 dated 23/07/2025 received in this office vide diary No. 195/PD dated 30/07/2025, on the subject cited above. In this connection, the said premise was visited by the officer concerned of this department on 18/09/2025 in the presence of Mr. Vivek Kumar (Technician) to verify the compliance of shortcomings earlier issued vide letter No. F6/DFS/MS/GH/2023/SZ/1874 dated 01/09/2023 and observed that shortcomings are not yet fully complied.

In view of the above, issuance of fire safety certificate cannot be considered at this stage. The occupancy of the premises in the absence of requisite fire safety arrangements/certificate shall be at the risk and liability of the owner/occupier/management. Further, you are requested to depute responsible officer/official to facilitate the inspection.

Yours faithfully,

(Virendra Singh) Chief Fire Officer

Delhi Fire Service

Copy to: -

1. The OSD, DAE, DAE Branch Secretariat, 145/A, South Block, New Delhi-110011





GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/GH/2023/SZ/ 1874

Dated: 0 / / 0 9 /2023

To,

Authorized Signatory, D. A. E. Guest House, Kidwai Nagar (West), New Delhi-110016.

Subject: Inspection Report in r/o D.A.E. Guest House, Kidwai Nagar (West), New Delhi-16.

Sir,

Please refer to your application no. 080/2015_OCC on the subject cited above, in this connection, it is to inform you that the said premises was re- inspected by the team of officers concerned of this department on 18/08/2023 in the presence of Mr. Anshumaan Shukla (SOD) from fire safety point of view. The building comprised of Basement+ Ground Floor+ Three Upper Floors only.

Following shortcomings were observed during the time of inspection:-

- 1. The width of staircases are less than the proposed width of 1.5m & 0.875m.
- 2. Terrace Fire pump of 1620 LPM still not provided.
- 3. Fire Check doors not provided of the building as per clause 7.31 of UBBL 2016.
- 4. Carbon Monoxide Detector not Provide as per clause 7.31 of UBBL 2016.
- 5. Fire Fighting pumps are not auto mode.

In view of above, the application for issuance fire safety certificate is rejected .the occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The licensing authority/statutory authority may take suitable necessary action as deemed fit.

ATUL GARG

Delhi Fire Service

Copy to :-

 The Addl. Commissioner of Police (Lic), Licensing Unit, 1st Floor, Police Station, Defence Colony, New Delhi-110049.