

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/Mall/2025/SZ/4 23

Dated: 15 /09 ... /2025

FIRE SAFETY CERTIFICATE

Mandela Marg, Vasant Kunj, New Delhi 110070 comprised of two Tiers Basement, Lower Ground, Upper ground, First Floor & Projection Room owned/occupied by DLF Promenade Limited was issued FSC by this department vide letter No. F6/DFS/MS/Mall/2022/SZ/464 dated 19/10/2022. The premise was re-inspected by the officer concerned of this department on 25/08/2025 in the presence of Mr. Anupam Sharma and found that the building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that the premise is fit for occupancy class "Mixed (Mercantile & Assembly) with effect from 15/06/2025 for period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued 15 09 /2025 at New Delhi by

(VIRENDRA SINGH) CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to: -

- The Executive Engineer Bldg./HQ, Delhi Municipal Corporation, 9th Floor, Civic Centre, Minto Road, New Delhi 110002.
- The Building Manager M/s DLF Promenade Mall situated at Plot No 3, Nelson Mandela Marg, Vasant Kunj, New Delhi 110070

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. The basement shall be used as per the provisions of BBL /NBC Part- IV.
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.



MR

Provided

30m

5_{mm}

Nozzle diameter

Automatic fire detection and alarming system

INSPECTION REPORT & address of the building: DLF Promenade Mall, Plot No.3, Nelson Mandela Road, Vasant Kunj type of Occupancy New Delhi - 110070 : Mixed Occupancy (Mercantile &Assembly) Type of Case : Renewal Comprised of : 2 tiers Basement + LG + UG + 1st Floor + 2nd Floor (Projection Room) Details of Previous NOC : F6/DFS/MS/Mall/2022/SZ/464 dated 19/10/2022 Fire Safety directives letter No : F6/DFS/MS/BP/2022/88 dated 02/03/2022 Date of inspection : 28/08/2025 Name of Inspecting Officer : ADO (BCP) Name and designation of officers From the building side : Mr. Anupam Sharma 10. Year of Construction : 2005 11. Applicant's letter No. : DFS Outdoor diary No 5240 dated 25/08/2025 Minimum Standards on fire prevention and S. BBL/NBC Provided at Remarks fire safety U/R 33 No. Requirement site MR/NMR Access to building 1. Road width 9m Provided MR Gate width 5m Abut on Road MR Width of internal road 6m Provided MR Number, Width, Type & Arrangement of Exits 2. a. Number of staircases Upper Floors 19 Nos Provided MR Basements 29 Nos + 3 Ramps Provided MR b. Width of staircases 1.5m No's MR(old case) Upper Floor 1.5m & 4 No's of 1.10-1.48m 1.5m No's MR(old case) Basements 1.5m & 5 No's of 1.43-1.48m c. Protection of exits Fire check door Required Provided MR Pressurization Required Provided MR d. No. of continuous staircases to terrace 4 Nos Provided MR e. Width of Corridor 1.5m Provided MR f. Door Size 2m Provided (final exit) MR 3. Compartmentation Fire check door Required Provided MR Sealing of electrical shafts Required Provided MR Fire Rating of shaft door Required Provided MR Water Curtain Required Provided MR Fire Dampers Required Provided MR 4. Smoke Management System Basements 30 ACPH M. V. Provided MR Upper floors MR 12 ACPH M. V. Provided 5. Fire Extinguishers Total numbers MR 290 No's 240 No's Types ABC/W.CO₂/CO₂ MR 210/50/30 No's IS marking ISI marked MR Yes 6. First-Aid Hose Reels Total numbers on each floor No's MR Basement & 12 Provided for Upper No's MR Provided Floors Length of hose reel hose

_	• Type of detectors			आज़ादी का अमृत महोत्य		
	• Location of Main Panel	Smoke/Heat		Provided	MK	
	• Location of Repeater Panel	Required		asement 1	MR	
	Alternate source of power	NA		TV Room-B1	TA	
	Hooters' Location	Required		VO. W. NOVEMBER SERVICES	MR	
8.	MOEFA	Dan' 1			MR	
9.			Tiovided		MR	
	Public Address System	Required Provided		MR		
10.	Automatic Sprinkler System	Required	P	Provided	MIK	
	 Basement 	n i i			1 1/P	
	 Ground Floor 	Required Required		rovided	MR	
	 Sprinkler above false ceiling 			rovided	MR	
11.	Internal Hydrants	Required	Required Provided		MR	
	Size of riser/down-comer					
	Size of fiser/down-comer	100mm		rovided	MR	
	 Number of hydrants per floor 	20 No's at Basement of 12 No's for Upper Floors				
	of flydrams per floor			Provided	MR	
	Hose Box	20 No's at Basen	nent &		100	
12.	100 V200 E-10 1	12 No's for Upper	Floors	Provided	MR	
12.	Yard Hydrants	_		10,		
	Total number of hydrants	13 Nos	Pro	ovided	MR	
	Hose Box	13 Nos		ovided	MR	
13.	Pumping Arrangements	1440 St. 25 - 1	. A.			
	 Ground Level 	J. W.			+	
	Discharge of main Pump	4500 LPM	Provided		MR	
	➤ Head of Main pump	70m		vided	MR	
	Number of main pumps	2 Nos		vided		
	> Jockey Pump out put	180 LPM		vided	MR	
	> Jockey pump head	70m			MR	
	➤ Standby Pump out put	4500 LPM		vided Provided	MR	
	> Standby Pump Head	70m	Contraction of the contract of		MR	
	➤ Auto Starting/Manual Stopping	Required			MR	
	> Pump House Access	Required		vided	MR	
	Terrace level	Required Provided		vided	MR	
	> Discharge of pump	NA				
	> Head of the pump	NA NA		A	NA	
	> Power Supply			Α	NA	
	> Auto Starting of pump	NA NA		A	NA	
	\U	NA	NA		NA	
14.	Captive Water Storage for fire fighting	4.60.000 =				
	Underground tank capacity	4,60,000 Lts	Provided		MR	
	> Draw-off connection > Fire service inlet	Required	Prov	37	MR	
	Access to tank	Required	Provi		MR	
	Overhead Tank capacity	Required	Provi		MR	
		30,000 Lts.	30,000		MR	
15.	Exit Signage.	Required	Provi	ded	MR	
	isian of Lifts.				will	
16.	regization of Lift Shall	Required	Provi		MD	
	-igotion of LIII 1000y	Required	Provid		MR	
	i-ofion in iiii Cai	Required	Provid		MR	
	Communication in the Carlot Fireman's Grounding Switch	Required	Provio	ded	MR	
	• Lift Signage	Required	Provid	2500000	MR	
		Required	Provid	274	MR	
	Standby power supply				MR	
17.	a zo Area.	NA	NT.			
18.	Refuge Para Total Area	INA	NA			

आज़ादी क अमृत महोत्सव Location NA Fire Control Room NA Detector System Panel Flow Switch Panel Required Provided MR PA System Panel Required Provided MR Batter backup Required Provided **Building Floor Plans** MR Required Provided MR Special Fire Protection System for Protection Required Provided MR of special Risks, if any: Required FE-36 flooding MR system provided for LT & HT Panels The fire protection system provided in the building were randomly checked and found functional at the time of inspection. Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/Mall/2022/SZ/464 dated 19/10/2022, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended. Accordingly, DFA is put up for approval. Signature of Inspecting Officer Name: Sh. Rajesh Kumar Designation: ADO (BCP) DO (South)

Do (south) Sport up for signature please.

As appeared, F.G. Suffer is put up for signature please.

[multiplease]