

No. F.6/DFS/MS/School/2025/SZ/ 674

Dated: 19/05/2025

FIRE SAFETY CERTIFICATE

Certified that the D.T.E.A. Sr. Sec. School situated at B-1, Janakpuri, New Delhi- 110058, comprised of ground plus two upper floors, owned/occupied by Delhi Tamil Education Association Regd. was issued FSC by this department vide letter No. F.6/DFS/MS/School/2021/SZ/953 dated 24.11.2021. The school building was re-inspected by the officer concerned of this department on dated 06.05.2025 in the presence of Principal, and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises (ground plus two upper floors) is fit for occupancy class "Educational" w.e.f. 1905/2025 for a period of three years in accordance with Rule 36 unless, renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed as below. Issued on 19 05 2025 at New Delhi by.

Director Delhi Fire Service

n

of

id

ed

rs

th

i

Copy to: -

Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

The Principal, D.T.E.A. Sr. Sec. School situated at B-1, Janakpuri, New Delhi- 110058. . 2.

Conditions for the validity of fire safety certificate: -

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.

2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.

- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.



INSPECTION REPORT

1. Name & address of the building : D.T.E.A. Sr. Sec. School, B-1, Janakpuri, New Delhi-58.

2. Building is comprised of : Ground plus Two upper floors

3. Type of Occupancy : Educational4. Type of Case : Renewal

5. Details of Previous NOC letter : F.6/DFS/MS/School/2021/SZ/953 dated 24.11.2021

6. Fire Safety Circular No. : NBC Part-IV
7. Date of Inspection : 06.43.2025 4
8. Name of the Inspecting officers : ADO R.K. Yadav

9. Name and designation of

Officer from the building side : Principal 10. Year of Construction : 2005

11. Applicant's letter No : Form 'J' dated Nil, outdoor dairy No. 354 dated 08.04.2025

Sr. No.	Minimum Standards on fire prevention and fire safety U/R33	Requirement	Provided at Site	Remarks			
1	Access to building						
	Road width	06 M	06 M	MR			
	Gate width	05 M	05 M	MR			
	Width of internal road	N/A	N/A	N/A			
2	Number, Width, Type and Arrang	200 000 00					
	a. Number of Staircases						
	Upper Floor	02 Nos.	02 Nos.	MR			
	Basement	N/A	N/A	N/A			
	B. Width of Staircases	477.2					
	Upper Floor	1.5 M	1.5 m each	MR			
	Basement	N/A	N/A	N/A			
	c. Protection of exits						
	Fire check door	N/A	N/A	N/A			
	Pressurization	N/A	N/A	N/A			
	e. No. of continuous staircases to	2 Nos	2 Nos	MR			
	terrace	1.5 M	1.5 M	MR			
	g. Width of Corridor	1.0 M	1.20 M	MR			
	h. Door Size	110 112		34.75			
3	Compartmentation.						
	Fire check door	N/A	N/A	N/A			
	 Sealing of electrical shafts 	N/A	N/A	N/A			
	Fire rating of shaft door	N/A	N/A	N/A			
	Water curtain	N/A	N/A	N/A			
	Fire Dampers	N/A	N/A	N/A			
4	Smoke Management System.						
	Basement	N/A	N/A	N/A			
	Upper floor	N/A	N/A	N/A			
5.	Fire Extinguishers						
	Total numbers	06 Nos.	06 Nos.	MR			
	 Types 	ABC & Co2	ABC & Co2	MR			
	IS marking	ISI marked	ISI marked	MR			
1	First-aid-Hose Reels.	.1					
+	Total numbers of each floor	1 Nos	Provided	MR			
- 1	 Length of hose reel hose 	30 M	Provided	MR			
- 1				1411/			

	Type of detectors	N/A	N/A				
	Type of detectors	N/A N/A	N/A N/A				
	Location of main panel Location of main panel	N/A	N/A N/A	N			
	Location of repeater panel Alternate source of power.	N/A	N/A	N			
	 Alternate source of power Hooter's location 	N/A	N/A	N			
		N/A	N/A	. N			
Į.	MOEFA		- 1	N/			
).	Public address System.	N/A	N/A				
0	Automatic Sprinkler System.	N/A	N/A	N/A			
	Basement	N/A	N/A	N/A			
	upper floor	N/A	N/A	N/A			
	sprinkler above false ceiling	N/A	N/A	N/A			
11	Internal Hydrants						
	size of riser/down-comer	N/A	N/A	N/A			
	Number of hydrants per floor	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
12	Yard Hydrants.						
	•	N/A	N/A	N/A			
	Total number of hydrants Hose Box	N/A	N/A	N/A			
	100000						
13	Pumping Arrangements.	N/A	N/A	N/A			
	Ground Level	N/A N/A	N/A	N/A			
	 Discharge of main Pump 	N/A	N/A	N/A			
	> Head of Main Pump	N/A	N/A	N/A			
	> Number of main pumps	N/A	N/A	N/A			
	> Jockey pump out put	N/A	N/A	N/A			
	> Jockey pump head	N/A	N/A	N/A			
	Standby pump out put	N/A	N/A	N/A			
	 Standby pump Head Auto Starting /Manual 	N/A	N/A	N/A			
	stopping	N/A	N/A	N/A			
	> Pump House Access	IV/A	IVA	1771			
	Terrace Level	450LPM	Provided	MR			
	> Discharge of pump	40M	Provided	MR			
	> Head of the Pump	Required	Provided	MR			
	Power supplyAuto Starting of pump	Required	Provided	MR			
14	Captive Water Storage for Fire Fighting.						
	Underground tank capacity	N/A	N/A	N/A			
	 Draw-off connection Fire service inlet 	N/A N/A	N/A	N/A			
	> Access to tank	N/A N/A	N/A	N/A			
	Overhead Tank capacity	•10,000 ltrs	N/A Provided	N/A			
15	Exit Signage.	Required		MR			
16		- toquileu	Provided	MR			
LU	Provision of Lifts. Pressurization of Lift Shaft						
	Pressurization of Lift lobby	N/A	N/A				
	Communication in lift car	N/A	N/A	N/A			
	Firemen's grounding switch	N/A	N/A	N/A			
	Lift Signage	N/A					
Da		N/A	N/A	N/A			
17			N/A	N/A			

17	Standby power supply	N/A	N/A	N/A		
18	Refuge Area.					
	Total area	N/A	N/A	N/A		
	Location	N/A	N/A	N/A N/A		
19	Fire Control Room					
	Detector system panel	N/A	N/A	N/A		
	 Flow switch panel 	N/A	N/A	N/A		
	PA system panel	N/A	N/A	N/A		
	Battery backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
20	Special Fire Protection systems for protection of special Risks, if any:	. N/A	N/A	N/A		

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The shortcomings was issued by this department vide letter No. F.6/DFS/MS/School/2024/SZ/822 dated 11.12.2024 have been rectified.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F.6/DFS/MS/School/2021/SZ/953 dated 24.11.2021, renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Signature of Inspecting Offic

Name: - R.K. Yadav Designation: - ADO (JKP)

DO (South West)

13/2/22

145

Miretar

-T Letter 4

but up to

Bogn

Mo N

DIRECTOR MYSM

(5)

 \setminus