

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001



No. F6/DFS/MS/Hospital/SZ/2025/21 0

Dated: 28 64 2025

FIRE SAFETY CERTIFICATE

Certified that the M/s Elantis Healthcare (A Unit of Delhi IVF and Fertility Clinic) Nursing Home located at 29, Ring Road, Lajpat Nagar-4, New Delhi-24, running at 1st & 2nd floor of the building which is comprised of Basement + Stilt + Upper Ground + 03 upper floors, owned & occupied by Elantis Healthcare (A Unit of Delhi IVF and Fertility Clinic), has complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by officer concerned of Delhi Fire Service on 23.04.2025 in the presence of Dr. Mannan Gupta (Chairman) and found that the Nursing Home is fit for occupancy of Group 'C' (Institutional Building) with effect from .2.8. 59. 2021 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire Service Rules, 2010 printed below.

Issued on 28 04 2025 at New Delhi by

(Arul Garg) Director

Defhi Fire Service

Copy to:-

 The Medical Superintendent Nursing Homes, Directorate General of Health Services, 3rd floor, DGD Building, S-1, School Block, Shakarpur, New Delhi-92.

The Executive Engineer (Bldg.) HQ: South Delhi Municipal Corporation, 9th floor, Civic Centre, Minto Road, New Delhi-110002.: To ensure the occupancy of the building as per this FSC

Conditions for the validity of Fire Safety Certificate

- The Temporary construction at 3rd floor shall not be used for any purpose whatsoever. In case
 the 3rd floor is regularized by the local building sanctioning authority, the same shall be
 intimated to this department alongwith with occupancy details and approved/regularized plans
 for further consideration from fire safety point of view.
- All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule
 of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- The means of escape shall be kept unobstructed/unlocked for unhindered evacuation in case of an emergency.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.

6-35

				<u>r</u>				
Г				INSPECTION REPO				
	Name	& ad	dress of the building	M/s Elantis Healthcare (A Unit of Delhi IVF and Fertility Clinic located at 29, Ring Road, Lajpat Nagar-4, New Delhi-24.				
	Buildi	ng is	comprised of	Basement + Stilt + Upper Ground + 03 upper floors Basement - Dermatology Clinic Stilt - Parking Upper Ground floor - Pastry shop & vacant space (office space) 1 st & 2 nd floor - Nursing Home 3 rd floor - Temporary construction (sealed)- As per affidavit da 23.05.2025 not to use above 2 nd floor for any purpose submitted				
+	-			the Owner.	Crown IC! Hospital			
3			cupancy	Institutional Building (New Case	Group C Hospital			
4	Туре			ANNUA SAMAS				
5 6			previous FSC direction letter no.	Nil F6/DFS/MS/BP/2023/253 dated 17.07.2023 for Basement + stilt upper ground + 02 upper floors				
7	Date	of in	enection	23.04.2025	W. 11007			
8	Date of inspection Name of the inspecting officers			Rajesh Kumar Shukla, ADO (M. Road)				
9	Name	e of	the designation of officer ouilding side	Dr. Mannan Gupta (
10			onstruction	2021				
11	Appl	icant	's letter no	Outdoor diary no. 557	dated 15.04.2025			
S. No	Minimum Standards on fire Prevention and fire safety requirements U/R 33			Requirement as per NBC/UBBL-2016	Provided at Site	Remarks MR/NMF		
1	Acce	ess to	building					
	a	Ro	ad width	12.0 mtrs.	60.0 mtrs.	MR		
	b		te width	5 meters	Directly accessible	MR NA		
4	c	W	idth of internal road	NA SErits	NA	INA		
2	Number, Width, Type and Arrange A Number of staircases:			ement of Exits				
	A	a	Upper floor	02 nos.	Stilt to terrace – 2 nos. Stilt to upper ground – 1 no. (Pastry shop)	MR		
		b	Basement	02 nos.	02 nos.	MR		
	В	W	idth of staircases					
		a	Upper floor	2.0 m & 1.50 m	Stilt to terrace- 2.0 m & 1.5 m Stilt to upper ground – 1.3 m (Pastry shop) separate entry/exit of pastry shop	MR		
П		b	Basement	2.0 m & 1.50 m	2.0 m & 1.50 m	MR		
	C		otection of exits	Dogwined	Provided	MR		
П		a b	Fire check door Pressurization	Required NA	NA	NA NA		
	D	No	o, of continuous staircases	02 nos.	02 nos.	MR		
Н	E	Wi	dth of corridor	2.4 mtrs	Provided	MR		
	F		or size	-2.0 m (for more than 5 beds) -1.5 m (for less than equal to 5 beds) -1.25 m (for less than equal to 2 beds)	Provided	MR		
3			tmentation	In	D 21-J	MD		
	A B		check door ling of electrical shafts	Required Required	Provided Provided	MR MR		
			e rating of shaft door	2 hr fire resistance	Provided	MR		
	C	Que l'es	ter curtain	NA NA	NA Provided	NA NA		
	E		dampers	NA NA	NA NA	NA NA		
4	1000000		Management System.	1.274.5	1 * 16.5	1 444		
H	A		ement	Required	Provided	MR		
	В		per floor	Required	Provided	MR		

11/19

+	-			uisher				
	A	3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3			15 nos.	15 nos.	MR	
	В	Ту	pes	Little Control of the	CO ₂ & ABC &WCO ₂	CO ₂ & ABC &WCO ₂	MR	
	C	IS	mark	ting	ISI marked	ISI marked	MR	
	Fir	rst-	aid-H	ose Reels.				
	A Total numbers of each floor			imbers of each floor	01 no.	01 no.	MR	
	В	Le	ngth		30 mtr.	30 mtr.	MR	
Ì	C Nozzle diameter		5 mm	5 mm	MR			
	Aı	itor	natic	fire detection and alarming				
	A Type of detectors				Smoke/Heat	provided	MR	
	В	_		on of main panel	Stilt	Provided	MR	
	C		Location of repeater panel Alternate source of power		NA NA	NA NA	NA NA	
	D							
	E]	Hoote	rs	Audible in entire building	Provided	MR	
8	M	OF	FA		Required	Provided	MR	
9	Public Address System.			dress System.	NA	NA	NA	
10	Automatic Sprinkler System.							
	A	-	Basem	Section 1 and the control of the section of the sec	Required	Provided	MR	
	В	Į	Jpper	floors	Required	Provided	MR	
	C	-	prink	ler above false ceiling	NA	NA	NA	
11			•	lydrants		1		
**	A			f riser/down comer	100 mm	Provided	MR	
	E			er of hydrants per floor	01 nos.	Provided	MR	
		C Hose Box			01 nos.	Provided	MR	
12	C Hose Box							
14	A Total number of hydrants			NA	NA	NA		
			Hose 1		NA	NA	NA	
12		San Control of the Co						
13	13 Pumping Arrangements. A Ground Level							
	-	1		Discharge of main Pump	1620 LPM	1620 LPM	MR	
		+		Head of Main Pump	50 m	50 m	MR	
				Number of main pumps	01 no.	01 no.	MR	
				Jockey pump out put	180 LPM	180 LPM	MR	
		}		Jockey pump head	50 m	50 m	MR	
		-		Standby pump out put	1620 LPM	1620 LPM	MR	
			g	Standby pump head	50 m	50 m Provided	MR MR	
			h	Auto starting /manual stopping	Required	Provided	MR	
		_		Pump House Access	Required	Tiovided		
	-	В		race Level	NA	900 LPM	NA	
			5775	Discharge of pump	NA NA	40 m	NA	
				Head of the Pump	NA NA	Provided	NA	
			1000	Power supply Auto Starting of pump	NA NA	Provided	NA	
		-	1000	144750 0000 0000 0000 0000 0000 0000 0000	1 - 0.00			
14			75,000 ltrs	Provided	MR			
		A		erground tank capacity	Required	Provided	MR	
	-	B		v-off connection service inlet	Required	Provided	MR	
	+	D		ess to tank	Required	Provided	MR	
	E Overhead Tank capacity			10,000 ltrs	10,000 ltrs	MR MR		
15	5	Exit Signage.			Required	Provided	IVIK	
	6			n of Lifts.		I pundad	MR	
		A	Press	surization of Lift Shaft	Required	Provided Provided	MR	
		B	Press	surization of Lift lobby	Required	Provided	MR	
				munication in lift car	Required Required	Provided	MR	
1				nen's grounding switch Signage	Required	Provided	MR	

17	Standby power supply	Required	DG Set	MR					
18	Refuge Area.								
	A Total area	NA	NA	NA					
	B Location	NA	NA	NA					
19	Fire Control Room								
	A Detector system panel	NA	NA	NA					
	B Flow switch panel	NA	NA	NA					
	C PA system panel	NA	NA	NA					
	D Battery backup	NA	NA	NA					
	E Building Floor Plans	NA	NA	NA					
20	Special Fire Protection systems for protection of special Risks, if any:	NA	NA	NA					

LEGENDS - Meeting requirement (MR), Not meeting requirement (NMR), Not applicable (NA), Provided but not functional (PNF).

Note:- The Hospital Management/Owner has submitted an affidavit that he has sealed the temporary construction on 3rd floor and shall not use it for any purpose whatsoever. Photo of the sealed 3rd floor is placed on file at C/32 & C/33.

The fire protection system was randomly checked and tested and was found functional at the

time of inspection. The shortcomings issued to the Hospital by this department vide letter F6/DFS/MS/Hospital/SZ/2024/365 dated 27.06.2024 has been compiled by the management.

If approved to the note above & in view of the substantial compliance of the minimum standards on fire prevention and fire safety measures as required under the Rules, it is recommended to grant Fire Safety Certificate under Rules 35 of Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer Name: Rajesh Kumar Shukla

ADO (M. Road) Designation

Director (D)