

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001



No.F6/DFS/MS/NDZ/EH/2025/ 306

Dated: 21/08 /2025

## **FIRE SAFETY CERTIFICATE**

Certified that the Eleven to Eleven Restaurant (A Unit of Gauri Food And Beverages) located at Shop No. 9B & 9C, 3rd floor, Cross River Mall, CBD Ground, Shahdara, Delhi -110092, building comprised of Two Basement + Ground + 03 upper floors only. (Restaurant running on third floor only) owned / occupied by Eleven to Eleven Restaurant was granted FSC by this department vide letter No. F6/DFS/MS/EH/2022/ NDZ/50 dated 25/02/2022. The premises was re-inspected by the officer concerned of this department on 13/08/2025 in the presence of Mr. Ramesh Singh and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Assembly Building" (Group -D) Restaurant running on third floor only, with effect from 21 /08/2025 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010. Subject to conditions printed below.

Issued 2108 2025 at New Delhi by.

CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to:-

1. The Commission, MCD Civic Center, New Delhi, w.r.t.- MCD portal ID - 2025072811956 dated 01/08/2025, with a request to ensure the occupancy as detailed above.

2. The Owner, Eleven to Eleven Restaurant (A Unit of Gauri Food And Beverages), Shop No. 9B & 9C, 3rd floor, Cross River Mall, CBD Ground, Shahdara, Delhi -110092.

## Conditions for the validity of Fire Safety Certificate:

- 1. This FSC is valid for Restaurant running on third floor only.
- 2. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 3. All the means of escape shall be kept free of all the type of obstruction all the time.
- 4. All the employees shall be acquainted with the use and maintenance of all fire equipment's and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 5. All the fire fighting equipment's shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 6. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 8. Basement shall be used strictly as per UBBL.
- 9. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

N-12

	Name	& 20		SPECTION REPO		V. Company		
١ ١	Name & address of the building			Eleven to Eleven	Restaurant (A Unit of Ga	uri Food And		
				Beverages) located at Shop No. 9B & 9C, 3rd floor				
				Cross River Ma	ll, CBD Ground, Shah	dara, Delhi		
				110092.				
2	Build	ing i	s comprised of	Two Basement + Ground + 03 upper floors only				
				(Restaurant running on third floor only)				
3	Type of occupancy			Assembly (Restaurnat)				
4	Type of case		ise	Renewal				
5	Details of previous FSC			F6/DFS/MS/EH/2022/NDZ/50 dated 25/02/2022.				
6	Fire safety direction letter no.			NBC Part-IV				
7	Date of inspection			13.08.2025				
8	Name of the inspecting officers			Sh. Suman Kumar (ADO)				
9	Name	of	the designation of	Mr. Ramesh Sing	h			
	officer From the building side		om the building side					
10	Year of construction 2015							
11	Appli	cant	's letter no	MCD I.D- 2025072811956 dated 01/08/2025				
S.N	Mi	nimı	ım Standards on fire	NBC Part-IV	Provided at Site	Remarks		
0	Prevention and fire safety		tion and fire safety	Requirement		MR/NM		
		requirements U/R 33				R		
1	Access to building							
	a	_	oad width	06 mtrs.	24 mtrs	MR		
	b		ate width	4.5 mtrs.	7.0 mtrs	MR		
	C	W	idth of internal road	6.0 mtrs.	6.0 mtrs	MR		
2	Nu	mbe	r, Width, Type and A	rrangement of Ex	its			
Т	A	N	Number of staircases		THE REPORT OF	1 1 2 1		
	5 15	a	Upper floor	02 nos.	02 nos.	MR		
		b	Basement	NA	NA	NA		
	В	1	Width of staircases					
		a	Upper floor	1.5 mtrs	1.50mtrs & 02mtrs	MR		
		b	Basement	NA	NA	NA		
	C	Pr	otection of exits	1 A 1 A 1	a brown that	and the second		
	33,147	a	Fire check door	NA	NA	NA		
	-	b	Pressurization	NA	NA	NA		
	D	No	o. of continuous ircases to terrace	01 no.	06 nos.	N/A		
	E		idth of corridor	1.5 mtrs.	1.5 mtrs. & 1.54 mtr	s. MR		
14	F	Do	or size	2.0 mtrs.	2.0 mtrs.	MR		
3	Co	mpa	rtmentation		The year of the			
	a	a Fire check door		N/A	N/A	N/A		
	ь	Sea sha	ling of electrical fts	N/A	N/A	N/A		
	С		rating of shaft door	N/A	N/A	N/A		
	d			N/A	N/A	N/A		
	e			N/A	N/A	N/A		
4	Sm		Management System.		l'	. 35.		
	a	Bas	sement	NA	NA	NA		
	b Upper floor							



. [	Fir	e Ex	tinguisher			T	
	a	-	l numbers	02 nos.	04 nos.	MR	
1	b	Тур		CO <sub>2</sub> & ABC	CO <sub>2</sub> & ABC	MR	
Į,	c			ISI marked	ISI marked	MR	
	c ISI marking ISI marked ISI marked First-aid-Hose Reels.						
5	1 m 1 1 c 1 d			01 nos.	Provided	MR	
4	a b	200000	gth of hose reel hose	30 mtrs.	Provided	MR	
A.	-	-		05 mm	Provided	MR	
1	c Nozzle diameter  Automatic fire detection and alarming s			1.000	3) 1-11		
'	-	_		Heat & Smoke	Provided	MR	
	a Type of detectors b Location of main panel			Control Room	Provided	MR	
	b	110	Section 1997 Company of the California Property of the California	Security Room	Provided	MR	
	d		lternate source of power	Battery & D.G Set	Provided	MR	
	e	Н	ooter	Stair Case	Provided	MR	
8	_	10EF		Required	Provided	MR	
9			address System.	Required	Provided	MR	
10	_		natic Sprinkler System.	Common with Mall			
	a		sement	N/A	Provided	N/A	
-	b	Up	per floors	N/A	Provided	N/A	
d	c	Sp	rinkler above false ceiling	N/A	Provided	N/A	
11	Internal Hydrants						
		a Size of riser		100 mm	Provided	MR	
	b	Nu	mber of hydrants per floor	01 no.	Provided	MR	
	C	_	se Box	01 no.	Provided	MR	
12	Yard Hydrants.						
	a	a Total number of hydrants		NA	NA	NA	
	b	Hose Box		NA	NA	NA	
13	Pumping Arrangements.			Common w	ith Mall	617 III	
	Α		Ground Level		74 41,742	J. A. T	
	1	a	Discharge of main Pump	2850 LPM	2850 LPM	MR	
1		b	Head of Main Pump	60 mtrs.	60 mtrs.	MR	
		С	Number of main pumps	02 nos.	02 nos.	MR	
		d	Jockey pump out put	180 LPM x 02	180 LPM x 02	MR	
9		е	Jockey pump head	60 mtrs.	60 mtrs.	MR	
4.1		f	Standby pump out put	2850 LPM	2850 LPM	MR	
	1	g	Standby pump head	60 mtrs.	60 mtrs.	MR	
		h	Auto starting /manual stopping	Required	Auto	MR	
-2		i	Pump House Access	Required	Provided	MR	
to the							
		a	Discharge of pump	NA	NA	NA	
1		b	Head of the Pump	NA	NA	NA	
Paris and	1	C	Power supply	NA NA	NA NA	NA NA	
7		d	Auto Starting of pump	NA	NA	NA	

14	C	aptive Water Storage for Fire Fightin	Common with Mall				
	a	Underground tank capacity	N/A	2,00,000 Ltrs.			
- 1	b	Draw-off connection	N/A	Provided	MR		
- 1	С	Fire service inlet	N/A	Provided	MR		
- 1	d	Access to tank	N/A	Provided	MR		
	е	Overhead Tank capacity	10,000 ltrs.	50,000 ltrs.	MR		
15	E	kit Signage.	Required	Provided	MR		
16	Pı	ovision of Lifts.	Common with Mall				
	a	Pressurization of Lift Shaft	NA	Provided	MR		
- 1	b	Pressurization of Lift lobby	NA	Provided /	MR		
- 1	C	Communication in lift car	NA	Provided	MR		
	d	Firemen's grounding switch	NA	Provided	MR		
	е	Lift Signage	NA	Provided	MR		
17	Standby power supply		Provided for Main Building				
18	Refuge Area.						
	a	Total area	NA	NA	NA		
	b	Location Con Con 1	NA	NA	NA		
19	Fire Control Room Common with Mall						
	a	Detector system panel	NA	Provided	MR		
	b	Flow switch panel	NA	Provided	MR		
	c	PA system panel	NA	Provided	MR		
	d	Battery backup	NA	Provided	MR		
	e	Building Floor Plans	NA	Provided	MR		
20		ecial Fire Protection systems for otection of special Risks, if any:	NA	Provided in all LT & HT Panels	NA ii		

Note:- Fire Safety Certificate to the mall has been issued by this department vide letter no.F6/DFS/MS/2023/NDZ/75 dated 13/02/2023.

The fire protection system was randomly checked and tested and was found functional at the time of inspection.

Keeping in view the compliance of the minimum standards of fire prevention and fire safety measures as required under the rules. The FSC issued vide letter no. F6/DFS/MS/EH/2022/NDZ/50 dated 25/02/2022 renewal under rule 35 (6) of the Delhi Fire Service rules 2010 is recommended.

المحتري

Signature of the Inspecting Officer

Name: Suman Kumar Designation: ADO

D.O/Esst (4.8.2)

RIV P Typesps

18/8/ 2025 18/8/ 2025

Principal Director

Ofo to Sem

CF2

201 81 200

ADO (Surpan Kv)