



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No. F.6/DFS/MS/2025/SZ/232

Dated :....12./.6.6./2025

FIRE SAFETY CERTIFICATE

Certified that the M/s Evergreen Sweet House situated at Plot No Y-48, Okhla Industrial Area, Phase-II, New Delhi 110020 comprised of Basement, Stilt + Ground plus Two upper floors owned/occupied by Evergreen Sweet House was issued FSC by this department vide letter no F6/DFS/MS/2022/SZ/79 dated 21/02/2022. The Premise was re- inspected by the officer concerned of this department on 03/06/2025 in the presence of Mr. Devendra Singh and found that the said Industrial building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and found that the said building / premises is fit for occupancy class Group G "Industrial Building" with effect from 12/06. /2025 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 12 ... 6... /2025 at New Delhi by

DELHI FIRE SERVICE

Copy to:

1. Evergreen Sweet House situated at Plot No Y-48, Okhla Industrial Area, Phase-

II, New Delhi 110020.

2. The Executive Engineer (Building), MCD, Central Zone, Jal Vihar, Lajpat Nagar, New Delhi110024.

Conditions for the validity of the safety certificate:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

2. Any deviations w.r.t. construction shall be verified by the concerned building

sanctioning agency.

3. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

4. Basement shall be used strictly as per Building Bye Laws.

5. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

6. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available

on www.dfs.delhigovt.nic.in.

M8

A.		B 1 - 3 W	0/18			
Name	& addr	ess of the building	TION	- L		
		: Evergro	een Sweet House, Plot Nov Delhi-110020 al "Group-G"	Mary Tiller		
. Type o	of Occu	Dancy II, New	v Delhi-110020	No. Y-48, Okhla Indue	trial 4	
. Type (of Case	: Industri	al "Group-G"		ulai Area Phas	
Comp	rised of	: Kenews	al .			
. Detail	s of Pre	vious NOC : Baseme	ent, Stilt, Ground & 2 U ₁ S/MS/2022/SZ/79 dated	100 100,42		
rire 5	atety di	10/DFS	5/MS/2022/SZ/79 dated : 5/MS/BP/2013/104 dated :	Pper Floors		
· Date (or inspec	tion : 03/06/0	5/MS/BP/2013/104 dated 025	103/06/2012		
Name	of Insp	ecting Officer : 03/06/2	025	03/00/2013		
from	the buil	ignation of officer : Sh. Raj	esh Kumar ADO (BCP)			
10.	Vear of	IDO CIDA				
	Year of Construction : Mr. Devendra Singh : 2014					
S. No.	Mini	it s letter No. : outdoor	diary no 1565 dated 13/	The late and a		
	and f	num Standards on fire prevention	BBL/NBC	05/2025	90 0 0	
1.	anu i	re safety U/R 33		Provided at site	Remarks	
4. 6	Acces	s to building	Requirement	La	MR/NMR	
	•	Road width	nadana.	المراجع		
	•	Gate width	12m	Provided	MR	
, dic.	•	Width of internal road	4.5m	Provided	MR	
2.	Num	ber, Width, Type & Arrangement of	-NA-	-NA-	-NA-	
Tu LL	a. Ni	imber of staircases	Exits	Carrier 4	enmost.	
	-	Upper Floors	Last In-	to London Control		
	-	Basements	2 Nos	Provided	MR	
	b w	idth of staircases	2 Nos	Provided	MR	
	J. W	10 10 10 10 10 10 10 10 10 10 10 10 10 1	- x #35.0	permit man M 1 %	1	
		Upper Floor	1.5m	Provided	MR	
		Basements	1.5m	Provided	MR	
	C. Pr	otection of exits	Janes Oralicon.	1 110 Vided	IVIX	
		Fire check door	Required	Provided	MD	
	•	Pressurization	-NA-	-NA-	MR	
	d. N	o. of continuous staircases to terrace	2 Nos	Provided	-NA-	
		idth of Corridor	-NA-	-NA-	MR	
	f. I	oor Size	1m	lm (final exit)	-NA-	
3.	Com	partmentation	Am minu jūro	im (imai exit)	MR	
-	Com		- Injur	53) 71-11 11 11		
		Fire check door	Required	Provided	MR	
	•	Sealing of electrical shafts	Required	Provided	MR	
	1	Fire Rating of shaft door	-NA-	-NA-	-NA-	
	-	Water Curtain	-NA-	-NA-	-NA-	
	•	Fire Dampers	-NA-	-NA-	-NA-	
4.	Smo	ke Management System	Other will	no montrol of		
- 4	•	Basements	30 ACPH	M. V. Provided	MR	
		Upper floors	12 ACPH	Ex. Fan Provided	MR	
5.	Fire	Extinguishers			IVIIC	
		Total numbers	Required	20 Nos	MR	
		Types	ABC/W.CO ₂ /CO ₂	10/10 Nos	MR	
		IS marking	Required	Provided		
6.	Firet	Aid Hose Reels	in the state of t	FIGVIDED	MR	
J.		Total numbers on each floor	01 Nos	Provided	MR	
		Length of hose reel hose	30m	Provided		
		Nozzle diameter	5mm	Provided	MR	
	A4-	matic fire detection and alarming sys		1 lovided	MR	
7.	Auto		Required	Smoke/Heat		
	•	Type of detectors	Required		MR	
	•	Location of Main Panel	-NA-	Ground Floor	MR	
	•	Location of Repeater Panel	Required	-NA-	-NA-	
•	•	Alternate source of power	Required	Provided	MR	
	•	Hooters' Location		All Levels	MR	
		FA	Required	Provided	MR	

m/119

	i i Kratem	Required	Provided	10
0,	Public Address System Automatic Sprinkler System	Required	Provided	MR
10.	Hassment	Required	Provided	MR
	4/4-17-17-17	-NA-	-NA-	MR
	Opper Ploors Sprinkler above fidse ceiling	-1177		-NA
	A seal Hedrauth	1 100mm	Provided	MR
P	A CAMPAGE PARTY OF THE PARTY OF	01 Nos	Provided	MR
	Number of hydrants per floor	01 Non	Provided	MR
	Hose Hos	50.1.15000	1	
	Const Designation	03 Nos	Provided	MR
1	Total number of hydrauts	02 Nos	Provided	MR
	a Hose Hoy			
	Pumping Arrangements			
M.	Chrystal Laves	3280 LPM	Provided	MR
	* (Swhape of main Pump	nom	Provided	MH
	F. Houst of Janua bands	01	Provided	Mil
	y Vennes or main bandas		Provided	MR
	W VANDA SAMINI SAM SAM	180 LPM	Provided	MR
	y years towns years	0001	Provided	MR
	WARE DANKED STANDS OF	2380 I PM	Provided	MR
	TANKI MAMAY MAMAY PANKI	66411	Provided	MR
	A STATE OF THE STA	Required	Provided	MR
	P. SPAN STAND STAND	Required	110	
	Threat head		Provided	MR
	· Maries in the	119199	Provided	MR
	in street or, sign hands	dibn	Provided	MR
	* Minter States	Required	Provided	MR
	* Anto Spacific or James	Required	Livinea	1
	Cabusa grant parada un usa ukuma			MR
14	Chust usus (mare)	1.00.000 Los	Provided	The second second
	Syrappin Anna Sameragehal) •	Required	Provided	MR
	P Spain-cos, spains	Required	Provided	MR
	head of morests.	Required	Provided	MR
	(Numbered Flank copensity)	MAN LIS	Provided	MR
2		Required	Provided	MR
18	Erit Ofmager			
16.	Provision of Life.	-1/4-	-NA-	-NA-
	Pressurgative of Lift Shall	-524-	-NA-	-NA-
	Presumation of Lift Arthr	-14-	-NA-	-NA-
	Communication In hill Car Pireman's Grounding Switch	25.55		MR
	1 ill Signage	Required	Provided	
		Required	Provided	MR
13.	Standby power supply	Required	Provided	MR
18.	Refuge Area.			
	> Total Area	-NA-	-NA-	-NA-
	> Liverion	-NA-	-NA-	-NA-
19,	Fire Control Room			
	Detector System Panel	-14-	-NA-	-NA-
	Phys Switch Panel	-14-	-NA-	-NA-
	PA System Panel	-14-	-V4-	
	Barrer Nackup	-14-		-NA-
	Building Pless Plans	-14-	-NA-	-NA-
20.	Special Fire Protection System for	164	-14-	-NA-
40.00	Protection of special Risks, if any:		Extinguisher	



The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/2022/SZ/79 dated 21/02/2022, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Designation: ADO (BCP)

DO (SD)

ADOCAETS
As appointed, F.F. Letter in pritrip for your
Synatrice 81.