



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F.6/DFS/MS/School/2025/SZ/ 787

Dated: 13 / 06 /2025

FIRE SAFETY CERTIFICATE

Certified that the building of Govt. Girls Senior Secondary School (New Block) located at Bijwasan Bharthal Road, New Delhi-110077 (School ID: 1821035) comprised of two blocks Ground + 03 upper floors, owned/occupied by Directorate of Education, Govt. of NCT of Delhi, was issued FSC by this department vide letter No. F6/DFS/MS/2022/WSZ/School/646 dated 14/06/2022. The premise was re-inspected by the officer concerned of this department on 05/06/2025 in the presence of Dr. Meena Rani Kashyap (Principal) and found that said building/premise is fit for occupancy class "Educational Group B" (School) with effect from 13/06/2025 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ___13 / o 6 /2025 at New Delhi by

Copy to: -

- The Principal, Govt. Girls Senior Secondary School located at Bijwasan Bharthal Road, New Delhi-110077 (School ID: 1821035)
- The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided there in shall be maintained in good working conditions at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 5. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, prior to its expiry.
- 6. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

N-26

1	INSPECT	TION REPO)DT		ri 	
1.	the building	Govt. Girls Senior Secondary School located at Bijwasan Phoeth J.D.				
2.	Type of Occupancy					
3.	Building Comprised of	Daucati	Educational (Group B)			
4.	Type of Case	Ground	plus t	three upper floo	rs.	
5.	Details of previous NOC No.	Kenewa			Pro Constitution of the Co	
6.	Fire Safety dimensional NOC No.	F6/DFS/MS/2022/SWZ/School/646 Dt. 14/06/202				
7.	Fire Safety directives Letter No. Date of inspection	NBC	NBC NBC			
8.	Name of the L	05/06/2025				
9.	Name of the Inspecting Officer	ADO (DWK)				
	Name and designation of Officer from the building side	Dr. Meen	Dr. Meena Rani Kashyap (Principal)			
10. 11.	Year of Construction	2021-22	A.			
	Applicant's letter No.	GGSSS/BIJ/2025-26/III Dt. 03/05/2025 Outdoor diary No. 1363 dated 06/05/2025				
S. No.	Minimum standards on fire	Old NO	Old NOC		Remark	
1.	prevention and fire safety U/R 33	Requirements		site	MR/NM	
1.	Access of building					
	Road width	06 mtr		06 mtr	MR	
	Gate width	Accessible		Provided	MR	
	Width of internal road	N/A		N/A	N/A	
2.	Number, width, Type & Arrangement	nts of exits		*14		
	a. Number of staircases	100000000000000000000000000000000000000			1	
	Upper floors	02 (Each B	lk)	Provided	MR	
	Basements	N/A		N/A	N/A	
	b. Width of staircases	1.7		D 11.1	100	
	Upper floors	1.5 mtr		Provided	MR N/A	
	Basements	N/A		N/A	IVA	
	c. Protection of exits	N/A	-	N/A	N/A	
	Fire check door	N/A N/A	- 10	N/A N/A	N/A	
	Pressurization			Provided	MR	
	d. No of continuous staircase to terracee. Width of Corridor	Required 1.50 mtr		Provided	MR	
	f. Door Size	1.20 mtr		Provided	MR	
3.	Compartmentation	1.20 ma	H	11011404		
3.	Fire check door	N/A	1	N/A	N/A	
	Sealing of electrical shafts	N/A		N/A	N/A	
	Fire Rating of shaft door	N/A		N/A	N/A	
	Water Curtain	N/A N/A	+	N/A N/A	N/A N/A	
	• Fire Dampers	IVA		14/14		
4.	Smoke Managements System Basements	N/A		N/A	N/A	
	Basements Upper floors	Required	Natu	ral ventilation	MR	
5.	Fire Extinguishers	<u>Virginia •</u>				
3.	Total numbers	26 Nos		Provided	MR	
	• Types	ABC & CO2		Provided	MR	
	ISI marking	ISI Marked		Provided	MR	
6.	First-Aid Hose Reels) (T)	
U.	Total numbers on each floor	02 Nos		Provided	MR	
	Length of hose reel hose	30m		Provided	MR MR	
	Nozzle diameter	5mm	14	Provided	IVIIC	



	Automatic fire detection and alarming	system	N/A	N/A
7.	Automatic fire detection and and		N/A	N/A
	Type of detector Type of detector Type of detector	N/A		N/A
	Location of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	E//25
	Hooters' Location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	1072		
10.	Automatic Sprinkler System	N/A	N/A	N/A
10.	Basements	N/A	N/A	N/A
	- Upper Floor	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A		
	Internal Hydrants		21/4	N/A
11.	Size of riser/down- comer	N/A	N/A	N/A
	Number of hydrants per floor	N/A	N/A	SW 8
		N/A	N/A	N/A
JI.	Hose Box Varid Hydrants	In A second		NT/A
12.	Yard Hydrants Total number of hydrants	N/A	N/A	N/A
		N/A	N/A	N/A
	Hose Box		4	
13.	Pumping Arrangements			
	Ground Level	N/A	N/A	N/A
	 Discharge of main pump 	N/A	N/A	N/A
	> Head of main pump	N/A	N/A	N/A
	> Number of main pumps	N/A	N/A	N/A
	Jockey pump out putJockey pump head	N/A	N/A	N/A
	Jockey pump headStandby Pump out put	N/A	N/A	N/A
	> Standby Pump Head	N/A	N/A	N/A
	> Auto Staring/Manual stopping	N/A	N/A	N/A
	Pump House Access	N/A	N/A	N/A
	Terrace level			
	> Discharge of pump	450 LPM (Each Block)	Provided	MR
	➤ Head of the pump	40 mtr	Provided	MR
	> Power supply	Required	Provided	MR
	> Auto starting of pump	Required	Provided	MR
14.	Captive water storage for firefighting	1		
arrest Marine	Underground tank capacity	N/A	N/A	N/A
	> Draw of connection	N/A	N/A	N/A
0	Fire service inlet	N/A	N/A	N/A
	> Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	10,000 ltr	Provided	MR
15.	Exit Signage	Required	Provided	MR
	Provision of Lifts	2 al	STATE OF THE STATE	
16.	> Pressurization of Lift Shaft	N/A	N/A	N/A
16.	1 1000ullZullUll Ull III Allan	14/74	N/A	11-447
16.		NT/A	INI / A	N/A
16.	Pressurization of lift lobby	N/A		
16.	Pressurization of lift lobbyCommunication in lift Car	N/A	N/A	N/A
16.	 Pressurization of lift lobby Communication in lift Car Fireman's Grounding Switch 			
	 Pressurization of lift lobby Communication in lift Car Fireman's Grounding Switch Lift Signage 	N/A	N/A	N/A
17.	 Pressurization of lift lobby Communication in lift Car Fireman's Grounding Switch Lift Signage Standby Power Supply 	N/A N/A N/A	N/A N/A N/A	N/A N/A
	 Pressurization of lift lobby Communication in lift Car Fireman's Grounding Switch Lift Signage Standby Power Supply Refuge Area 	N/A N/A	N/A N/A	N/A N/A
17.	 Pressurization of lift lobby Communication in lift Car Fireman's Grounding Switch Lift Signage Standby Power Supply 	N/A N/A N/A	N/A N/A N/A	N/A N/A N/A N/A

M)

19.	Fire Control Room			
	 Detector system panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
20.		N/A	N/A	N/A
	Special Fire Protection Systems for Protection of Special Risks, if any;	N/A	N/A	N/A

The fire protection systems provided in the building were checked, tested at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety required under the rules, the fire safety certificate issued vide letter No. F6/DFS/MS/2022/SWZ/School/646 dated 14/06/2022, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for perusal/approval & signature please.

Signature of the Inspecting Officer
Name: Santosh Kumar

Name: Santosh Kumar Designation: ADO (DWK)

DO (SW)

Red) 9/6/25

CFO Mug

Director

N Dollm

Siriki I mand for your

12/06/2