



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/2025/School/ 450

Dated: 07 /04 /2025

FIRE SAFETY CERTIFICATE

Certified that the Govt. Girls/Boys Sr. Sec. School (I.D No. 1309129-30) located at Azadpur Village, Delhi-110033 comprised of 04 Blocks Interconnected, Ground & 03 upper floors each owned/ occupied by Sarvodaya Kanya Vidyalaya was issued Fire Safety Certificated vide this office letter no. F6/DFS/MS/2022/School/WZ/258 dated 11.03.2022. The premise was re-inspected by the officer concerned of this department on 28.03.2025 in the presence of Sh. Yogesh Aggarwal (Principal) and observed that all the fire prevention and fire safety arrangements as provided in the premise found in good working condition. The premise have therefore deemed complied with the requirements under rule 33 of the Delhi Fire Service Rules, 2010 and the building premise is fit for occupancy under "Group-B Educational (School)" with effect from ... of 104.2025... for a period of three years, in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40, subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010,

Issued on . 07 04 2025 at New Delhi

(Atul Garg) Director Ph:-011-23414000

Copy to: -

- 1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi 110054.
- The Principal, Govt. Girls/Boys Sr. Sec. School (I.D No. 1309129-30) located at Azadpur Village, Delhi-110033

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape shall be kept free from any type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipment and method of smooth and speedy safe evacuation of occupants in case of emergency
- 3. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seem during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities. This Fire Safety Certificate is valid only for permanent building structure as per plan.
- 5. This fire safety certificate may not be treated in any case of regularizations of unauthorized construction/unauthorized use of land or activities, if any.
- The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on the official website of Delhi Fire Service i.e. www.dfs.delhigovt.nic.in.
- 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

119

INSPECTION REPORT

Name & address of the building

Composition of building

: Govt. Girls Sr. Sec. School located at Azadpur Village, Delhi-110033. 04 New Block Interconnected Ground + 03 upper Floors, (School ID. No-1309129-30)

Type of Occupancy

: Educational

Type of Case

5. Details of previous NOC

: Renewal

: F6/DFS/MS/2022/School/WZ/258 dated 11.03.2022

6. Fire Safety directives letter No

: Nil

Date of inspection

: 28.03.2025

Name of the Inspecting Officers

: ADO (RN)

Name and designation of officers

from the building side

: Sh. Yogesh Aggarwal (Principal)

10. Year of Construction

: 2019-20

		num Standards on fire prevention and fire safety U/R 33	NBC Part-4 /UBBL Requirement	Provided at site	Remarks MR/NMR		
1	Access	o building		1	MINIMIK		
	•	Road width	06m	0/			
	•	Gate width		06m	MR		
		Width of internal road	06m	06m	MR		
	Numbe		NA	NA	NA		
	Number, Width, Type & Arrangement of Exits a. Number of staircases						
1	a. Num	- E - S COMMON COMM					
	•	Upper Floors	04	04	MR		
	•	Basements	NA	NA	NA		
	i. m.						
r		h of staircases	1.50m	1.70m each	MR		
	•	Upper Floors	NA	NA NA			
	•	Basements		4.113	NA		
	c. Prote	ection of exits					
	•	Fire check door	NA	NA	NA		
	•	Pressurization	NA	NA	NA		
		of continuous staircases to terrace	04	04	MR		
	e. Widt	h of Corridor	1.50m	1.50m			
	f. Door	Size	1.20m	100	MR		
	Compa	rtmentation.	1.2011	. 1.20m	MR		
-							
	•	Fire check door	NA	NA	NA		
		Sealing of electrical shafts	NA	NA	NA		
	•	Fire Rating of shaft door	NA	NA	NA		
	•	Water Curtain	NA	NA			
	•	Fire Dampers		8VCV-8	NA		
1	Smoke Management System. NA NA NA						
	•	Basements	NA	NA			
	•	Upper floors			NA		
			Required	Natural Ventilation	MR		
5	Fire Extinguishers						
	•	Total numbers	24nos	42nos	MR		
	•	Types	ABC/Co2	ABC-30/ Co2-12	MR		
	•	ISI marking	ISI Marked				
6	First-	Aid Hose Reels	131 Warkeu	Provided	MR		



		MIO					
	Total numbers on each floor	04 each floor	Provided				
	Length of hose reel hose	30m	30m	N. S. S.			
	Nozzle diameter						
		5mm	5mm	MR			
į.	Automatic fire detection and alarming system.	NA	NA	NA			
	Type of detectors	NA	NA	NA			
	Location of Main Panel	NA	NA	NA			
	Location of Repeater Panel		NA	NA			
	Alternate source of power	NA		INA			
	Hooters' Location	NA	NA	NA			
	MOEFA	NA	NA	NA			
3	Public Address System.						
)							
10	Automatic Sprinkler System.	NA	NA	NA			
	Basement	NA	NA	NA			
	Upper Floor	NA	NA	NA			
	Sprinkler above false ceiling						
11	Internal Hydrants		NA	T NA			
	Size of riser/down-comer	NA	NA NA	NA NA			
	Number of hydrants per floor Hose Box	NA		NA NA			
		NA	NA	NA			
12	Yard Hydrants.						
	Total number of hydrants	NA	NA	NA			
	Hose Box	NA	NA	NA			
13	Pumping Arrangements						
	Ground Level						
	> Discharge of main Pump	N/A	N/A	N/A			
	➤ Head of Main pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	 Jockey Pump out put Jockey pump head 	NA	N/A	NA			
	Standby Pump out put	NA	N/A	NA ,			
	> Standby Pump Head	N/A	N/A	N/A			
	➤ Auto Starting/ Manual stopping						
	➤ Pump House Access	N/A	N/A	N/A			
	Pump House Access	N/A	N/A	N/A			
	Terrace level						
	> Discharge of pump	450 LPM	450 LPM	100			
	➤ Head of the pump	40m	430 LPM	MR			
	> Power Supply	Required		MR			
	Auto Starting of pump		Provided	MR			
14	Captive Water Storage for fire fighting	Required	Provided	MR			
	Underground tank capacity						
	Draw-off connection	NA	N/A	NA			
	> Fire service inlet	NA	NA	NA			
	> Access to tank	NA	NA	NA			
	Overhead Tank capacity	NA	NA	NA.			
	,,,,,	10,000 LTR	Provided	MR			

12	Exit Sig	nage.	Required	Provided	MR			
16	Provision of Lifts.							
	•	Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage	N/A	N/A	N/A			
	•		N/A	N/A	N/A			
			N/A	N/A	N/A			
			N/A	N/A	N/A			
			N/A	N/A	N/A			
17	Standby	power supply	N/A	N/A	N/A			
18	Refuge	Refuge Area.						
	A	Total Area	N/A	N/A	N/A			
	>	Location	N/A	N/A	N/A			
19	Fire Control Room							
	•	Detector System Panel	N/A	N/A	N/A			
	Flow Switch Panel	N/A	N/A	N/A				
	•	Batter backup	N/A	N/A	N/A			
			N/A	N/A	N/A			
		Duniding Floor Flans	N/A	N/A	N/A			
20	Special Protection	Fire Protection Systems for on of special Risks, if any:	N/A	N/A	N/A			

The fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection. The management has complied all the shortcomings issued and communicated by this department vide letter of even no. F6/DFS/MS/2024/School/153 dated 13.03.2025.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in NBC Part 4, the FSC issued vide letter of even no. F6/DFS/MS/2022/School/WZ/258 dated 11.03.2022, renewal under rule 37 of the Delhi Fire Service Rules, 2010.

Signature of the Inspecting Officer Name: - C.L. Meena

Designation:- Asst. Div. Officer (RN)

D.B. Mukharjee (DO/W)

0110412025

7/4/22

Jun / 2012

Denetar May

Another

LOW -- P.T.O.