## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2025/ 153

Dated: 24./03/2025

FIRE SAFETY CERTIFICATE

DIRECTOR
Delhi Fire Service

Copy to:-

1. The Commissioner, North MCD, Civic Centre, New Delhi: to ensure the occupancy as detailed above and deviation if any.

 The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. Online id no. 2025022502420 dated 26/02/25.

3. The Manager,

M/s Geetanjali Inn 3997,4000 & 4001, Gali School Wali, Bagichi Ram Chander, Mohalla Kaseruwalan, Pahar Ganj, New Delhi.

## Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. This FSC is valid only for guest house from ground to third floor.
- 2. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. The trained firefighting staff should be available round the clock.

- The compliance with regards to electrical installation, structural stability, set back area, occupancy
  and any deviation in construction etc. shall be verified from authority concerned.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.
- Any flammable material for interior decoration is prohibited.

N/32

INSPE	CTION	REPORT
TITOLE	CITOIN	KLIUKI

1. Name & address of the building M/s Geetanjali Inn at 3997, 4000 & 4001, Gali

School Wali, Bagichi Ram Chander, Mohalla

Kaseruwalan, Pahar Ganj, New Delhi.

2. Type of occupancy:-Residential, Sub Division-A-1

Gr. + 03 Upper floors (total 07 Guest rooms) Ground floor (01 guest rooms), 1<sup>st</sup> floor to 3<sup>rd</sup> floor (02 guest rooms at each floor).

3. Type of case:-Renewal

No. F6/DFS/MS/GH/NDZ/2022/34 dated 4. Details of previous FSC:-

18/01/22.

5. Fire safety directives No .-N/A

6. Date of inspection:-12/03/25.

7. Name of the inspecting officer:-

Sh. Ravinder Singh (ADO/CC)

8. Name & designation of officer From the building side:-

9 Year of construction:-

Mr. Salman

2010

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR
1.	Access to Building			NIA DCC
	1) Road width	N/A	06 mtr.	N/A( PSS)
.02	2) Gate width	N/A	N/A	N/A
	3) Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Arr	angement of Ex	its	
2.	A. Number of staircases			100
-	1. Upper floors	01 No.	01 No.	MR
	2. Basements	N/A	N/A	N/A
	B. Width of staircase	All		MR
	1. Upper floors	0.80 mtr.	1.25 mtr.	N/A
	2. Basements	N/A	N/A	N/A
	C. Protection of exits			NI/A
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous staircase to terrace	01	01	MR
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	01 mtr.	01 mtr.	MR
3.	Compartmentation			
<b>3.</b>	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
<b>1</b> .	Smoke Management System			
P.	1) Basements	N/A	N/A	N/A
}	2) Upper floors	Required	provided	MR
5.	Fire Extinguishers			1
<u>,                                     </u>	1) Total numbers	08 Nos.	8 Nos.	MR
H	2) Types	ABC & CO2	ABC & CO2	MR
	3) ISI marking	Required	Provided	MR
6.	First-Aid Hose Reel			IVII
	THE THU HUSE ICCI		2	

	=			
	floor			
4_	2) Length of hose reel hose	30 mtr.	30 mtr.	MR
	3) Nozzle diameter	05 mm	05 mm	MR
7.	Automatic Fire Detection &	T 1225 CA 1020 CA 1020 CA		IVIK
15-11	1) Type of detectors Co Type		Provided	MR
	2) Location of main panel	Required	Provided	MR
	Location of main panel     Location of repeater panel		N/A	N/A
	4) Alternate source of power		Provided	MR
	5) Hooter's Location	Required	Provided	MR
				MR
8.	MOEFA	Required	Provided	
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			7/4
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	N/A
	ceiling			
11.	Internal Hydrants			
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor			-
	3) Hose box	N/A	- N/A	N/A
12.	Yard Hydrants		-	
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			
	1) Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	N/A	N/A
	pump	F		
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump	N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual	N/A	N/A	N/A
	stopping			
	<ol><li>Terrace level</li></ol>		•	
	a) Discharge of pump	450 LPM	Provided	MR
	<ul><li>b) Head of pump</li></ul>	30 mtr.	30 mtr.	MR
	c) Power supply	Required	Provided	MR
	d) Auto starting of pump	Required	Provided	MR
4.	Captive Water Storage for Fi	re Fighting		
	Under ground tank	N/A	N/A	N/A
	capacity			
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank	2500 ltr.	2500 ltr.	MR
	capacity			- W
5.		Required	Provided	MR
5.	Provision of Lifts.			

			. ,	
	a) Pressurization of lift shaft	N/A	N/A	N/A
an f	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
18	d) Fireman's switch	N/A	N/A	N/A
10	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
× .	a) Detector system	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
		N/A	N/A	N/A .
	c) PA system panel d) Battery backup	N/A	N/A	N/A
		N/A	N/A	N/A
	e) Building floor plan			MR
20.	Special Fire Protection System for Protection of special Risk, if any: One ABC type fire extinguisher found provided.			2722

The fire protection systems provided in the guest house building were randomly tested, checked and found functional at the time of inspection.

n view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as equired under the rules, if agreed, we may renew the FSC issued vide letter No. No. 6/DFS/MS/GH/NDZ/2022/34 dated 18/01/22, renewal under rule 35 of the Delhi Fire Service rules 2010, accordingly, DFA is put up for kind perusal and signature please.

Signature of the Inspecting Officer

Name: - Ravinder Singh Designation: - ADO (CC)

<u>k</u>] 17|3125

KIV 18/03/25

Dineeta

nos/14/