



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/School/2025/SZ/ 470

Dated: 09/04/2025

FIRE SAFETY CERTIFICATE

Certified that the **Govt. Girls/Boys Senior Secondary School** located at Bindapur (Near DDA Flats), New Delhi-110059 (School ID: 1618060), having five blocks each comprised of Ground + One upper floors, owned/occupied by Govt. of NCT of Delhi was issued FSC by this department vide letter No. F6/DFS/MS/SZ/2022/111 dated 03/02/2022. The premise was re-inspected by the officer concerned of this department on dated 27/03/2025 in the presence of Ms. Sarita Dhaka (HOS) and observed that said premises have deemed complied with the fire prevention and fire safety requirements in accordance with DOE Circular No. 3298 – 3398 issued by the Director of Education, Govt. of NCT of Delhi and that the building/premises is fit for occupancy class “**Educational Group B**” (School) with effect from 09/04/2025 for a period of **three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 09/04/2025 at New Delhi by

(ATUL GARG)
DIRECTOR
Ph. 011-23414000

Copy to: -

1. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054
2. Principal, Govt. Girls Senior Secondary School located at Bindapur (Near DDA Flats), New Delhi-110059

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangement provided therein shall be maintained in good working conditions at all time as seen during inspection.
3. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
4. All the staff members must know the correct method of operation of fire-fighting system.
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form ‘J’ [sub rule (1) of rule 37] along with a copy of this Certificate, prior to its expiry.
7. The owner/occupier shall submit a declaration every year in form “K” provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1.	Name & address of the building	Govt. Girls/Boys Senior Secondary School located at Bindapur (Near DDA Flats), New Delhi-110059 (School ID: 1618060)		
2.	Type of Occupancy	Educational (Group B)		
3.	Building Comprised of	05 Blocks of Ground + One upper floor. 03 Blocks interconnected at each floor level		
4.	Type of Case	Renewal		
5.	Details of previous NOC No.	F6/DFS/MS/SZ/2022/111 dated 03/02/2022		
6.	Fire Safety directives Letter No.	DOE Cir. No. 3298-3398 dated 01.03.2011		
7.	Date of inspection	27/03/2025	No. of Students: 2756 No. of Classroom: 40 Plot Area: 10,500 m ² Covered Area: 5414 m ²	
8.	Name of the Inspecting Officer	ADO (DWK)		
9.	Name and designation of Officer from the building side	Ms. Sarita Dhaka (HOS)		
10.	Year of Construction	Old Blk: 1990, New Blk: 2007 & Blk: 3,4 & 5 in 2015-16		
11.	Applicant's letter No.	Email dated 25/02/2025 <1618060bindapur@gmail.com>		
S. No.	Minimum standards on fire prevention and fire safety U/R 33	Requirements As per N/9	Provided at site	Remarks MR/NMR
1.	Access of building			
	<ul style="list-style-type: none">Road width	6m	Provided	MR
	<ul style="list-style-type: none">Gate width	4.5m	Abuts on Road	MR
	<ul style="list-style-type: none">Width of internal road	N/A	N/A	N/A
2.	Number, width, Type & Arrangements of exits			
	a. Number of staircases	OB, NB & Blk 3: 02 each Blk 4 & 5: 01 each	Provided	MR
	<ul style="list-style-type: none">Upper floorsBasements	N/A	N/A	N/A
	b. Width of staircases	1.5m/0.75m	NB: 2 x1.90m, OB & Blk 3: 1.50, 1.45,1.37m, Blk 4&5: 1.50m each	MR (old case)
	<ul style="list-style-type: none">Upper floorsBasements	N/A	N/A	N/A
	c. Protection of exits			
	<ul style="list-style-type: none">Fire check doorPressurization	N/A	N/A	N/A
		N/A	N/A	N/A
	d. No of continuous staircase to terrace	N/A	N/A	N/A
	e. Width of Corridor	1.5m	NB: 1.55m, OB & Blk 3: 1.52, Blk 4 &5: 1.7m & 1.75 respectively	MR
	f. Door Size	1.0m	NB: 1.14, OB: 0.98m Blk 3: 1.10m, 1.0m, Blk4&5: 1.10m in each (Double door in each)	MR (old case)
3.	Compartmentation			
	<ul style="list-style-type: none">Fire check doorSealing of electrical shaftsFire Rating of shaft doorWater CurtainFire Dampers	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
4.	Smoke Managements System			
	<ul style="list-style-type: none">BasementsUpper floors	N/A	N/A	N/A
		Required	Natural ventilation	MR
5.	Fire Extinguishers			
	<ul style="list-style-type: none">Total numbersTypesISI marking	32 Nos	40Nos Provided	MR
		ABC & CO ₂	Provided	MR
		ISI Marked	Provided	MR
6.	First-Aid Hose Reels			
	<ul style="list-style-type: none">Total numbers on each floorLength of hose reel hoseNozzle diameter	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A

N-21

7.	Automatic fire detection and alarming system			
	• Type of detector	N/A	N/A	N/A
	• Location of Main Panel	N/A	N/A	N/A
	• Location of Repeater Panel	N/A	N/A	N/A
	• Alternate source of power	N/A	N/A	N/A
	• Hooters' Location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			
	• Basements	N/A	N/A	N/A
	• Upper Floor	N/A	N/A	N/A
	• Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	• Size of riser/down- comer	N/A	N/A	N/A
	• Number of hydrants per floor	N/A	N/A	N/A
	• Hose Box	N/A	N/A	N/A
12.	Yard Hydrants			
	• Total number of hydrants	N/A	N/A	N/A
	• Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements			
	• Ground Level			
	➤ Discharge of main pump	N/A	N/A	N/A
	➤ Head of main pump	N/A	N/A	N/A
	➤ Number of main pumps	N/A	N/A	N/A
	➤ Jockey pump out put	N/A	N/A	N/A
	➤ Jockey pump head	N/A	N/A	N/A
	➤ Standby Pump out put	N/A	N/A	N/A
	➤ Standby Pump Head	N/A	N/A	N/A
	➤ Auto Staring/Manual stopping	N/A	N/A	N/A
	➤ Pump House Access	N/A	N/A	N/A
	• Terrace level			
	➤ Discharge of pump	N/A	N/A	N/A
	➤ Head of the pump	N/A	N/A	N/A
	➤ Power supply	N/A	N/A	N/A
	➤ Auto starting of pump	N/A	N/A	N/A
14.	Captive water storage for firefighting			
	• Underground tank capacity	N/A	N/A	N/A
	➤ Draw of connection	N/A	N/A	N/A
	➤ Fire service inlet	N/A	N/A	N/A
	➤ Access to tank	N/A	N/A	N/A
	• Overhead Tank capacity	N/A	N/A	N/A
15.	Exit Signage	N/A	N/A	N/A
16.	Provision of Lifts			
	➤ Pressurization of Lift Shaft	N/A	N/A	N/A
	➤ Pressurization of lift lobby	N/A	N/A	N/A
	➤ Communication in lift Car	N/A	N/A	N/A
	➤ Fireman's Grounding Switch	N/A	N/A	N/A
	➤ Lift Signage	N/A	N/A	N/A
17.	Standby Power Supply	N/A	N/A	N/A
18.	Refuge Area			
	➤ Total area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A

19.	Fire Control Room			
	➤ Detector system panel	N/A	N/A	N/A
	➤ Flow Switch Panel	N/A	N/A	N/A
	➤ PA System Panel	N/A	N/A	N/A
	➤ Battery backup	N/A	N/A	N/A
	➤ Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection Systems for Protection of Special Risks, if any;			N/A

The fire protection systems provided in the building were checked, tested at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety required under the rules, the fire safety certificate issued vide letter No. F6/DFS/MS/SZ/2022/111 dated 03/02/2022, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for perusal/approval & signature please.

Suman
04.04.25
Signature of the Inspecting Officer
Name: Santosh Kumar
Designation: ADO (DWK)

DO (SW)

[Signature]
4/4/25

[Signature]

[Signature]
4/4/2025

Director

[Signature]
A/9/21

[Signature]

Sir, F+ letter is put up for your sig. pl

[Signature]
[Signature]

Suman
07.04.25