GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

00

No F6/DFS/MS/2025/School/WZ/ 9 7 9

Dated 11 08 2025

FIRE SAFETY CERTIFICATE

Certified that the Govt. Boys Sr. Sec. School (New Block) ID- 1309266 located at Bakhtawarpur, Delhi-110036 comprised of Ground + Three upper floors owned/occupied by Govt. Boys Sr. Sec. School have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules 2010 and verified by the officer concerned of Fire Service on 29.07.2025 in the presence of Sh. Arvind Kumar (Principal) and found that the building is fit for occupancy class Group B Educational (Excluding M.P. Hall) with effect from 11 68 2025 for a period of 03 (Three) years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on .. الله على الماء at New Delhi by

(Virendra Singh) Chief Fire Officer

Copy to:-

1. The Director, Education, Government of NCT of Delhi. Old Sect. Delhi-110054

2. Principal, Govt. Boys Sr. Sec. School, Bakhtawarpur, Delhi-110036.

Conditions for the validity of Fire Safety Certificate:

 All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.

Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

 Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

5. This certificate cannot be treated in any case for regularizations of unauthorized construction.

 The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

9. This FSC is only for Ground plus three upper floors excluding M.P. Hall.

INSPECTION REPORT

1. Name & address of the building: Govt. Boys Sr. Sec. School (New Building) located at Bakhtawarpur,

Delhi- 110036.

2. Type of Occupancy 3. Building Comprised of : Educational : Ground plus Three Upper Floors & 01 M.P. Hall single storey.

4. Type of Case 5. Details of Previous NOC : New Case

6. Fire Safety directives letter No : NBC Part IV 7. Date of inspection : 29/07/2025

8. Name of Inspecting Officer 9. Name and designation of officers : R.K.Sinha, ADO (BW)

From the building side : Sh. Arvind Kumar (Principal) 10. Year of Construction

lo.	prevention	NBC Part IV	Provided at site	Remarks		
	- Ty Duliding	Requirement	and the second	MR/NMR		
	Road width					
	Gate width	6 m	Provided	MR		
2.	• Widel or	4.5 m	Provided	MR		
	Width, Type & Arrangement	NA NA	NA	NA		
	a. Number of staircases					
	Upper Floors					
	Range	03	03	MR		
	b. Width of staircases	NA	NA	11		
	• Upper Floor		Shill I I Take a	NA		
	Basements	1.50 m each	Provided			
	c. Protection of exits	NA	19 29 10 10 10 10 10	MR		
	• Fire ch. 1		NA	NA		
	me check door	NA				
	ressurization	NA	NA	NA		
	d. No. of continuous staircases to	THAT WELL	NA	NA		
		03	Provided			
	e. Width of Corridor			MR		
		1.50 m	Provided			
3.	J OOI SIZE	1.20 m	ACC-244 A	MR		
·	Compartmentation	- Kerty-en-	Provided	MR		
	Fire check door					
		NA	NA			
	- Spanning of electrical shafts	NA		NA		
	- Rating of shaft door	NA	NA	NA		
	- dici Cuitain	NA	NA	NA		
4.	i iic Dailipers	NA	NA	NA		
	Smoke Wanagement System NA NA					
	Basements	NA		I be any		
	Upper floors		NA	NA		
		Required	Naturally Ventilated	74 BAUM		
5.	Fire Extinguishers	v"		MR		
	m I I					
	Types	15 Nos.	Provided	0		
	IS marking	ABC/ Co2 Type	Provided	MR		
-	First-Aid Hose Reels	Required	Provided	MR		
6.	MR					
		03	Provided			
		30 m	Provided	MR		
	Nozzle diameter	5 mm	Provided	MR		
	detection and alarmi	no svetam		MR		
7.	Automatic fire detection and alarming system Type of detectors NA NA NA					
	Type of detectors		NA	NA		
	Location of Main Panel	NA	NA			
	I Lection of Reneater Panel	NA	NA	NA		
	A ternate source of power	NA	NA	NA		
	Hooters' Location	NA		NA		
	1999		NA NA			

8.	MOEFA	N.21		7		
9.	Public Add	NA	NA	NA		
10.	Public Address System	NA	NA	NA		
	Automatic Sprinkler System Basement		100	NA		
	Ground Floor	NA -	NA	NA NA		
		NA	NA			
	Sprinkler above false ceiling	NA	NA	NA		
11.	Internal Hydrants					
	 Size of riser/down-comer 	NA	NA	NA		
	Number of hydrants per floor	NA	NA	NA		
12.	Hose Box	NA	NA	NA		
14.	Yard Hydrants	A 1910		1		
	Total number of hydrants	NA	NA	NA		
13.	Hose Box	NA	NA	NA		
	Pumping Arrangements	I Salara Maria				
	Ground Level					
	- technige of main rump	NA	NA	NA		
	Head of Main pump	NA	NA	NA		
	➤ Number of main pumps	NIA				
	➤ Jockey Pump out put	NA	NA NA	NA		
	➤ Jockey pump head	NA	NA	NA		
	Standby Pump out put	NA NA	NA	NA		
	Standby Pump Head	NA NA	NA	NA		
	Auto Starting/Manual	NA NA	NA	NA		
	Stopping	INA	NA	NA		
	Pump House Access	NA	NA	NA		
	Terrace level	T. Av				
	Discharge of pump	450 lpm	D 111			
	➤ Head of the pump	40 m	Provided Provided	MR MR		
	➤ Power Supply	Required	Provided	MR		
14.	Auto Starting of pump	The control of the control	Provided	MR		
	Suprive Water Storage for fire fighting					
	Underground tank capacity	NA	NA	NA		
	Draw-off connection	NA	NA NA	9		
	➤ Fire service inlet	NA	NA NA	NA		
	Access to tank	NA NA	NA NA	NA		
-	Overhead Tank capacity	10,000 ltrs		NA		
5.	Exit Signage.	Required	Provided	MR		
	A-91	ræquired	Provided	MR		
6.	Provision of Lifts.					
	Pressurization of Lift Shaft	NA	NA	NA		
	 Pressurization of Lift lobby 	NA	NA	NA		
	 Communication In lift Car 	NA	NA	NA		
	Fireman's Grounding Switch	NA	NA	NA		
	Lift Signage	NA	NA	NA		
7.	Standby power supply	NA	NA NA	TWO VOMENS		
		INA	- NA	NA		
3.	Refuge Area.	1.4.				
	➤ Total Area	NA	. NA	NA.		
	> Location	NA	NA	NA		
.	Fire Control Room					
	Detector System Panel	NA	NA	NA		
- 1	Flow Switch Panel	NA	NA	NA		
-	FIOW SWILL LAUGE			I NIA		
	PA System Panel	NA	NA	NA NA		

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The management had rectified the shortcomings issued vide letter no. F6/DFS/MS/School/2024/WZ/723 dated 22/10/2024.

Note: The Principal of the school has given undertaking to excluded the M.P. Hall.

Keeping in view of satisfactory compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, it is **recommended** to grant Fire Safety Certificate under Rule 35 of the Delhi Fire Service Rules, 2010.

Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W.

R. C.

CFO)
Story
S

CFO

Tulta ni proto for signi !

cfo | While 2005

Ms cell