GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE

No.F6/DFS/MS/School/2025/SZ/ 853

Dated: 03/07/2025

Delhi Fire Service

FIRE SAFETY CERTIFICATE

Certified that the Govt. Boys Sr. Sec. School located at KG-1/2, Vikaspuri, New Delhi-110018, building comprised of ground plus three upper floors, was issued FSC by this department vide letter No. F.6/DFS/MS/School/2022/SZ/605 dated 01.06.2022. The school building was re-inspected by the officer concerned of this department on dated 24.06.2025 in the presence of Sh. Bhom Singh Shakhawat (Principal), and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises (ground plus three upper floors) is fit for occupancy class "Educational Building" w.e.f. 63 64 2021 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on ___03|07|2025 at New Delhi by.

Copy to: -

1. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

2. The Principal, Govt. Boys Sr. Sec. School located at KG-1/2, Vikaspuri, New Delhi-18.

Conditions for the validity of fire safety certificate: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building

Building is comprised of

3. Type of Occupancy

4. Type of Case

5. Details of Previous FSC letter

6. Fire Safety direction letter No

7. Date of Inspection

8. Name of the Inspecting officers

9. Name and designation of Officer: From the building side

10. Year of Construction

11. Applicant's letter No

Govt. Boys Sr. Sec. School, KG -1/2, Vikaspuri, New Delhi-18.

G+3 upper floors. (New block)

Educational

Renewal

F.6/DFS/MS/School/2022/SZ/605 dated 01.06.2022

Nil

24.06.2025

ADO R.K. Yadav

Sh. Bhom Singh Shekhawat (Principal)

2020-2021

Form 'J' dated Nil, outdoor dairy No. 1526 dated 09.05.2025

Sr. No.	Minimum Standards on fire prevention and fire safety U/	Requirement	Provided at Site	Remarks MR/NMR				
1	Access to building							
	Road width	06 m.	Provided	MR				
	Gate width	4.5 m	Provided	MR				
	Width of internal road	N/A	N/A	N/A				
2	Number, Width, Type and Arrangement of Exits							
	a. Number of Staircases							
	Upper Floor	04 Nos.	04 Nos.	MR				
	Basement	N/A	N/A	N/A				
	B. Width of Staircases							
	Upper Floor	1.50 m each	1.77 M each	MR				
	Basement	N/A	N/A	N/A				
	c. Protection of exits	2	. + -					
	Fire check door	N/A	N/A	N/A				
	Pressurization	N/A	N/A	N/A				
	d. No. of continuous staircases terrace	to 04 No.	04 No.	MR				
	e. Width of Corridor	1.5 m.	1.7 m.	MR				
	f. Door Size	1.20 m	2X1.30 m	MR				
3	Compartmentation.							
	Fire check door	N/A	N/A	N/A				
	Sealing of electrical shapes	afts N/A	N/A	N/A				
	Fire rating of shaft doo	TOTAL WILLIAM TO THE PARTY OF T	N/A .	Ŋ/A				
	Water curtain	N/A	N/A	N/A				
	Fire Dampers	N/A	N/A	N/A				
4	Smoke Management System.							
	Basement	N/A	N/A	N/A				
	Upper floor	Required	Natural Ventilation	MR				
5.	Fire Extinguishers							
	Total numbers	40 nos.	Provided	MR				
	• Types	ABC /CO ₂	ABC /CO ₂	MR				
	IS marking	IS I marked	ISI marked	MR				



Mps

6	First-aid-Hose Reels.				
	Total numbers of each floor	04 Nos.	06 Nos.	100	
	Length of hose reel hose	30 m	Provided	MR MR	
	Nozzle diameter	05mm	Provided	MR	
7	Automatic fire detection and alarming system.				
	Type of detectors	N/A	N/A	N/A	
	Location of main panel	N/A	N/A	N/A	
	Location of repeater panel	N/A	N/A	N/A	
	Alternate source of power	N/A	N/A	N/A	
	Hooter's location	N/A	N/A	N/A	
8	MOEFA	N/A	N/A	N/A	
9	Public address System.	N/A	N/A	N/A	
10	Automatic Sprinkler System.				
	Basement	N/A	N/A	N/A	
	upper floor	N/A	N/A	N/A	
	sprinkler above false ceiling	N/A	N/A	N/A	
11	Internal Hydrants				
	size of riser/down-comer	N/A	N/A	N/A	
	Number of hydrants per floor	N/A	N/A	N/A	
	Hose Box	N/A	N/A	N/A	
12	Yard Hydrants.				
	Total number of hydrants	N/A	N/A	N/A	
	Hose Box	N/A	N/A	N/A	
13	Pumping Arrangements.				
	Ground Level				
	> Discharge of main Pump	N/A	N/A	N/A	
	> Head of Main Pump	N/A	N/A	N/A	
	> Number of main pumps	N/A	N/A	N/A	
	> Jockey pump out put	N/A	N/A	N/A	
	Jockey pump head	N/A	N/A	N/A	
	Standby pump out put	N/A	N/A	N/A	
	> Standby pump Head	N/A	N/A	N/A	
	> Auto Starting /Manual	N/A	N/A	N/A	
	stopping > Pump House Access	N/A	N/A	N/A	
	Terrace Level				
	➤ Discharge of pump	450 LPM	2 x 450 LPM	MR	
	➤ Head of the Pump	40 M	Provided	MR	
	> Power supply	Required	Provided	MR MR	
32	➤ Auto Starting of pump	Required	Provided	IVIK	
14	Captive Water Storage for Fire Fighting.				
	Underground tank capacity	N/A	N/A	N/A	
	> Draw-off connection	N/A	N/A	N/A	
	> Fire service inlet	N/A	N/A	N/A	
	> Access to tank	N/A	N/A	N/A MR	
	Overhead Tank capacity	10,000 Ltr.	10,000 Ltrs		
	0.00	l l		MR	

14

\mathcal{V}	124
l	

10						
	•	Pressurization of Lift Shaft	N/A			
11	•	Pressurization of Lift lobby		N/A	N/A	
	•	Communication in lift car	N/A	N/A	N/A	
	10:	Firemen's grounding switch	N/A	N/A	N/A	
	•	Lift Signage	N/A	N/A	N/A	
	-	NYSO CON	N/A	N/A	N/A	
17	Standb	y power supply	N/A	N/A	N/A	
18	Refuge Area.					
	•	Total area	N/A	N/A	N/A	
	•	Location	N/A	N/A	N/A	
19	Fire Control Room					
	•	Detector system panel	N/A	N/A	N/A	
	•	Flow switch panel	N/A	N/A	N/A	
	•	PA system panel	N/A	N/A	N/A	
	•	Battery backup	N/A	N/A	N/A	
	•	Building Floor Plans	N/A	N/A	N/A	
20	Special	Fire Protection systems for tion of special Risks, if any:	N/A	N/A	N/A	

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F.6/DFS/MS/School/2022/SZ/605 dated 01.06.2022, renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Signature of Inspecting Officer Name: - R.K. Yadav

Designation: - ADO (JKP)

DO (South West)

26/6/25

ĊĠ

30 61 201S

Diverta / / /

 \sim