

2/43

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE
CONNAUGHT PLACE: NEW DELHI-110001

No. F.6/DFS/MS/School/2025/SZ/ 812

Dated: 23/06/2025

FIRE SAFETY CERTIFICATE

Certified that the building of **Govt. Co-Ed. Senior Secondary School** located at Sector-3, Site-1, Dwarka, New Delhi-110075 (School ID: 1821203) comprised of **Ground + 03 upper floors**, owned/occupied by Directorate of Education, Govt. of NCT of Delhi, was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/SZ/2022/School/310 dated 23/03/2022. The premise was re-inspected by the officer concerned of this department on 14/06/2025 in the presence of Dr. Poonam (Vice Principal) and found that the premises have complied with the fire prevention and fire safety requirements in accordance with DOE Circular No. 3298-3398 dated 01/03/2010 and that the said building/premise is fit for occupancy class "**Educational Group B**" (School) with effect from 23/06/2025 for a period of **three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 23/06/2025 at New Delhi by

(ATUL GARG)
DIRECTOR

Ph. 011-23414000

Copy to: -

1. The Principal, Govt. Co-Ed. Senior Secondary School at Sector-3, Site-1, Dwarka New Delhi-110075 (School ID: 1821203).
2. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangement provided there in shall be maintained in good working conditions at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire-fighting system.
4. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
5. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, prior to its expiry.
6. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

| INSPECTION REPORT | | | | |
|-------------------|---|---|-------------------------------|------------------|
| 1. | Name & address of the building | Govt. Co-Ed. Senior Secondary School, Sector-3, Site-I, Dwarka, New Delhi-110075 (School ID: 1821203) | | |
| 2. | Type of Occupancy | Educational (Group-B) | | |
| 3. | Building Comprised of | Ground + 03 Upper Floors. | | |
| 4. | Type of Case | Renewal | | |
| 5. | Details of previous NOC No. | F6/DFS/MS/SZ/2022/School/310 Dt. 23/03/2022 | | |
| 6. | Fire Safety directives Letter No. | DOE Cir. 3298-3398 dated 01/03/2011 | | |
| 7. | Date of inspection | 14/06/2025 | | |
| 8. | Name of the Inspecting Officer | ADO (DWK) | | |
| 9. | Name and designation of Officer from the building side | Dr. Poonam (Vice Principal) | | |
| 10. | Year of Construction | 2010 | | |
| 11. | Applicant's letter No. | G. Co-Ed/Site-1/D-3/2025-26/123 Dt. 16.05.2025 Outdoor Diary No. 1775 dated 19 May 2025 | | |
| S. No. | Minimum standards on fire prevention and fire safety U/R 33 | Old NOC Requirement | Provided at site | Remarks MR/NMR |
| 1. | Access of building | | | |
| | • Road width | 06 mtr | Provided | MR |
| | • Gate width | 4.5 mtr | provided | MR |
| | • Width of internal road | N/A | N/A | N/A |
| 2. | Number, width, Type & Arrangements of exits | | | |
| | a. Number of staircases | | | |
| | • Upper floors | 4 Nos | Provided | MR |
| | • Basements | N/A | N/A | N/A |
| | b. Width of staircases | | | |
| | • Upper floors | 1.5m | 2 x 1.49m, 2 x 1.50m | MR (Old case) |
| | • Basements | N/A | N/A | N/A |
| | c. Protection of exits | | | |
| | • Fire check door | N/A | N/A | N/A |
| | • Pressurization | N/A | N/A | N/A |
| | d. No of continuous staircase to terrace | 2 Nos | Provided | MR |
| | e. Width of Corridor | 1.5m | 1.27m (Old case) | MR |
| | f. Door Size | 1.0 m | 90cm & 109cm (Double Door) | MR (old case) |
| 3. | Compartmentation | | | |
| | • Fire check door | N/A | N/A | N/A |
| | • Sealing of electrical shafts | N/A | N/A | N/A |
| | • Fire Rating of shaft door | N/A | N/A | N/A |
| | • Water Curtain | N/A | N/A | N/A |
| | • Fire Dampers | N/A | N/A | N/A |
| 4. | Smoke Managements System | | | |
| | • Basements | N/A | N/A | N/A |
| | • Upper floors | Required | Natural Ventilation | MR |
| 5. | Fire Extinguishers | | | |
| | • Total numbers | 16 Nos | 18 Nos | MR |
| | • Types | ABC & CO ₂ | Provided | MR |
| | • ISI marking | ISI Marked | Provided | MR |
| 6. | First-Aid Hose Reels | | | |
| | • Total numbers on each floor | 03 Nos | 05 Nos | MR |
| | • Length of hose reel hose | 30m | 30m | MR |
| | • Nozzle diameter | 5mm | 5mm | MR |

| | | | | |
|-----|--|------------|----------|-----|
| 7. | Automatic fire detection and alarming system | | | |
| | • Type of detector | N/A | N/A | N/A |
| | • Location of Main Panel | N/A | N/A | N/A |
| | • Location of Repeater Panel | N/A | N/A | N/A |
| | • Alternate source of power | N/A | N/A | N/A |
| | • Hooters' Location | N/A | N/A | N/A |
| 8. | MOEFA | N/A | N/A | N/A |
| 9. | Public Address System | N/A | N/A | N/A |
| 10. | Automatic Sprinkler System | | | |
| | • Basements | N/A | N/A | N/A |
| | • Upper Floor | N/A | N/A | N/A |
| | • Sprinkler above false ceiling | N/A | N/A | N/A |
| 11. | Internal Hydrants | | | |
| | • Size of riser/down-comer | N/A | N/A | N/A |
| | • Number of hydrants per floor | N/A | N/A | N/A |
| | • Hose Box | N/A | N/A | N/A |
| 12. | Yard Hydrants | | | |
| | • Total number of hydrants | N/A | N/A | N/A |
| | • Hose Box | N/A | N/A | N/A |
| 13. | Pumping Arrangements | | | |
| | • Ground Level | | | |
| | ➤ Discharge of main pump | N/A | N/A | N/A |
| | ➤ Head of main pump | N/A | N/A | N/A |
| | ➤ Number of main pumps | N/A | N/A | N/A |
| | ➤ Jockey pump out put | N/A | N/A | N/A |
| | ➤ Jockey pump head | N/A | N/A | N/A |
| | ➤ Standby Pump out put | N/A | N/A | N/A |
| | ➤ Standby Pump Head | N/A | N/A | N/A |
| | ➤ Auto Starting/Manual stopping | N/A | N/A | N/A |
| | ➤ Pump House Access | N/A | N/A | N/A |
| | • Terrace level | | | |
| | ➤ Discharge of pump | 450 LPM | 450 LPM | MR |
| | ➤ Head of the pump | 40m | 40m | MR |
| | ➤ Power supply | Required | Provided | MR |
| | ➤ Auto starting of pump | Required | Provided | MR |
| 14. | Captive water storage for firefighting | | | |
| | • Underground tank capacity | N/A | N/A | N/A |
| | ➤ Draw of connection | N/A | N/A | N/A |
| | ➤ Fire service inlet | N/A | N/A | N/A |
| | ➤ Access to tank | N/A | N/A | N/A |
| | • Overhead Tank capacity | 10,000 Ltr | Provided | MR |
| 15. | Exit Signage | Required | Provided | MR |
| 16. | Provision of Lifts | | | |
| | ➤ Pressurization of Lift Shaft | N/A | N/A | N/A |
| | ➤ Pressurization of lift lobby | N/A | N/A | N/A |
| | ➤ Communication in lift Car | N/A | N/A | N/A |
| | ➤ Fireman's Grounding Switch | N/A | N/A | N/A |
| | ➤ Lift Signage | N/A | N/A | N/A |
| 17. | Standby Power Supply | N/A | N/A | N/A |
| 18. | Refuge Area | | | |
| | ➤ Total area | N/A | N/A | N/A |
| | ➤ Location | N/A | N/A | N/A |

N-21

| | | | | |
|-----|--|-----|-----|-----|
| 19. | Fire Control Room | | | |
| | ➤ Detector system panel | N/A | N/A | N/A |
| | ➤ Flow Switch Panel | N/A | N/A | N/A |
| | ➤ PA System Panel | N/A | N/A | N/A |
| | ➤ Battery backup | N/A | N/A | N/A |
| | ➤ Building Floor Plans | N/A | N/A | N/A |
| 20. | Special Fire Protection Systems for Protection of Special Risks, if any; | | | N/A |

The fire protection systems provided in the building were checked, tested at random and found functional at the time of inspection. The shortcomings communicated vide letter No. F.6/DFS/MS/School/2025/SZ/185 dated 03/04/2025 found rectified.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety required under the DOE circular, the fire safety certificate issued vide letter No. F6/DFS/MS/2022/School/310 dated 23/03/2022, renewal under rule 37 of Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for perusal/approval and signature please.

Signature of the Inspecting Officer
Name: Santosh Kumar
Designation: ADO (DWK)

DO (SW)

DO
17/6/25

CGO / Ward
18/6/2025

Director

Sir, F.T. Wtgs is put up for your sing. pl

Director / Ward
20/6/25

Ward
20/06/25