GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110001

No. F6/DFS/MS/School/2025/SZ/ 484

Dated: 15/04/2025

FIRE SAFETY CERTIFICATE

Certified that the Govt. Girls Sr. Sec. School at Ghumanhera, New Delhi-110073, Comprised of ground plus one upper floor only and MP Hall, owned/occupied by Govt. Girls Sr. Sec. School was issued FSC by this department vide letter No. F.6/DFS/MS/school/2022/SZ/648 dated 15.06.2022. The school building was re-inspected by the officer concerned of this department on dated 23.01.2025 in the presence of Mr. Dharmender Dagar and found that School building have deemed complied the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises (ground plus one upper floor except MP Hall) is fit for occupancy class "Educational" w.e.f. 15 04 2025 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on 15 04 2025 at New Delhi by.

Director

Delhi Fire Service

Copy to: -

1. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

2. The Principal, Govt. Girls Sr. Sec. School at Ghumanhera, New Delhi-110073.

Conditions for the validity of fire safety certificate: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building : Govt. Girls Sr. Sec. School at Ghumanhera, New Delhi-110073

2. Building comprised of : Ground plus one upper floor and MP Hall

3. Type of Occupancy : Educational
4. Type of Case : Renewal

5. Details of Previous NOC : F.6/DFS/MS/school/2022/SZ/648 dated 15.06.2022

6. Fire Safety directives letter No : DFS Act & Rules 2010

7. Date of inspection : 04.04.2025

8. Name of Inspecting Officer : A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side : Sh. Dharmender Dagar

10. Year of Construction : 2016-17

11. Applicant's letter No. : SV/GH/2025/ dated 21.02.2025

| No. | Minimum Standards on fire prevention and fire safety U/R 33 | NBC Requirement | Provided at site | Remarks MR/NMR |
|-----|---|-----------------------------------|--|--------------------------|
| | Access to building | | | |
| | Road width | Accessible 06 m | 06 m | MR |
| | Gate width | 4.5 m | Provided | MR |
| | Width of internal road | N/A | N/A | N/A |
| 2. | Number, Width, Type & Arrangem | ent of Exits | | |
| | a. Number of staircases | | |) (D |
| | Upper Floors | 03 No.'s | 03 No.'s | MR |
| | Basements | N/A | N/A | N/A |
| | b. Width of staircases | | | |
| | Upper Floor | 1.50 m | 1.50 m | MR |
| | Basements | N/A | N/A | N/A |
| | c. Protection of exits | | | |
| | Fire check door | N/A | N/A | N/A |
| | Pressurization | N/A | N/A | N/A |
| | d. No. of continuous staircases to | | | |
| | terrace | 02 No.'s | 02 No.'s | MR |
| | e. Width of Corridor | 1.50 m | 2.25 m | MR |
| | f. Door Size | 1.0 m in CR & 2.0 m in MP Hall | .98 to 1.0 m (Double door) in CR & 1.80 m (02 no.'s) in MP Hall | MR in CR & NM in MP Hall |
| 3. | Compartmentation | | | |
| | Fire check door | N/A | N/A | N/A |
| | Sealing of electrical shafts | N/A | N/A | N/A |
| | Fire Rating of shaft door | N/A | N/A | N/A |
| | Water Curtain | N/A | N/A | N/A |
| | Fire Dampers | N/A | N/A | N/A |
| 4. | Smoke Management System | | | |
| 4. | | N/A | N/A | N/A |
| | Basements Upper floors | Required | Natural ventilation provided | M/R |
| 5. | Fire Extinguishers | | | 1 |
| J. | | 20 no's | Provided | MR |
| | Total numbersTypes | ABC/CO ₂ type | Provided | MR |
| | IS marking | ISI marked | Provided | MR |
| 6. | First-Aid Hose Reels | | (for M | P Hall) |
| | Total numbers | One | Provided | MR |
| | Total numbers Length of hose reel hose | 30 m | Provided | MR |
| | Nozzle diameter | 5 mm | Provided | MR |

| | Automatic fire detection and alarmin | g system | | N/A |
|-------|--|-------------|----------------------|------------|
| | | N/A | N/A | N/A |
| | • Type of detectors | N/A | N/A | |
| | Location of Main Panel Spaneater Panel | N/A N/A | N/A | N/A |
| | Location of Repeater Panel Alternate source of power. | N/A N/A | N/A | N/A |
| | Alternate source of power Hooters' Location | N/A | N/A | N/A |
| | Hoolers Location | | N/A | N/A |
| 3. | MOEFA | N/A | N/A | N/A |
|). | Public Address System | N/A | | |
| 10. | Automatic Sprinkler System | | N/A | N/A |
| | Basement | N/A | N/A | N/A |
| | Ground Floor | N/A | N/A N/A | N/A |
| | Sprinkler above false ceiling | N/A | N/A | |
| 11. | Internal Hydrants | | | 27/4 |
| | g: C'arr/down comer | N/A | N/A | N/A |
| | Size of riser/down-confer Number of hydrants per floor | N/A | N/A | N/A |
| | Number of hydrants per floor Hose Box | N/A | N/A | N/A |
| | | | | |
| 12. | Yard Hydrants | 27/4 | N/A | N/A |
| | Total number of hydrants | N/A | N/A | N/A |
| | Hose Box | N/A | 17/12 | |
| 13. | Pumping Arrangements | | | |
| | Ground Level | | 27/4 | N/A |
| | > Discharge of main Pump | N/A | N/A | N/A |
| | > Head of Main pump | N/A | N/A | N/A |
| | > Number of main pumps | N/A | N/A | N/A |
| | > Jockey Pump out put | N/A | N/A | N/A |
| | > Jockey pump head | N/A | N/A | N/A |
| | Standby Pump out put | N/A | N/A | N/A |
| | Standby Pump HeadAuto Starting/Manual | N/A | N/A | N/A |
| | > Auto Starting/Manual Stopping | N/A | N/A | |
| | | N/A | N/A | N/A |
| | > Pump House Access | | | MD |
| | Terrace level (for MP Hall) Discharge of pump | 450 LPM | Provided | MR MR |
| | Discharge of pump Head of the pump | 30 mtrs. | Provided Provided | MR |
| | > Power Supply | Required | Provided | MR |
| | > Auto Starting of pump | Required | Tiovided | |
| 14. | Captive Water Storage for fire fighting | | | |
| | Underground tank capacity | N/A | N/A | N/A |
| | > Draw-off connection | N/A | N/A | N/A |
| | > Fire service inlet | N/A | N/A | N/A |
| | Access to tank Overhead Tank capacity (for | N/A | N/A | N/A |
| | MP Hall) | 5,000 ltrs. | 10,000 ltrs | MR MR |
| 15. | Exit Signage. (In MP Hall) | Required | Provided | |
| 16. | Provision of Lifts. | • | No Lift | |
| Res v | Pressurization of Lift Shaft | N/A | N/A | N/A |
| | Pressurization of Lift lobby | N/A | N/A | N/A |
| | Communication In lift Car | N/A | N/A | N/A |
| | Fireman's Grounding Switch | N/A | N/A | N/A N/A |
| | Lift Signage | N/A | N/A | IVA |

| tandby power supply | N/A | N/A | N/A |
|--|-----|--------|------------|
| lefuge Area. | | 200.00 | 1471 |
| > Total Area | 27/ | | |
| ➤ Location | N/A | N/A | N/A |
| Fire Control Room | N/A | N/A | N/A |
| Flow Switch Panel PA System Panel | N/A | N/A | N/A N/A |
| Detector System Panel Flow Society Panel | N/A | N/A | N/A |
| Tri System Fanel | N/A | N/A | N/A |
| Dattery backup | N/A | N/A | N/A |
| Building Floor Plans | N/A | N/A | N/A |
| Special Fire Protection System for Protection of special Risks, if any: | N/A | N/A | N/A |

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F.6/DFS/MS/school/2022/SZ/648 dated 15.06.2022, renewal under rule, 37 of the Delhi Fire Service Rules, 2010 is recommended.

Signature of Inspecting Officer

Name: - R.K. Yadav Designation: - ADO (JKP)

DO (South West)

84/15

De nectar