अप्रतिका अपरा महोत्सव

No. F6/DFS/MS/School/NDZ/2025/ 837

Dated: 30 /06/2025

## FIRE SAFETY CERTIFICATE

Certified that the Govt. Girls Senior Secondary School located at Block-27, Trilokpuri, Delhi – 110091, (Building I.D – 10021615) Comprised of (05 blocks) Ground plus one upper floors, owned / occupied by Govt. Girls Senior Secondary School was issued FSC vide letter No. F6/DFS/MS/School/NDZ/2022/649 dated 15/06/2022. The School building have complied with the fire prevention and fire safety requirements in accordance with the Circular No.F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated01/03/2011 issued by the Director of Education and re-inspected by the officer concerned of this department on 23/06/2025 in presence of Ms. Anita Chauhan (Principal) of the school and that the school building is fit for occupancy class "Educational Building" (Group-B) with effect from 30/06/2025 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010 & also conditions printed bellow.

Issued on 30 06 2025 at New Delhi by.

DIRECTOR DELHI FIRE SERVICE

## Copy to:-

- 1. The Dy. Director of Education, D Block, Anand Vihar, Delhi 110092.
- 2. The Principal, Govt. Girls Senior Secondary School located at Block-27, Trilokpuri, Delhi 110091.

## Conditions for the validity of Fire Safety Certificate

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipment's and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the firefighting equipment's shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- 6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.

01.	Na	me	& address of the building	ECTION REPORT		W 141 7 10			
				Govt. Girls Senior Secondary School located Block-27, Trilokpuri, Delhi - 110091(Buildin I.D – 10021615.					
02.	Bu	ildi	ng is comprised of	Ground plus one upper floor only					
03.	Ту	pe e	of occupancy	Educational					
04.	Ту	pe e	of case	Renewal					
05.	De	tail	s of previous FSC						
06.			Marin of Lade	F6/DFS/MS/School/NDZ/2022/649 dated 15/06/2022					
7-	Fire safety directives letter no. F.16/Estate/CC/Fire Safety/2011/3298 to 339 dated 01/03/2011					298 to 3398			
07.	Da	te c	of inspection	23/06/2025					
08.			of the inspecting officers	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Yashwant Singh Meena ADO (L.N)				
09.	Na	me	of the designation of office		The state of the s	)			
Ž	fro	m t	he building side	i Wis. Ainta Chau	Ms. Anita Chauhan (Principal)				
10.			of construction	2002	mark and the	prior of the R			
11.	Applicant's letter no.			Email dated 16	Email dated 16/06/2025				
S.No	p		nimum standard of fire ention and fire safety U/R	Circular Requirement	Provided at site	Remarks MR/NMF			
М	7		33		and resemble				
01.	-		s to Building:			ne hii			
	A	-	oad width	6.0 mtrs.	10 mtrs.	MR			
	В		ate width	4.5 mtrs.	4.5 & 4.0 mtrs.	MR			
	C		Vidth of internal road	N/A	N/A	N/A			
02.			oer, Width, Type and Arra	ngement of Exits:					
	A	N	lumber of staircases	A1. 10	Will be the state of the				
		a	Upper floor	05 nos.	10 nos.	MR			
1 -		b	All Blocks	01 no.	02 no.	MR			
		_	Basement	N/A	N/A	N/A			
	В	- 1	Vidth of staircases						
		a	A block	1.50 mtrs.	1.25 & 1.5 mtrs	MR			
10		b	B block	1.50 mtrs.	1.40 mtrs each	MR			
		С	C block	- 1.50 mtrs.	1.5 mtrs each	MR			
1 ×	1	d	D block	1.50 mtrs.	1.5 mtrs each	MR			
		е	E block	1.50 mtrs.	1.5 mtrs each	MR			
		f	Basement	N/A	N/A	N/A			
	C		otection of exits	Handdous (	ushigi gwal siy	V 4			
	11	a	Fire check door	N/A	N/A	N/A			
	200	b	Pressurization	N/A	N/A	N/A			
	D	st	o. of continuous aircases to terrace	05 nos.	05 nos.	MR			
	E		/idth of corridor	1.50 mtrs.	1.5 to 1.7 mtrs	MR			
02	F	_	oor size	1.0 mtr	1.0 mtr.	MR			
03.			artmentation: re check door	77/4	Mary III III III III III III III III III I				
	A	- 7	Sept.	N/A	N/A	N/A			
	B		ealing of electrical shafts re rating of shaft door	N/A	N/A	N/A			
	C		re rating of shall door	N/A	N/A	N/A			
	D	17500		N/A	N/A	N/A			
-	E		re dampers	N/A	N/A	N/A			
		- 2				4 1/ 4 7			
04.	Sm		e Management System:	2000					
04.		В	asement  pper floor	N/A N/A	N/A	N/A			

Govt. Girls Secondary School located at Block-27, Trilokpuri, Delhi - 110091.

05	5-0-0							
	A		21 nos.	22 nos.	MR			
	E		ABC/CO <sub>2</sub>	ABC/CO <sub>2</sub>	MR			
	C	8	ISI Marked	ISI Marked	MR			
06								
	A	Total numbers of each floor	N/A	N/A	N/			
	В		N/A	N/A	N/			
	C		N/A	N/A	N/			
07.	. A	utomatic Fire Detection and Alarm	ing System:					
	A	7.1	N/A	N/A	N/A			
	В		N/A	N/A	N/A			
	C		N/A	N/A	N/A			
	D	Alternate source of power	N/A	N/A	N/A			
	E	Hooters	N/A	N/A	N/A			
08.	APRICE.	OEFA:	N/A	N/A	N/A			
09	_	ıblic Address System:	N/A	N/A	N/A			
10.	_	tomatic Sprinkler System:						
	A	Basement	N/A	N/A	N/A			
gh	B	Upper floor	N/A	N/A	N/A			
	C	Sprinkler above false ceiling	N/A	N/A	N/A			
11.	In	ternal Hydrants:		Manage and a second				
	A	Size of riser/down-comer	N/A	N/A	N/A			
- 1	B	Number of hydrants per floor	N/A	N/A	N/A			
	C	Hose box	N/A	N/A	N/A			
2.	Ya	rd Hydrants:	Processes	Names Westell	24			
	A	Total number of hydrants	N/A	N/A	N/A			
	B	Hose box	N/A	N/A	N/A			
3.	Pu	mping Arrangements:		ardicine T				
- 15	G	round level		La Millia				
	A	Discharge of main pump	N/A	N/A	N/A			
3	В	Head of main pump	N/A	N/A	N/A			
	C	Number of main pumps	N/A	N/A	N/A			
Γ	D	Jockey pump out put	N/A	N/A	N/A			
	E	Jockey pump head	N/A	N/A	N/A			
	F	Standby pump out put	N/A	N/A	N/A			
Į.	G	Standby pump head	N/A	N/A	N/A			
	H	Auto starting /manual stopping	N/A	N/A	N/A			
	I	Pump house access	N/A	N/A	N/A			
1	Teri	ace Level	. 1/42	113 121 0				
-	A	Discharge of pump	N/A	N/A	N/A			
_	В	Head of the pump	N/A	N/A	N/A			
-		Power supply	N/A	N/A	N/A			
1 .		Auto starting of pump	IN/A	14/71	TANTA			

Govt. Girls Secondary School located at Block-27, Trilokpuri, Delhi - 110091.

14.	Captive Water Storage for Fire Fighting:						
	A	Underground tank capacity	N/A	N/A	N/A N/A		
	В	Draw-off connection	N/A	N/A	N/A		
	C	Fire service inlet	N/A	N/A	12.00		
	D	Access to tank	N/A	N/A	N/A		
	E	Overhead tank capacity	N/A	N/A	N/A		
15.	100 miles	it Signage:	N/A	N/A	N/A		
16.	Provision of Lifts:			27/4	N/A		
	A	Pressurization of lift shaft	N/A	N/A	N/A		
	B	Pressurization of lift lobby	N/A	N/A	N/A		
	C	Communication in lift car	N/A	N/A	N/A		
	D	Firemen's grounding switch	N/A	N/A	N/A		
	E	Lift signage	N/A	N/A	N/A		
	1500	andby Power Supply:	NA	N/A	* "		
17.			27/4	N/A			
18.	-	fuge Area:	N/A	N/A	N/A		
	A	Total area	N/A	N/A	14/12		
	В	Location			N/A		
19.	Fire Control Room:		N/A	N/A	N/A		
	A	Detector system panel	N/A	N/A	N/A		
	В	Flow switch panel	N/A	N/A	N/A		
	C	PA system panel	N/A	N/A	N/A		
	D	Battery backup	N/A	N/A	N/A		
	E	Building floor plans ecial Fire Protection systems for	NA	N/A	IN/A		
20.	Spe	otection of special Risks, if any:					

The fire protection system was randomly checked and tested and was found functional at the time of inspection.

Keeping in view of the deemed compliance of minimum standards on fire prevention and fire safety measures as required under the Rules the Fire Safety Certificate issued vide letter no. F6/DFS/MS/School/NDZ/2022/649 dated 15/06/2022 under the Circular no F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011 is recommended to be renewed.

Signature of the Inspecting Officer
Name: - Yashwant Singh Meena

Designation: - ADO (L.N)

D.O JED

by 070 (102)

25/04/25

C.F.O. +> On leave

Directory

Rota Mr