

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE

NEW DELHI- 110001

No. F6/DFS/MS/School/2025/SZ/ 496

Dated: 16/04/2025

FIRE SAFETY CERTIFICATE

Certified that the Govt. Sarvodaya Co-Ed Vidyalaya located at L-Block, Hari Nagar, New Delhi-110064, comprised of ground plus three upper floors (New Block), owned/occupied by Sarvodaya Co-Ed Vidyalaya, was issued FSC by this department vide letter No. F.6/DFS.MS/School/2022/SZ/389 dated 06.04.2022. The school building was re-inspected by the officer concerned of this department on dated 02.04.2025 in the presence of Mr. Sahoo (Estate Manager) and found that School building have deemed complied the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises (ground plus three upper floors) is fit for occupancy class "Educational Building" w.e.f. 16 04 2025 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed as below Issued on 16 04 2025 at New Delhi by.

> Atul Garg) Director Delhi Fire Service

Copy to: -

Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054

The Principal, Govt. Sarvodaya Co-Ed Vidyalaya located at L-Block, Hari Nagar, New Delhi- 110064. 1. 2.

Following fire safety directives must be adhered to: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

Name & address of the building

Sarvodaya (Co-Ed) Vidyalaya, L-Block, Hari Nagar, New Delhi-110064.

Building is comprised of

G+3 upper floors. (New block)

Type of Occupancy

Educational

Type of Case

Renewal

5. Details of Previous NOC letter

F.6/DFS.MS/School/2022/SZ/389 dated 06.04.2022

6. Fire Safety direction letter No

Nil

Date of Inspection 7.

02.04.2025

8. Name of the Inspecting officers

A DO R.K. Yadav

9. Name and designation of Officer

From the building side

Sh. Sahoo (Estate Manager)

10. Year of Construction

2019-20

11. Applicant's letter No.

Sr. NO.	11. Applicant's letter No : 89/SV/HN dated 21.02.2025						
	Minimum Standards on fire prevention and fire safety U/R33	n Requirement	Provided at Site	Remarks			
l	Access to building						
	Road width	06 m.	Provided	MR			
	Gate width	N/A	N/A	N/A			
	Width of internal road	N/A	N/A	N/A			
2	Number, Width, Type and Arrangement of Exits						
	a. Number of Staircases						
	Upper Floor	02 Nos.	02 Nos.	MR			
	Basement	N/A	N/A	N/A			
	B. Width of Staircases	а					
	• Upper Floor	1.50 m each	1.80 M each	MR			
	• Basement	N/A	N/A	N/A			
	c. Protection of exits	N/A	N/A	N/A			
	Fire check doorPressurization	N/A	N/A	N/A			
	e. No. of continuous staircases to	02 No.	02 No.	MR			
	terrace	1.5 m.	1.8 m.	MR			
	g. Width of Corridor h. Door Size	1.20 m	1.20 m	MR			
3	Compartmentation.						
		27/4	27/1	1			
	• Fire check door	N/A	N/A	N/A			
	Sealing of electrical shafts	N/A	N/A	N/A			
	Fire rating of shaft door	N/A	N/A	N/A			
	Water curtain	N/A	N/A	N/A			
	• Fire Dampers	N/A	N/A	N/A			
4	Smoke Management System.						
	Basement	N/A	N/A	N/A			
	 Upper floor 	Required	Natural Ventilation	MR			
5.	Fire Extinguishers						
	Total numbers	08 Nos.	10 Nos.	MR			
	• Types	ABC & Co2	ABC & Co2	MR			
	IS marking	ISI marked	ISI marked	MR			
	First 11 W			IVIX			
6.	First-aid-Hose Reels.						
	Total numbers of each floor	03Nos.	Provided	MR			
	• Length of hose reel hose	30 m	Provided	MR			
	Nozzle diameter	05mm	Provided	MR			
		L		IVIK			

7	Automatic fire detection and alarming sys	stem.		
	Type of detectors	N/A	N/A	N/A
	Location of main panel	N/A	N/A	N/A
	 Location of repeater panel 	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooter's location	N/A	N/A	N/A
8	MOEFA	N/A	N/A	N/A
9	Public address System.	N/A	N/A	N/A
10	Automatic Sprinkler System.			
	Basement	N/A	N/A	N/A
	upper floor	N/A	N/A	N/A
	sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants			
	size of riser/down-comer	N/A	N/A	N/A
	Number of hydrants per floor	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
12	Yard Hydrants.			
	Total number of hydrants	N/A	DT/A	27/1
	Hose Box	N/A N/A	N/A N/A	N/A
13	Pumping Arrangements.			N/A
		N/A	N/A	N/A
	Ground Level	N/A	N/A	N/A
	 Discharge of main Pump Head of Main Pump 	N/A	N/A	N/A
	or main rump	N/A	N/A	N/A
	Number of main pumpsJockey pump out put	N/A	N/A	N/A
	> Jockey pump head	N/A	N/A	N/A
	> Standby pump out put	N/A	N/A	N/A
	> Standby pump Head	N/A N/A	N/A	N/A
	> Auto Starting /Manual stopping	N/A	N/A	N/A
	> Pump House Access	N/A	N/A	N/A
	Terrace Level	IVA	N/A	N/A
	Discharge of pump	450 LPM	450 770 7 77	
	➤ Head of the Pump	40 M	450 X2 LPM	MR
	> Power supply	Required	Provided	MR
	➤ Auto Starting of pump	Required	Provided	MR
14	Captive Water Storage for Fire Fighting.	•	Provided	MR
		N/A	N/A	N/A
	 Underground tank capacity Draw-off connection 	N/A	N/A	N/A
	> Fire service inlet	N/A	N/A	
	> Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	N/A	N/A N/A
5	Exit Signage.	10,000 Ltr.	10,000 Ltrs	MR
		Required	Provided	
6	Provision of Lifts.	•	Frovided	MR
	Pressurization of Lift Shaft	N7/A		
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication in lift car	N/A	N/A	
	Firemen's grounding switch	N/A	N/A	N/A
M	Lift Signage	N/A	N/A	N/A
	06-	N/A		N/A

1	27	
		123

Standby power supply			
	N/A	N/A	N/A
	N/A	N/A	N/A
 Location 	N/A	N/A	N/A
Fire Control Room	N/A	N/A	N/A
	N/A	N/A	N/A
Flow switch panel	N/A	N/A	N/A
PA system panel		N/A	N/A
		N/A	N/A
Building Floor Plans		N/A	N/A
	N/A	N/A	N/A
protection of special Risks, if any:	N/A	N/A	N/A
	Refuge Area. Total area Location Fire Control Room Detector system panel Flow switch panel PA system panel Battery backup Building Floor Plans Special Fire Protection systems for	Refuge Area. N/A Total area Location N/A Fire Control Room N/A Detector system panel Flow switch panel PA system panel N/A Battery backup Building Floor Plans N/A Special Fire Protection systems for	Refuge Area. N/A N/A N/A N/A Total area N/A Location N/A N/A N/A N/A N/A N/A N/A N/

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F.6/DFS.MS/School/2022/SZ/389 dated 06.04.2022, renewal under rule, 37 of the Delhi Fire Service Rules, 2010 is recommended.

Signature of Inspecting Officer

Name: - R.K. Yadav Designation: - ADO (JKP)

DO (South West)

7/4/25

8 41 5

Director / My

Sloules yoursh

Thetter is put up for soon

DIRECTORMA

Clar

11/04/2028