



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

c/48



No: F.6/DFS/MS/School/2025/WZ/ 451

Dated: 26/05/2025

To,  
The Principal,  
Govt. Sarvodaya Kanya Vidyalaya,  
BL Block, Shalimar Bagh,  
Delhi-110086.

Sub: - Regarding issuance of Fire Safety Certificate in r/o Govt. Sarvodaya Kanya Vidyalaya located at BL Block, Shalimar Bagh, Delhi-110088.

Sir,

This has reference to your letter no. SKV/BL/SB/1336 dated 08/05/2025 received through outdoor diary no. 1543 dated 13.05.2025 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 21.05.2025 to see the compliance of the shortcomings issued vide letter no. F6/DFS/MS/School/2023/WZ/586 dated 15/12/2023 in presence of Smt. Aishwarya Ratna Pandey (H.O.S.). During the course of inspection it was observed that shortcomings of above mentioned letter were not rectified yet.

You are advised to rectify the shortcomings for taking further action as necessary for issuance of Fire Safety Certificate.

Yours Faithfully

(Atul Garg)

Director

Ph. 011-23414000

23/5

Copy to:-

1. Director of Education, Govt. Of NCT of Delhi, Old Secretariat, New Delhi.

c/38  
30  
3

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No: F.6/DFS/MS/School/2023/WZ/ 586

Dated: 15/12/2023

To,  
The Principal,  
Govt. Sarvodaya Kanya Vidyalaya,  
BL Block, Shalimar Bagh,  
Delhi-110086.

Sub: - Regarding issuance of Fire Safety Certificate in r/o Govt. Sarvodaya Kanya Vidyalaya located at BL Block, Shalimar Bagh, Delhi-110086.

Sir,

This has reference to your letter no. SKV/BL/2023/SB/3563 dated 21/11/2023 received via outdoor diary no. 8937 dated 21.11.2023 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 01.12.2023 to see the compliance of the requisite fire safety measures. Sh. Smt. Aishwarya Ratna Pandey (H.O.S) was present at the time of inspection.

During the course of inspection it was observed that previously this department had issued FSC for a building of Ground plus three upper floors vide letter no. F6/DFS/MS/School/WZ/2020/556 dated 16/12/2020 but now the school building found comprised of three blocks interconnected (01 Block- Ground plus three upper floors & 02 Blocks- Ground plus two upper floors). Your request for issuance of FSC is rejected as the following shortcomings were observed:-

1. Width of staircases of Block 03 found 1.40 m each against the required width of 1.50 m each.
2. First Aid Hose reels not provided in block 02 & 03.
3. Terrace level pumps found provided but not functional.
4. Exit signage's not provided.
5. Electric meter and electrical panel found installed in a room which opens into the corridor.
6. Building plan for new blocks not provided.

You are advised to rectify the above-mentioned shortcoming for taking further action as necessary for issuance of Fire Safety Certificate.

Yours Faithfully

(Atul Garg)  
Director

Ph. 011-23414000

Copy to:-

1. Director of Education, Govt. Of NCT of Delhi, Old Secretariat, New Delhi.