



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/GH/2025/SZ/63

Dated: 03/02/2025

FIRE SAFETY CERTIFICATE

Certified that M/s Grand Plaza Guest House located at Prop. No. 3429-3434, Desh Bandhu Gupta Road, Pahar Ganj, New Delhi-110055, comprised of Basement, Stilt, Ground + 03 upper floors, [Basement (Storage), Stilt Floor (Parking), Ground Floor (Reception) 1st to 3rd Floor (09 guest rooms at each), total 27 guest rooms], owned/occupied by M/s Grand Plaza Guest House, was issued FSC by this department vide letter No. F6/DFS/MS/GH/NDZ/2021/233 dated 19/07/2021. The premises was re-inspected by the officer concerned of this department on dated 22/01/2025 in the presence of Sh. Lalit Mittal (Caretaker) and found that said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential, Sub Division A-1" (1st Floor to 3rd Floor-09 guest rooms at each floor, total 27 guest rooms only), with effect from 03/02/2025 for a period up to 31/03/2028 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on <u>03</u>/02 /2025 at New Delhi by

DIRECTOR T. No. 011-23414000

Copy to: -

- The Joint Commissioner of Police, Licensing Unit, 1st Floor, Police Station Defence Colony, New Delhi – 110049 (w.r.t. Online ID: 2025011100397 dated 11/01/2025)
- 2. Ms. Anita Mittal M/s Grand Plaza Guest House at Prop. No. 3429-3434, Desh Bandhu Gupta Road, Pahar Ganj, New Delhi-110055 <mittal_lalit@hotmail.com>

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangement provided therein shall be maintained in good working conditions at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 5. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry.

N-27

1 T	Nome & address St. 1 333		Count II count land	nd at Dean		
1.	Name & address of the building	Grand Plaza Guest House located at Prop. No. 3429-3434, Desh Bandhu Gupta Road, Pahar Ganj, New Delhi-110055				
2.	Type of Occupancy	Residential "Group A-1" (Guest House)				
3.	Building Comprised of	B+S+G+03 UFs. (Total 27 Guest Rooms) [Basement (Storage), Stilt Floor (Reception + Parking), Ground Floor to 3 rd Floor (09 guest rooms at each floor) & floor above TF not in use as per affidavit dt. 20/12/19]				
4.	Type of Case	Renewal				
5.	Details of previous NOC No.	F6/DFS/MS/GH/NDZ/2021/233 Dt 19/07/2021				
6.	Fire Safety directives Letter No.	Nil				
7.	Date of inspection	22/01/2024				
8.	Name of the Inspecting Officer	ADO (SJ)				
9.	Name and designation of Officer	Sh. Lalit Mittal (Caretaker)				
10	from the building side	2009 (N/8)				
10. 11.	Year of Construction Applicant's letter No./Online ID.	No. 2025011100397 dated 11/01/2025				
S.	Minimum standards on fire	Requirement/	Provided at site	Remarks		
No.	prevention and fire safety U/R 33	Existing Fire Safety Measures	7-10 ⁴ (MR/NMR		
1.	Access of building		16	MR		
	Road width	N/A	16 mtr	N/A		
	Gate width	N/A	N/A	N/A		
	Width of internal road	N/A	N/A	N/A		
2.	Number, width, Type & Arrangements	of exits				
854873	a. Number of staircases					
	Upper floors	01 No.	01 No	MR		
	Basements	01 No.	01 No.	MR		
	b. Width of staircases					
	Upper floors	1.50 mtr	1.50 mtr	MR		
	Basements	1.10 mtr	1.10 mtr	MR		
	c. Protection of exits	As per clause 7.31 of UBBL 2016				
	Fire check door	Required	Provided	MR		
	Pressurization	N/A	N/A	N/A		
	d. No of continuous staircase to terrace	01 No.	01 No.	MR		
	e. Width of Corridor	1.50 mtr	1.67 mtr	MR		
	f. Door Size	1.25 mtr	1.25 mtr	MR		
3.	Compartmentation					
	Fire check door	N/A	N/A	N/A		
	 Sealing of electrical shafts 	N/A	N/A	N/A		
	 Fire Rating of shaft door 	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	• Fire Dampers	N/A	N/A	N/A		
4.	Smoke Managements System	20 4 0077	D.1	1.00		
	Basements Unear floors	30 ACPH 12 ACPH	Exhaust fan Natural/Exh. Fan	MR MR		
5.	Upper floors Fire Extinguishers	12 ACFII	Matural/EXII. Pan	IVIK		
٦,	Total numbers	10 Nos	10 Nos	MR		
		ABC/ CO ₂				
	Types	50 34 247	ABC & CO ₂	MR		
	ISI marking First Aid Hose Books	Required	Provided	MR		
6.	First-Aid Hose Reels	0137				
	Total numbers on each floor	01 No.	01 No.	MR		
	Length of hose reel hose	30 mtr	30 mtr	MR		
	Nozzle diameter	05 mm	05 mm	MR		



N-28

7.	Automatic fire data si					
	Automatic fire detection and alarming system. (As per clause 7.31 of UBBL 2016) • Type of detector (CO type) Required Provided No.					
	Location of Main Panel	Required	Provided	MR		
		Ground floor	Provided	MR		
	Location of Repeater Panel Alternation	N/A	N/A	N/A		
	Alternate source of power	Required	Provided	MR		
8.	Hooters' Location MOEFA	Each floor	Provided	MR		
9.	10 CONTROL (10 CON	Required	Provided	MR		
10.	Public Address System	Required	Provided			
10.	Automatic Sprinkler System		- 10 Vided	MR		
	Basements	Required	Provided	M		
	Upper Floor	N/A	N/A	MR		
	Sprinkler above false ceiling	N/A	N/A	N/A		
11.	Internal Hydrants	- Walana	IVA	N/A		
	Size of riser/down- comer	N/A	N/A	N/A		
	 Number of hydrants per floor 	N/A	N/A	N/A		
10	Hose Box	N/A	N/A			
12.	Yard Hydrants	<u></u>	10/11	N/A		
	 Total number of hydrants 	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13.	Pumping Arrangements			11111		
	Ground Level			-		
	Discharge of main pump	N/A	N/A	N/A		
	Head of main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	Jockey pump out put	N/A	N/A	N/A		
	> Jockey pump head > Standby Pump out put	N/A	N/A	N/A		
	Standby Pump out putStandby Pump Head	N/A	N/A	N/A		
	➤ Auto Staring/Manual stopping	N/A	N/A	N/A		
	> Pump House Access	N/A N/A	N/A N/A	N/A		
	Terrace level	N/A N/A N/A				
	> Discharge of pump	900 LPM	900 LPM (MR		
	➤ Head of the pump	40m	40m	MR		
	> Power supply	Required	Provided	MR		
	> Auto starting of pump	Required	Provided	MR		
14.	Captive water Storage for fire fighting	rtequirea	Tiorided	IVIIC		
	Underground tank capacity	N/A	N/A	N/A		
	> Draw of connection	N/A	N/A	N/A		
	Fire service inlet	Required	Provided	MR		
	> Access to tank	N/A	N/A	N/A		
15	Overhead Tank capacity	15,000 ltrs	15,000 ltrs	MR		
	Exit Signage	Required	Provided	MR		
16.	Provision of Lifts	Required	Tiovided			
10.	> Pressurization of Lift Shaft	N/A	N/A	N/A		
		N/A	N/A	N/A		
	➤ Pressurization of lift lobby ➤ Communication in lift Car	N/A	N/A	N/A		
	Fireman's Grounding Switch	N/A	N/A	N/A		
		N/A	N/A	N/A		
	, 8	Required	Provided	MR		
17.	Standby Power Supply	Required	Tiovided	1111		
18.	Refuge Area	NT/A	N/A	N/A		
Jid	> Total area	N/A	N/A	N/A		
	> Location	N/A	MA	T4177		

SP

19.	Fire Control Room			
	> Detector system panel	N/A	N/A	N/A
	➤ Flow Switch Panel	N/A	N/A	N/A
	> PA System Panel	N/A	N/A	N/A
	➤ Battery backup	N/A	N/A	N/A
	➤ Building Floor Plans	N/A	N/A	N/A N/A
20.	GG '-1 Disks if any			

The fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety as required under the rules, the fire safety certificate issued vide letter No. F6/DFS/MS/GH/NDZ/2021/233 dated 19/07/2021, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for perusal/approval & signature please.

Signature of the Inspecting Officer Name: Santosh Kumar

Name: Santosh Kumar Designation: ADO (SJ)

Director Any Sir, Fit where is prompt for your sing plans

U plorated Ochosiss D