

C-25

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI- 110001

No.F6/DFS/MS/School/NZ/2026/916

Dated: 22 / 10 / 2026

To

The Manager,
Guru Nanak Girls Sr. Sec. School,
Singh Sabha Road, Subzi Mandi,
Delhi - 110007.

Sub: - Regarding issuance of "Fire Safety Certificate" from fire safety point of view in r/o Guru Nanak Girls Senior Secondary School, Singh Sabha Road, Subzi Mandi, Delhi - 110007.

Sir,

This has reference to your letter no. GN/P=908/26 dated 24.06.2026 received in this department through outdoor diary No. 2926 dated 24.06.2026 on the subject cited above. In this connection, this is to inform you that the school building was inspected by officer concerned from this department on 09.10.2026 in the presence of Ms. Amrita Kaur (Principal) and found that the school building is comprised of ground plus two upper floors have complied the shortcomings issued vide letter no. F6/DFS/MS/2024/School/251 dated 16.05.2024 except following which still exists.

1. Fire extinguishers provided but some found non functional.
2. Terrace level fire pump capacity of 450 LPM provided but not on auto start mode.
3. Exit signage and floor signage not provided at strategic locations in the school.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management.

Yours faithfully,


21/10/26

(Dr. S. K. Tomar)
Chief Fire Officer
Delhi Fire Service

9/c 8/2
21/10

Copy to:-

1. The Director of Education,
Govt. of NCT of Delhi, Old Secretariat, Delhi.