GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE

NEW DELHI-110 001. No. F.6/DFS/MS/School/2025/SZ

Dated: 04/12/2025

FIRE SAFETY CERTIFICATE

Certified that the Happy Child Public School located at B-12, Chander Vihar, Palam Extension, Sector- 07, Dwarka, New Delhi- 110075, is comprised of ground floor plus one upper floor, was issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/2021/166 dated 01.03.2021. The school building was re-inspected by the officer concerned of this department on dated 17.11.2025 in the presence of Sh. Jai Mohan Vats (Chairman), and found that the school management now running school at ground plus three upper floors and building have complied the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises (ground plus three upper floors) is fit for occupancy class "Educational Building" w.e.f. 04 12 2025 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on _____ o4|12|2025 at New Delhi by.

A.K. Malik) Dy. Chief Fire Officer

South Zone

Copy to: -

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

2. The Chairman, Happy Child Public School located at B-12, Chander Vihar, Palam Extension, Sector- 07, Dwarka, New Delhi- 110075.

Conditions for the validity of fire safety certificate: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building •

Happy Child Public School at B-12, Palam Extension, Sec. 07,

Dwarka, New Delhi- 110075.

2. Building comprised of

Ground plus three upper floors.

3. Type of Occupancy

Educational

4. Type of Case

Addition/Alteration (New Case)

5. Details of Previous NOC

F.6/DFS/MS/2021/166 dated 01.03.2021 (issued for G+1 UF's)

6. Fire Safety directives letter No

N/A

7. Date of inspection

17.11.2025

8. Name of Inspecting Officer

A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side

Sh. Jai Mohan Vats (Chairman)

10. Year of Construction

2014 & 2016-17

11. Applicant's letter No.

HCPS/455/2025 dated 03.10.2025

| Sr. No. | Minimum Standards on fire prevention and fire safety U/R 33 | Requirements as per BBL/UBBL - 2016 | Provided at site | Remarks MR/NMR | | | |
|------------|--|--|-------------------------------------|-------------------|--|--|--|
| 1. | Access to building | | | | | | |
| | Road widthGate widthWidth of internal road | Accessible 6.0 m 4.5 m N/A | 6.0 m Directly accessible N/A | M/R MR N/A | | | |
| 2. | Number, Width, Type & Arrangement of Exits | | | | | | |
| | a. Number of staircases | | | N4/D | | | |
| | Upper Floors | 02 No | 02 No's | M/R | | | |
| | Basements | N/A | N/A | N/A | | | |
| | b. Width of staircases | 1.50 | Provided | MR | | | |
| | Upper Floor | 1.50 m | | N/A | | | |
| | Basements | N/A | N/A | IN/A | | | |
| | c. Protection of exits | 21/4 | NI/A | N/A | | | |
| | Fire check door | N/A | N/A | N/A N/A | | | |
| | Pressurization | N/A | N/A | N/A | | | |
| | d. No. of continuous staircases to | | | NA/D | | | |
| | terrace | Required | 02 nos. Provided | M/R M/R | | | |
| | e. Width of Corridor | 1.50 m | | | | | |
| | f. Door Size | 1.0 m. | Provided | M/R | | | |
| 3. | Compartmentation | | 1000 2 - | F | | | |
| | Fire check door | N/A | N/A | N/A | | | |
| | Sealing of electrical shafts | N/A | N/A | N/A | | | |
| | Fire Rating of shaft door | N/A | N/A | N/A | | | |
| | Water Curtain | N/A | N/A | N/A | | | |
| | Fire Dampers | N/A | N/A | N/A | | | |
| 4. | Smoke Management System | | | | | | |
| | Basements | N/A | N/A | N/A | | | |
| | Upper floors | 12 ACPH | Natural ventilation | M/R | | | |
| 5. | Fire Extinguishers | | | | | | |
| - | Total numbers | 12 Nos. | Provided | M/R | | | |
| | • Types | ABC/CO ₂ type | Provided | M/R | | | |
| | IS marking | ISI marked | Provided | M/R | | | |
| | First-Aid Hose Reels | | | | | | |
| - 6 | Total numbers on each floor | 01 nos. | Provided | M/R | | | |
| | Length of hose reel hose | 30 M | Provided | M/R | | | |
| | | 5 mm | Provided | M/R | | | |
| | Nozzle diameter | | Trovided | | | | |

MIM

| 7. | Automatic fire detection and alarming system | | | |
|------|--|-------------|------------|-----------|
| 1705 | | | N/A | N/A |
| | Type of detectors | N/A N/A | N/A | N/A |
| | Location of Main Panel | N/A N/A | N/A | N/A |
| ** | Location of Repeater Panel | N/A N/A | N/A | N/A |
| | Alternate source of power | N/A | N/A | N/A |
| | Hooters' Location | N/A | Provided | N/A |
| 8. | MOEFA | N/A | Provided | N/A |
| 9. | Public Address System | 1.7.6 | | |
| 10. | Automatic Sprinkler System | 21/4 | N/A | N/A |
| | Basement | N/A N/A | N/A | N/A |
| | Ground Floor Sprinkler above false ceiling | N/A | N/A | N/A |
| | | | | |
| 11. | Internal Hydrants | NIA | N/A | N/A |
| | Size of riser/down-comer | N/A N/A | N/A | N/A |
| | Number of hydrants per floor Hose Box | N/A | N/A | N/A |
| 10 | Established and St. | | | |
| 12. | Yard Hydrants | 21/4 | N/A | N/A |
| | Total number of hydrants | N/A N/A | N/A | N/A |
| | Hose Box | IVA | | |
| 13. | Pumping Arrangements | | | |
| | Ground Level | | N/A | N/A |
| | Discharge of main Pump | N/A | N/A | N/A |
| ň | ➤ Head of Main pump | N/A | N/A | N/A |
| | Number of main pumps | N/A | N/A | N/A |
| | Jockey Pump out put Jockey pump head | N/A | N/A N/A | N/A |
| | > Standby Pump out put | N/A | N/A | N/A |
| | Standby Pump Head | N/A | N/A | N/A |
| | Auto Starting/Manual Stopping | N/A | N/A | N/A |
| | | N/A N/A | N/A | N/A |
| | Pump House Access Terrace level | N/A | IVA | 137.63 |
| | Terrace level Discharge of pump | 450 LPM | 450 LPM | MR |
| | Head of the pump | 40 mtr | 40 mtr | MR |
| | Power Supply | Required | Provided | MR |
| | ➤ Auto Starting of pump | Required | Provided | MR |
| 4. | Captive Water Storage for fire fighting | | | |
| | Underground tank capacity | N/A | N/A | N/A |
| | Praw-off connection | N/A | N/A | N/A |
| | Fire service inlet | N/A | N/A | N/A |
| | ➤ Access to tank | N/A | N/A | N/A |
| | Overhead Tank capacity | 10,000 ltrs | Provided | MR |
| | Exit Signage. | Required | Provided | MR |
| | Provision of Lifts. No Lift | | | |
| | - 1 1 0110 01 0 | N/A | N/A | N/A |
| | 5 1 2 01 01 11 | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| - 1 | | | | N/A |
| 1 | Fireman's Grounding Switch | N/A | N/A | 1 1 / / 1 |

| | A Company of the Comp | 4 | | |
|-----|--|----------|----------|-----|
| 17. | Standby power supply | Required | Provided | MR |
| 18. | Refuge Area. | required | Tiovided | |
| | - Total Area | | | |
| | - Location | N/A | N/A | N/A |
| 19. | Fire Control Room | N/A | N/A | N/A |
| | Detector System Panel | N/A | N/A | N/A |
| | Detector System Panel | N/A | N/A | N/A |
| | Flow Switch Panel | N/A | N/A | N/A |
| | PA System Panel | N/A | N/A | N/A |
| | Battery backup | N/A | N/A | N/A |
| | Building Floor Plans | N/A | N/A | N/A |
| 20. | Special Fire Protection System for Protection of special Risks, if any: | N/A | N/A | N/A |

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The shortcomings was issued by this department vide letter No. F.6/DFS/MS/SZ/2024/405 dated 08.07.20245 (placed at C- 20) have been rectified.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the Fire Safety Certificate issued vide letter No. F.6/DFS/MS/2021/166 dated 01.03.2021 is recommended to be renewed under rule 37, of the Delhi Fire Service Rules, 2010.

Signature of the Inspecting

Name: - R.K. Yadav Designation: - ADO (SRD)

60

RAJINDER ATWAL

A.K. MALIK

Psincipal Director

Do - CFS

A C

28/11/25

Ago/ Durk

POD