

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS : DELHI FIRE SERVICE, NEW DELHI - 110001

No: F6/DFS/MS/GH/NDZ/2025/539

Dated: '07 /w/2025

Certified that the M/s Hare Rama Guest House located at T-416, T-298, Main Bazar, Pahar Ganj, New Delhi - 110055, comprised of Ground + 04 upper floors: Ground floor - (reception + 03 guest rooms + 03 offices), 1st floor - (14 guest rooms + 01 office), 2nd floor - (16 guest rooms), 3rd floor - (13 guest rooms + 01 store room) & 4th floor - (not in use). FSC was granted by this department vide letter no. F6/DFS/MS/GH/NDZ/2022/329 dated 05.07.2022 for total 46 guest rooms upto 3<sup>rd</sup> floor. The building/premises was re-inspected by officer concerned of this department on 22.10.2025 in presence of Mohd. Galib (Manager) and found that the building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. The owner has submitted an affidavit on 30.10.2025 stating not to use any floor above third floor for any purpose. Accordingly, the premises is fit for occupancy class "Residential" (Sub Division-A-1), Ground floor - (03 guest rooms), 1st floor - (14 guest rooms), 2nd floor - (16 guest rooms), 3rd floor - (13 guest rooms) for total 46 guest rooms upto 3rd floor only, with effect from 37 or sooner cancelled under rule 40 and subject to conditions under rule 38 of Delhi Fire service 

(Dr. S. K. Tomar) Dy. Chief Fire Officer Delhi Fire Service

## Copy to:-

- 1. The Commissioner, Municipal Corporation of Delhi, Dr. SPM Civic Centre, New Delhi.w.r.to ID No. 2025101314161 dated 14.10.2025.
- 2. The Licensee, M/s Hare Rama Guest House at T-416, T-298, Main Bazar, PaharGani, New Delhi -110055.

## Conditions for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 8. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.
- 9. The occupancy of above 3<sup>rd</sup> floor not allowed as per clause 7.31 in UBBL-2016.

1 2 3 4 5 6 7 8 9	Ty Ty De	pe of occupancy pe of case tails of previous FSC	416, T-298, M Delhi - 55.  (Ground + 04 up Ground floor - 03 offices)  1 <sup>st</sup> floor - (14 gu 2 <sup>nd</sup> floor - (16 gu 3 <sup>rd</sup> floor - (13 gu 4 <sup>th</sup> floor - (not 30.10.2025)  Residential, Sub Renewal F6/DFS/MS/GH/	(reception + 03 g est rooms + office) test rooms) est rooms + 01 stor in use as per aff	r Ganj, Ne uest rooms re room) fidavit dated		
3 4 5 6 7 8	Ty Ty De Fin	pe of occupancy pe of case tails of previous FSC	Ground floor - 03 offices)  1st floor - (14 gud  2nd floor - (16 gud  3rd floor - (13 gud  4th floor - (not  30.10.2025)  Residential, Sub the series of the	(reception + 03 g est rooms + office) lest rooms) est rooms + 01 stor in use as per afficient	re room) fidavit dated		
4 5 6 7 8	Ty Ty De Fin	pe of occupancy pe of case tails of previous FSC	03 offices)  1st floor - (14 gue  2nd floor - (16 gue  3rd floor - (13 gue  4th floor - (not  30.10.2025)  Residential, Sub  Renewal  F6/DFS/MS/GH/	est rooms + office) est rooms) est rooms + 01 stor in use as per aff	re room) fidavit dated		
4 5 6 7 8	Ty De Fir	pe of case tails of previous FSC	1 <sup>st</sup> floor - (14 gue 2 <sup>nd</sup> floor - (16 gue 3 <sup>rd</sup> floor - (13 gue 4 <sup>th</sup> floor - (not 30.10.2025) Residential, Sub Renewal F6/DFS/MS/GH/	est rooms) est rooms + 01 stor in use as per aff Division-A-1	re room) fidavit dated		
4 5 6 7 8	Ty De Fir	pe of case tails of previous FSC	1 <sup>st</sup> floor - (14 gue 2 <sup>nd</sup> floor - (16 gue 3 <sup>rd</sup> floor - (13 gue 4 <sup>th</sup> floor - (not 30.10.2025) Residential, Sub Renewal F6/DFS/MS/GH/	est rooms) est rooms + 01 stor in use as per aff Division-A-1	re room) fidavit dated		
4 5 6 7 8	Ty De Fir	pe of case tails of previous FSC	2 <sup>nd</sup> floor - (16 gu 3 <sup>rd</sup> floor - (13 gu 4 <sup>th</sup> floor - (not 30.10.2025) Residential, Sub Renewal F6/DFS/MS/GH/	est rooms) est rooms + 01 stor in use as per aff Division-A-1	re room) fidavit dated		
4 5 6 7 8	Ty De Fir	pe of case tails of previous FSC	3 <sup>rd</sup> floor - (13 gu 4 <sup>th</sup> floor - (not 30.10.2025) Residential, Sub Renewal F6/DFS/MS/GH/	est rooms + 01 stor in use as per aff Division-A-1	fidavit dated		
4 5 6 7 8	Ty De Fir	pe of case tails of previous FSC	30.10.2025)  Residential, Sub  Renewal  F6/DFS/MS/GH/	Division-A-1			
4 5 6 7 8	Ty De Fir	pe of case tails of previous FSC	Residential, Sub Renewal F6/DFS/MS/GH/				
4 5 6 7 8	Ty De Fir	pe of case tails of previous FSC	Renewal F6/DFS/MS/GH/				
5 6 7 8	De Fir Da	tails of previous FSC	F6/DFS/MS/GH/	NDZ/2022/329 dat			
6 7 8	Fir Da	- 1 91 n		NDZ/2022/329 dat			
7 8	Da	e safety direction letter no.	05 07 2022	The second secon	ed		
7 8	Da	e safety direction letter no.	05.07.2022	05.07.2022			
8	Da		Fire safety direction letter no. Nil				
	Na	te of inspection	22.10.2025	22.10.2025			
9	-	me of the inspecting officers	Suman Kumar, A	Suman Kumar, ADO (SPM)			
	Name of the designation of officer		er Mohd. Galib (Ma	Mohd. Galib (Manager)			
	from the building side		* T	4			
10	Year of construction 1990						
11	Ap	plicant's letter no.	MCD Portal	application	ID No		
			20252025101314	161 dated 14.10.20	)25		
	Minimum Standards on fire		Requirements/	Provided at	Remar		
	Prevention and fire safety		Existing fire	Site	s MR/		
L	req	uirements U/R 33	safety		NMR		
1	A	ess To Building:	arrangements				
		d width	NA	09 m	NIA		
	a war	e width	NA NA	NA NA	NA NA		
		th of internal road	NA NA	NA NA	NA		
_		nber, Width, Type and Arra		144	11121		
	A	Number of staircases					
		a Upper floor	01 no.	01 no.	MR		
		b Basement	NA	NA	NA		
- 1	В	Width of staircases					
		a Upper floor	0.80 m	1.26 m	MR		
	_	b Basement	NA	NA	NA		
1	C	Protection of exits		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	22.55-25		
	ŀ	a Fire check door b Pressurization	Required	Provided	MR		
1	D	No. of continuous staircases	NA NA	NA NA	NA NA		
150		to terrace	IVA .	INA	NA		
1	E	Width of corridor	NA	NA	NA		
	F	Door size	1.0 m	1.0 m	MR		
	Compartmentation:						
		Fire check door	NA L	NA	NA		
		Sealing of electrical shafts	NA	NA	NA		
		Fire rating of shaft door	NA	NA	NA		
		Water curtain	NA	NA	NA		
- 5	Smo	Fire dampers ke Management System:	NA	NA	NA		
	A I	pper floors	Danie	In	1-		
		asements	Required NA	Exhaust Fans NA	MR NA		

5.	Fi	re Extinguisher:					
	A		10 nos.	10 nos.	MR		
	В	Types	ABC& Co2	ABC& Co2	MR		
	C	ISI marking	Required	Provided	MR		
6	First-Aid-Hose Reels:						
	A	Total numbers at each floor	01 no.	01 no.	MR		
	В	Length of hose reel hose	30 mtr.	30 mtr.	MR		
	C		05 mm	05 mm	MR		
7	Automatic Fire Detection And Alarming System:						
	A	Type of detectors	Required	Provided	MR		
	В	Location of main panel	Required	Provided	MR		
	C	Location of repeater panel	NA	NA	NA		
	D	Alternate source of power	Required	Provided	MR		
	E	Hooters Location	Required	Provided	MR		
8	M	OEFA:	Required	Provided	MR		
9	_	blic Address System:	Required	Provided	MR		
10	Au	itomatic Sprinkler System:	111				
	A	Basement	NA	NA	NA		
	В	Upper floor	NA	NA	NA		
	C	Sprinkler above false ceiling	NA	NA	NA		
11	Int	ternal Hydrants:					
	A	size of riser/down-comer	NA	NA	NA		
	В	Number of hydrants per floor	NA	NA	NA		
	C	Hose box	NA -	NA	NA		
12	Ya	rd Hydrants:	10	, a d			
	A	Total number of hydrants	NA	NA	NA		
	В	Hose box	NA	NA	NA		
13	Pur	mping Arrangements:					
	A	Ground level					
	a)	Discharge of main pump	NA	NA	NA		
	b)	Head of main pump	NA	NA	NA		
	c)	Number of main pumps	NA	NA	NA		
	d)	Jockey pump out put	NA	NA	NA		
	e)	Jockey pump head	NA	NA	NA		
	f)	Standby pump out put	NA	NA	NA		
Ì	g)	Standby pump head	NA	NA	NA		
İ	h)	Auto starting /manual	NA .	NA	NA		
		stopping					
Ī	i	Pump House Access	NA	NA	NA		
	В	Terrace level		1222022	1		
r	a)	Discharge of pump	225 LPM	225 LPM	MR		
-	b)	Head of the pump	30 m	30 m	MR		
-	c)	Power supply	Required	Provided	MR		
-	d)	Auto starting of pump	Required	Provided	MR		

14	Ci	Underground tank capacity	NA	NA	100
	A	Underground tank oup as y	NA	NA	NA NA
	B	Draw-off connection	NA	NA	NA NA
11 - 27	C	Fire service inlet	NA	NA	NA
	D	- to tank	2500 ltrs.	2500 ltrs.	MR
	10	Overhead tank capacity	Required	Provided	MR
_	-	T			
15	D	it Signage: ovision of Lifts:	NA	NA	NA
16		ovision of Litts.  Pressurization of lift shaft	NA	NA	NA
	A	Pressurization of lift lobby Pressurization in lift car	NA	NA	NA
	B	Pressurization of Intro- Communication in lift car	NA	NA	NA
	C	Communication in the Firemen's grounding switch	NA NA	NA	NA
	D	Firemen s g.	Required	Provided	MR
	E	Lift signage andby Power Supply:	Required		
7	Sta	ndby Power Supr		NA	NA
7_	Do	fuge Area:	NA	NA NA	NA
8		Total area	NA	IVA	
	A	T - action			NA
	B	And Room	NA	NA	NA
9	Fir	e Control Room:  Detector system panel  ich panel	NA NA	NA	NA
	A	- testor system		NA	NA
	В	Elaw switch part	NA	NA	NA
	C	Do cystem paner	NA	NA	NA NA
	ň	Battery backup	NA	NA	147.
	D Battery backup NA  E Building floor plans  Special Fire Protection Systems For Protection  Special Risks, If Any:				

The fire protection systems provided in the building were tested, checked at random

Shortcomings communicated vide letter no. F6/DFS/MS/GH/NDZ/311 dated and found functional at the time of inspection.

Keeping in view of the deemed compliance of minimum standard of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter No. F6/DFS/MS/GH/NDZ/2022/329 dated 05.07.2022 is recommended to be renewed upto 3rd floor only, under Rule 35 of the Delhi Fire Service Rules 2010.

Accordingly, DFA is put for approval and signature please.

Signature of the Inspecting Officer

Suman Kumar Name ADO (SPM) Designation

Principal Direct