

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/Industrial/SZ/2025/370

Dated: 07/1) /2025

## **FIRE SAFETY CERTIFICATE**

Certified that the M/s Haldiram Marketing Pvt. Ltd. located at Plot No. B-1/F-10, M.C.I.E, Main Mathura Road, Delhi-110044, building comprised of Basement + Ground + 02 upper floors owned/occupied by M/s Haldiram Marketing Pvt. Ltd. was earlier issued FSC from this department vide letter No. F6/DFS/MS/Industrial/SZ/2022/262 dated 15/09/2022. Now, the building was re-inspected by the officer concerned of this department on 13/10/2025 in presence of Mr. Asfaq Khan and found that the premises has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010 and that the building is fit for occupancy class 'Industrial Building' (Group – G) with effect from 07 / 11 /2025 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010.

Issued on 07 11 200 at New Delhi by

Dy. Chief Fire Officer

Delhi Fire Service

Copy to: -

- 1. The Executive Engineer (Building), South DMC, Jal Vihar, Lajpat Nagar, New Delhi-24.
- 2. The Manager, M/s Haldiram Marketing Pvt. Ltd., Plot No. B-1/F-10, M.C.I.E, Main Mathura Road, Delhi-110044.

## Conditions for the validity of Fire Safety Certificate

- 1. The owner occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipment's and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the firefighting equipment's shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- 6. Basement shall be used as per NBC/UBBL.
- This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.

		IN	いして ISPECTION REPO	RT	1919 F		
1	Na	ame & address of the building		onto 1			
•	Building is comprised of			M/s Haldiram Marketing Pvt. Ltd. located at Plot 1			
				B-1/F-10, M.C.I.E, Main Mathura Road, Del			
2				110044.			
3		pe of occupancy		Basement + Ground + 02 upper floors			
<u> </u>		pe of case		Industrial, Group – G			
200		-	TELES MINES.	Renewal			
5	Details of previous FSC			F6/DFS/MS/Industrial/SZ/2022/262 dated			
5	E:	ro pofoto dinastina lau		15/09/2022			
,	-	re safety directives letter no.	The second of th	F6/DFS/MS/2001/642 dated 18/04/2001			
	_	ate of inspection		13/10/2025			
		ame of the inspecting officers		h Meena, A.D.O / Math	ura Road		
)		ame of the designation of offi	cer Mr. Asfag Khar	Mr. Asfag Khan			
10		om the building side ear of construction	1000	project 8,			
	-		The state of the s	1998			
1		oplicant's letter no.		No.6340 dated 23/09/20			
. No		inimum standard of fire	Requirements	Provided at site	Remarks		
	33	evention and fire safety U/F	2.31.294		MR/NMF		
	1.00	cess to Building:					
				a agent phres	) m		
	A	Road width	6.0 mtrs.	Provided	MR		
	B	Gate width	3.3 mtrs	Provided	MR (Old case)		
	C	Width of internal road	N/A	N/A	N/A		
2.	Number, Width, Type and Arrangement of Exits:						
	A Number of staircases						
		a Upper floor	02 nos.	02 nos.	MR		
	-	Basement	02 nos.	02 nos.			
	В	Width of staircases	11 mgCE	U3 nos.	MR		
		a Upper floor	1.50 mtr. each	1.5 to 2.70m &	MR		
	, ix			1.90m	TALK.		
		Basement	1.50 mtr. each	1.8, 1.60m & 1.30m	MR		
	C	Protection of exits	17 17 11	Land Stanie at a land			
		a Fire check door	Required	Provided	MR		
	D	b Pressurization  No. of continuous	N/A	N/A	N/A		
	וש	staircases to terrace	02 Nos.	Provided	MR		
	E	Width of corridor	N/A	N/A	27/4		
à	F	Door size	1.5 m	The state of the s	N/A		
3.	Cor	mpartmentation:	1100 1200	1.5 m(Final exit)	MR		
	A	Fire check door	Domina 1				
ŀ	В	Sealing of electrical	Required N/A	Provided	MR		
The state of the s		shafts	IN/A	N/A	N/A		
	C	Fire rating of shaft door	N/A	N/A			
	D	Water curtain	N/A	N/A N/A	N/A		
	-	Fire dampers	N/A	N/A	N/A		
	E						
1 n	Smo	oke Management System:		IVA	N/A		
-	Smo	oke Management System:  Basement	30				
	Smo	Basement System:	Mechanical/Natural Mechanical/Natural	Exhaust Fan Exhaust Fan	N/A MR		

5.	Fir	e Extinguisher:	NI:					
SI	A	Total numbers	14 nos.	Provided	MR			
	B	Types	CO <sub>2</sub> & ABC	CO <sub>2</sub> & ABC	MR			
	C	ISI marking	ISI Marked	ISI Marked	MR			
6	Fir	st-Aid-Hose Reel:		1711				
	A	Total numbers of each floor	02 nos.	Provided	MR			
	В	Length of hose reel hose	30 mtrs.	Provided	MR			
	C	Nozzle diameter	05 mm	Provided	MR			
7	Au	tomatic Fire Detection and Alar	Tiovided	IVIK				
	A	Type of detectors	Heat / Smoke	Provided	MR			
	В	Location of main panel	At. ground floor	Provided	MR			
	C	Location of repeater panel	N/A	N/A	N/A			
	D	Alternate source of power	Required	Provided	MR			
	E	Hooters Location	Required	Provided	MR			
8	M	OEFA:	Required	Provided	_			
9		blic Address System:	Required	Provided	MR			
10		tomatic Sprinkler System:		Daptvott	MR			
	A	Basement	N/A	Provided	NT/A			
	В	Upper floor	Required	Provided	N/A			
	C	Sprinkler above false ceiling	Required	Williams XVIII	MR			
11	In	ternal Hydrants:	Required	Provided	MR			
	A	Size of riser/down-comer	100 mm	B (14)				
	В	Number of hydrants per floor	02 no	Provided	MR			
	C	Hose box	02 no	Provided	MR			
12	Ya	ord Hydrants:	V2 NO	Provided	MR			
	A	Total number of hydrants	04 nos.	10 20 11				
	В	Hose box		Provided	MR			
13	Pu	mping Arrangements:	04 nos.	Provided	MR			
1	(	Ground level						
	A	Discharge of main pump	2200 7 72 6					
	В	Head of main pump	2280 LPM	2280 LPM	MR			
	C	Number of main pumps	70 m	70 m	MR			
	D	Jockey pump out put	01 no	01 no	MR			
	E	Jockey pump head	180 LPM	180 LPM	MR			
	F	Standby pump out put	70 m	70 m	MR			
	G	Standby pump head	2280 LPM	2280 LPM	MR			
	H	Auto starting /manual	70 m	70 m	MR			
	_	stopping	Required	Provided	MR			
2	I	Pump house access	Required	Dravid - 1	1 75			
2	84	rrace Level	17	Provided	MR			
	A	Discharge of pump each block	900 LPM	900 LPM	) m			
	B	Head of the pump	35 m		MR			
	-	Power supply	Required	35 m Provided	MR			
	D	Auto starting of pump	Required	Provided	MR			
14	Captive Water Storage for Fire Fighting:							
	A	Underground tank capacity	71	p-free n				
	В	Draw-off connection	1,00000 ltrs	Provided	MR			
	C		Required	Provided	MR			
		Fire service inlet	Required	Provided	MR			
	D.	Access to tank	Required					
	E	Overhead tank capacity		Provided	MR			
5	Exi	t Signage:	20,000 liters	Provided	MR			
			Required	Provided	MR			

16	Provision of Lifts:				
1	A	Pressurization of lift shaft	N/A	N/A	N/A
ŀ	В	Pressurization of lift lobby	N/A	N/A	N/A
ŀ	Č	Communication in lift car	N/A	N/A	N/A
and the same	D		N/A	N/A	N/A
	-	Firemen's grounding switch	N/A	N/A	N/A
17	E	Lift signage and by Power Supply:	Required	Provided (125KVA)	MR
18	Refuge Area:				
ī.o	A	Total area	N/A	N/A	N/A N/A
	B	Location	N/A	N/A	IN/ZX
19	Fire Control Room:				MR
- Colores	A	Detector system panel	Required	Provided	MR
	В	Flow switch panel	Required	Provided	N/A
	-	PA system panel	N/A	N/A	N/A
	C	Battery backup	N/A	N/A	N/A
	D		N/A	N/A	N/A
20	E Building floor plans  Special Fire Protection systems for protection of special Risks, if any:		N/A	N/A	IV/A

The fire protection system was randomly checked and tested and was found functional at the time of inspection. The shortcomings issued by this department vide letter no. F6/DFS/MS/WZ/2025/362 dated 03/09/2025 have been rectified.

Keeping In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the rules of the FSC issued vide letter no. F6/DFS/MS/Industrial/SZ/2022/262 dated 15/09/2022, renewal under Rule 3 of the Delhi Fire Service rules 2010, is recommended.

Signature of the Inspecting Officer
Name Yashwant Singh Meena
Designation: ADO/Mathura Road

D.O/SD

14/192

Dres (2)

L. K. MALIK

fing Outr

To to

my. (50 (SZ)

Dilais \_