



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No.F.6/DFS/MS/EH/2025/SZ/14

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of Hikki (A Unit of Drama Restaurant Pvt. Ltd) located at Unit nos. G3RA, G3RB, G4R G5R, Ground Floor, Eldico Center, Malviya Nagar, New Delhi 110017 comprised of 03 Tiers Basement, Ground plus Three Upper Floors owner/occupied by Hikki (A Unit of Drama Restaurant Pvt. Ltd) have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on presence 26/12/2024 in the Mr. Gagandeep (Project Manager) and that the premise is fit for occupancy class Group-D Assembly (Restaurant) at Ground floor only and validity upto 31/03/2027 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on <u>68 / of</u> /2025 at New Delhi by

DELHI FIRE SERVICE

Copy to: -

- 1. The Addl. Commissioner of Police Lic/Branch, 1st Floor PS Defence Colony, New Delhi 110049.
- M/s Hikki (A Unit of Drama Restaurant Pvt. Ltd) located at Unit nos. G3RA, G3RB, G4R G5R, Ground Floor, Eldico Center, Malviya Nagar, New Delhi 110017

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.

3. The basement shall be used as per the provisions of BBL /NBC Part- IV.

- 4. All the staff members must know the correct method of operation of fire fighting system.
- 5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the MHA portal along with a copy of this Certificate, six months prior to its expiry".



	- un	INCRECEN	ON DEBORE					
1	Name	& Address of the Building	ON REPORT	U-it -C D	. D . T.D			
100	, vain	& Address of the Building	M/s Hikki (A Unit of Drama Restaurant Pvt. Ltd) G3RA, G3RB, G4R G5R, Ground Floor, Eldeco					
2	Type	of Occupancy	Centre, Malviya Nagar, New Delhi 110017 Restaurant at Ground Floor only					
3	Build	ing Comprised of	03 Basement, Ground plus Three Upper Floor					
4		of Case	New Case					
5		s of Previous NOC	Nil					
6	Fire S	afety Directives Letter No	F.6/MS/DFS/BP/2022/58 dated 18-02-2022					
7		of Inspection	26/12/2024					
8		of the Inspecting Officers	ADO (RN)					
9	Name & Designation of Officers		Mr. Gagandeep (Project Manager)					
10	from the building side Year of construction		2021					
10	Year	or construction	2021					
11	Appli	cant letter online ID.	MHA Portal ID No- 2024113017487 dated 16/12/202					
S. No.			Directive	Provided at Site	Remarks			
		ire Safety U/R 33	Requirements	DC (DDC (350 /351 4 /00	MR/NMR			
1	Access to Building.		Building FSC F6/DFS/MS/Mixed/2023/SZ/68 dated 08/02/2023					
	Road width		18 mtr	Provided Provided	MR			
	•	Gate width	6 mtr	Provided	MR			
×	•	Width of internal road	6 mtr	Provided	MR			
2		ber, width, type & arrangement of ex						
	a) Number of Staircase		Provided and maintained by MRTS Station					
12	>	Upper floors.	NA	Provided	NA			
	3	Post State S		Provided	NA			
	>	Basement floor.	NA					
	b) Width of Staircase		Ground floor only					
	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	Upper floors	NA	NA	NA			
	= = 1		NA	NA	NA			
	>		NA.		NA			
	c) Pi	otection of exits	100					
	. >	Fire check door	Required	Provided	MR			
	>		Required	Provided	MR			
	d) No	o. of continuous staircase to terrace	04 Nos	Provided	MR			
	e) Width of corridor		Required	Provided	MR			
11		or size	1.50 mtr each	1.50 mtr each	MR			
3	Compartmentation.			17 (2000)				
_			Provided and maintained by MRTS Station					
	•	Fire check door.	Required	Provided	MR			
- 1	•	Sealing of electrical shafts.	Required	Provided	MR			
	•	Fire rating of shaft door.	Required	Provided	MR			
	•	Water curtain	N/A	N/A	N/A			
		Fire dampers.	N/A	N/A	N/A			
4	Smok	Management system.	Provided and maintained by MRTS Station					
			The second secon					
	•	Basement	N/A	N/A	N/A			
	•	Upper floors	12 ACPH	Exhaust fan provided				
5	Fire E	xtinguishers.		7 - 16.W				
	•	Total numbers		05 Nos	MD			
	•	Types	ISI marked	W. CO ₂ , DCP & CO ₂	MR			
		ISI Marking	101 Harkou		MR			
6	-	Aid Hose Reels.	Duovidad	Provided	MR			
	ALOSE RECES.		Provided and maintained by MRTS Station					
	 Total numbers on each floor. Length of hose-reel hose. 		Hose Reel	Near restaurant	MR			
				30m				
	•	Nozzle Diameter			MR			
7	Automa	atic fire detection & alarming system.	E S	5mm	MR			
			Provided and maintained by MRTS Station					
	•	Type of detectors	Required	Provided				
	•	Location of Main Panel	Required	Provided	MR			
	•	Location of Repeater Panel	N/A		MR			
	•	Alternate source of power	Required	N/A Provided	N/A			
		Hooter's location	The second secon	Provided	MR			
T		ovanon	All floor	Provided	MR			

		1/2	-	₹.		
8	MOEFA	Required	Provided	N		
9	Public Address System			-		
10	Automatic Sprinkler System	Required Provided M Provided and maintained by MRTS Stati				
	Basement					
	Upper floors	Required	Provided	M		
	 Sprinkler above false ceiling 	N/A		M		
11	Internal Hydrants.	140.00	N/A nd maintained by MR	N/		
	Size of Riser/Down-comer	150 mm	Provided Provided			
	 Number of Hydrant per floor 	06 Nos	A 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	M		
	Hose box.	06 Nos	Provided	M		
12	Yard Hydrants.	Provided and maintained by MRTS Station				
	Total number of hydrants.	Required 07 Nos Provided				
	Hose box.	100000000000000000000000000000000000000		M		
13	Pumping arrangements.	Required	07 Nos Provided	MI		
	Ground Level	Provided and maintained by MRTS Station				
	Discharge of main pump.	2850 LPM	Provided Provided			
	Head of main pump.	70m	Provided	MI		
	Number of main pumps.	Two	Provided	MF		
	> Jockey Pump output.	180 LPM	Provided	MF		
	Jockey Pump head.	70m	Provided	MF		
	Standby Pump output.Standby Pump head.	2850 LPM	Provided	MR		
	Auto Starting/Manual Stopping.	70m	Provided	MR		
	Pump house access.	Required	Provided	MR		
	Terrace Level	Required	Provided	MR		
	Discharge of pump.	N/A	N/A	NI/A		
	➤ Head of pump.	N/A	N/A	N/A		
	➤ Power supply.	N/A	N/A	N/A		
	Auto starting of pump.	N/A	N/A	N/A		
14	Captive water storage for fire fighting.	Provided and	l maintained by MRT:	S Station		
	 Underground tank capacity. Draw-off connection. 	2,00,000 Ltrs	Provided	MR		
	Fire Service Inlet.	Required	Provided	MR		
	Access to tank.	Required Required	Provided	MR		
	Overhead tank capacity.	30,000 Ltr	Provided Provided	MR		
15	Exit Signage.	Required	Provided	MR MR		
16	Provision of Lifts.		maintained by MRTS			
	Pressurization of lift shaft.	Required	Provided			
	Pressurization of lift lobby.	Required	Provided	MR		
	Communication in lift car.	Required	Provided	MR		
	Fireman's switch.	Required	Provided	MR		
	Lift signage.	Required	Provided	MR MR		
17	Standby Power Supply	Required	Provided	19709900000		
18	Refuge Area	required	Hovided	MR		
	Total area	N/A	N/A	N/A		
	• Location	N/A	N/A	N/A		
19	Fire Control Room.	- CONDING TO	maintained by MRTS			
+	Detector system panel.	Required	Provided) m		
	Flow switch panel.	Required	Provided	MR MR		
		Required	Provided	MR		
	PA system panel. Pattern bealers.	Required	Provided	MR		
	 Battery backup. Building floor plan. 	Required	Provided	MR		
20	Special Fire Protection System for the	100 3030				
1/0767	Protection of special Risk, if any.	CO ₂ type fire exti for HT / LT par	nguishers provided	MR		



The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Signature of the Inspecting Officer

Name :-C.L. Meena Designation:- ADO/RN

Mukesh Verma/(DO/South)

As approved, F.T. letter is het up for your signature Please.

Directo