

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F6/DFS/MS/2025/SZ/EH/ 33 |

Dated: 22 09 2015

FIRE SAFETY CERTIFICATE

Certified that M/s Hunger Pangs Pvt. Ltd. Burma Burma Restaurant and Tea Room located at Shop No 311, 312 & 314, 2nd floor, DLF Promenade Plot No.3, Nelson Mandela Marg, Vasant Kunj, New Delhi-110070, comprised of Two tier Basement, Ground plus Two upper Floors and Restaurant is running at 2nd floor only has already been issued FSC by this department vide letter No. F6/DFS/MS/EH/2022/SZ/182 dated 17.06.2022. The restaurant premise was re-inspected by the officer concerned of this department on 04.09.2025 in the presence of Mr. Sujit Sameer (Electrical Engineer) and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class D "Assembly Building" with effect from 32 of 2010 and that the for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 29 09 2025 at New Delhi by

(Virendra Singh) Chief Fire Officer Delhi Fire Service

Copy to: -

- 1. The DHO, (South Zone), SDMC, Public Health Department, Aurobindo Marg, Green Park, New Delhi-110016.
- MCD Portal ID-2025071711493 dated 26.08.25.

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

1			INSP	ECTION REPORT				
F 1	. Name & ad	dress of the building	Roon Prom	Hunger Pangs Pvt. Ltd. In located at Shop No 3 enade Plot No.3, Nelson 1-110070.	11 312 & 314	2 11001, DI		
2.	Type of Oc	cupancy		mbly Building "Group-D"	Restaurant			
3.			Two	tier Basement, Ground plus	Two Upper Floo	or		
4.			Renev	wal (Restaurant is runnin	g at 2nd floor on	ly)		
	Details of P		F.6/D	Renewal (Restaurant is running at 2 nd floor only) F.6/DFS/MS/EH/2022/SZ/182 dated 17.06.2022.				
6.	Fire Safety	directives letter No		UBBL-2016 04.09.2025				
	Date of inst		04.09					
_	. Name of Inspecting Officer		A.K.Sharma (ADO Rohini)					
9.	Name and of From the bu	lesignation of officers ailding side	Mr. St	ujit Samee)(Electrical Engi	neer)			
1(). Year of Cor	nstruction	2005		1000	0.25		
1	l. Applicant's	letter No.	Online	application No.20250717	11493 dated 26.0	Remarks		
S.	Minimum	Standards on fire preve		UBBL/NBC	Provided at	MR/NMR		
No				Requirement	site	0.5%		
1.	Access to b	ouilding [FSC No.F.6/D	FS/MS	Requirement /Mall/2022/SZ/464 dated	19.10.2022 01 1	JEF Tromena		
	Mall			e .	T 1			
	DVVV - DVAD - DV	d width		10.1 N. 11	As Above	MR		
		Gate width		Restaurant within Mall	AS Above			
	7,000			-	1.0			
2.	Number W	idth Tyne & Arrangel	nent of	Exits (Provided & Maintain	ed by DLF Prome	enade Mall)		
4.	 Width of internal road Number, Width, Type & Arrangement o a. Number of staircases 					All the second s		
	Upper Floors			02nos.	Provided	MR		
				Restaurant within Mall	As Above	MR		
	Basements			Provided & Maintained by DLF Promenade Mall				
	b. Width of staircases			1.5m	1.5m each	MR		
	The second secon	pper Floor		Restaurant within Mall	As Above	MR		
	Basements			Provided & Maintained by DLF Promenade Mall				
	c. Protection of exits			Required	Provided	MR		
		re check door		Restaurant within Mall	As Above	MR		
		Pressurization		Restaurant within Mall	As Above	MR		
	d. No. of con	ntinuous staircases to te	rrace		As Above	MR		
	e. Width of	Corridor		Restaurant within Mall	1.5m & 2m	MR		
	f. Door Size			1.5m each	1.5m & 2m	MIC		
	Compartmentation			- 11: 14:1	A - A barra	MR		
	a) Fire o	heck door		Restaurant within Mall	As Above			
	b) Sealing of electrical shafts			Restaurant within Mall	As Above	MR		
	c) Fire Rating of shaft door			Restaurant within Mall	As Above	MR		
	d) Water		111	Restaurant within Mall	As Above	MR		
	e) Fire Dampers			Restaurant within Mall	As Above	MR		
	Smoke Management System			Provided & Maintained by DLF Promenade Mall				
57	a) Basements			Restaurant within mall	As Above	MR		
	b) Upper			Required	Mechanical ventilation	MR		
i.	Fire Extinguishers			Provided & Maintained b				
	a) Total numbers			04nos.	Provided	MR		
ı	b) Types			ABC/CO2	ABC/CO2	MR		
	b) Types							

		D 11-1 0 M-1 4			
6.	First-Aid Hose Reels	Provided & Mainta			
-	a) Total numbers on each floor	01 near to restaurant	As Above	IVIA	
	b) Length of hose reel hose	30mm	As Above	1411	
		5m	As Above	MR	
7.	c) Nozzle diameter Automatic fire detection and alarming s	ystem Provided & Mainta	ined by DLF P	romenade Mall	
·-	a) Type of detectors	Required	Tiovided	MIK	
	b) Location of Main Panel	Restaurant within mall	As Above As Above		
	c) Location of Repeater Panel	Restaurant within mall			
	d) Alternate source of power	Restaurant within mall Restaurant within mall		MR	
	e) Hooters' Location	Required	Provided	MR	
8.	MOEFA	Required	Provided	MR	
9.	Public Address System	[Provided & Mair	tained by Mall	management]	
10.	Automatic Sprinkler System	-NA-	As Above	-NA-	
	a) Basement	-NA-	As Above	-NA-	
	b) Ground & Upper Floors	V 80 (14 / 2-1)	As Above	-NA-	
	c) Sprinkler above false ceiling	-NA- [Provided & Mainta			
11.	Internal Hydrants	150	As Above	MR	
	a) Size of riser/down-comer	100mm		MR	
	b) Number of hydrants per floor	One(near to Restaurant)		MR	
	c) Hose Box	One(near to Restaurant)		100000000000000000000000000000000000000	
12.	Yard Hydrants	[Provided & Maint	As Above	MR	
12.	a) Total number of hydrants	Restaurant within mall		MR	
	b) Hose Box	Restaurant within mall	As Above		
	Pumping Arrangements	[Provided & Maintained by Mall management]			
13.	Ground Level		17001	MR	
	> Discharge of main Pump	Restaurant within mall	4500lpm 70m	MR	
	> Head of Main pump	Restaurant within mall	02nos.	MR	
	> Number of main pumps	Restaurant within mall	180lpm	MR	
	> Jockey Pump out put	Restaurant within mall	70m	MR	
	> Jockey pump head	Restaurant within mall	4500lpm	MR	
	> Standby Pump out put	Restaurant within mall	70m	MR	
	> Standby Pump Head	Restaurant within mall		MR	
	> Auto Starting/Manual Stopping	Restaurant within mall	As Above As Above	MR	
	> Pump House Access	Restaurant within mall	T. ASSESSED		
_	Terrace level	[Provided & Maintained by Mall managem		nagement	
	➤ Discharge of pump	-NA-	As Above	MR	
		-NA-	As Above	MR	
	> Head of the pump	Required	As Above	MR	
	> Power Supply	Required	As Above	MR	
	> Auto Starting of pump	[Provided & Maintained by Mall management]			
4.	Captive Water Storage for fire fighting	Restaurant within mall	4,50,000ltr	MR	
	Underground tank capacity	Restaurant within mall	As Above	MR	
	> Draw-off connection	Restaurant within mall	As Above	MR	
15.	 Fire service inlet Access to tank 	Restaurant within mall	As Above	MR	
		Restaurant within mall	30,000ltr	MR	
	Overhead Tank capacity Exit Signage.	Required	Provided	MR	
-	Provision of Lifts.	[Provided & Maintain	ed by Mall man	agement]	
6.	· · · · · · · · · · · · · · · · · · ·	-NA-	-NA-	-NA-	
1	Pressurization of Lift Shart Pressurization of Lift lobby	-NA-	-NA-	-NA-	
- 1	0) Pressurization of Entriolog				

1	c) Communication In lift Car	-NA-			
Y	d) Fireman's Grounding Switch		-NA-	-NA-	
	e) Lift Signage	-NA-	-NA-	-NA-	
17.	Standby power supply	-NA-	-NA-	-NA-	
18.		Required	Provided (DG set)	MR	
18.	Refuge Area.	[Provided & Maintained by Mall management]			
	a) Total Area	-NA-	-NA-	-NA-	
	b) Location	-NA-	-NA-	-NA-	
19.	Fire Control Room [Provided & Maintained by Mall management]				
	a) Detector System Panel	-NA-	-NA-	-NA-	
	b) Flow Switch Panel	-NA-	-NA-	-NA-	
	c) PA System Panel	-NA-	-NA-	-NA-	
	d) Battery backup	-NA-	-NA-	-NA-	
	e) Building Floor Plans	-NA-	-NA-	-NA-	
20.	Special Fire Protection System for Protection of special Risks, if any:	-NA-	-NA-	-NA-	

Accordingly, the fire protection systems provided in the building were tested/ checked

randomly and found in working condition at the time of inspection.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F.6/DFS/MS/EH/2022/SZ/182 dated 17.06.2022 is recommended for renewal of FSC under rule 37 of the Delhi Fire Service rules 2010.

> Signature of the Inspecting Officer Ajay Kumar Sharma Name Designation ADO(Rohini)

FT lette & pour up for Kind perusal and Synatur Pls

Waleeded