

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI – 110001

No. F6/DFS/MS/GH/NDZ/2025/ 536

Dated:06/1) / 2025

FIRE SAFETY CERTIFICATE

Certified that the M/s Hotel Metro Star located at 2405, Faiz Road, Karol Bagh, New Delhi-110005, comprised of Ground + 03 upper floors: Ground floor - (reception + 04 guest rooms + 01 office), 1st floor - (05 guest rooms), 2nd floor - (04 guest rooms) & 3rd floor - (02 guest rooms). FSC was granted by this department vide letter no. F.6/DFS/MS/GH/2022/NDZ/480 dated 21.10.2022 for total 15 guest rooms upto 3rd floor only. The building/premises was re-inspected by officer concerned of this department on 18.10.2025 in presence of Manager and found that the building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. The owner has submitted an affidavit on 27.10.2025 stating not to use any floor above third floor for any purpose. Accordingly, the premises is fit for occupancy of "Residential" (Sub-Division-A-1), Ground floor - (reception + 04 guest rooms + 01 office), 1st floor - (05 guest rooms), 2nd floor - (04 guest rooms) & 3rd floor - (02 guest rooms) for total 15 guest rooms upto 3rd floor only, with effect from ...06.11.1.2025.................. for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to conditions under rule 38 of Delhi Fire service Rules, 2010 subject to condition printed below.

Issued on 06 11 202 _____at New Delhi by

(Dr. S. K. Tomar)

Dy. Chief Fire Officer

Delhi Fire Service

Copy to:-

- The Commissioner, MCD, Dr. SPM Civic Centre, New Delhi 110002. w.r.to ID No. 2025032804878 dated 14.10.2025:- to kindly ensure the occupancy as detailed above & deviation, if any.
- 2. The Licensee, M/s Hotel Metro Star located at 2405, Faiz Road, Karol Bagh, New Delhi 110005.

Conditions for the validity of fire safety certificate

- All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 8. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.
- 9. The occupancy of above 3rd floor not allowed as per clause 7.31 in UBBL-2016.

1	Na	me	& address of the building		CTION REPORT M/s Hotel Metro Star located at 2405, Faiz				
2	Ru	:14	no is some 1 1 s		Bagh, New Delhi -	110005.			
2	Du	IIQ.	ng is comprised of	(Ground + 0	3 upper floors)				
				Ground floor	r - (reception + 04	guest rooms			
				01 office)	•				
	-			1 st floor - (05	guest rooms)				
				2 nd floor – (04					
				3rd floor - (02	2 guest rooms) an	affidavit give			
				by owner day	ted 27.10.2025 re	garding not t			
				use ony floor	above third floor				
3	Tv	ne	of occupancy		ab Division A-1				
4	_			F104-200 00 00 00	IO DIVISION 71				
	_		of case	Renewal	11/2022 AID 7/400	dated			
5	Details of previous FSC			21 2000-2	H/2022/NDZ/480	udicu			
		ı		21.10.2022					
6	Fir	e sa	fety direction letter no.	Nil					
7 .	Da	te c	of inspection	18.10.2025					
8			of the inspecting officers	ADO (Hqrs)	January Commence				
9				of Manager					
			from the building side						
10			of construction	2008		The state of the s			
		(C.S.W) (2	Property of the Control of the Contr	1 construction 1 construction No. 20250328					
11	Ap	pii	eant's letter no.	14.10.2025					
	550,000		~	Requirements	Provided at	Remarks			
S.No	Mi	nir	num Standards on fire	/ Existing fire	A CONTRACTOR OF THE PROPERTY O	MR/			
	Pr	eve	ntion and fire safety	safety	Dite	NMR			
	rec	luı	rements U/R 33	arrangements					
1	Access To Building:								
*			width	NA	06 m	NA			
	200		vidth	NA	NA	NA			
	337:	dth	of internal road	NA	NA	NA			
2	Nu	mh	er, Width, Type and Arra	angement of Exits	:				
L	A	IN	umber of staircases	A STATE OF THE STA	Later March				
	A		Upper floor	01 no.	01 no.	MR			
	BIA		Basement	NA	NA	NA			
	В		idth of staircases	Mal	12.4				
	D	2746	Upper floor	0.80 m (Old	1.15 to 1.20 m	MR			
		a	Oppor moor	case)					
		h	Basement	NA	NA	NA			
	C	Pı	otection of exits						
			Fire check door	NA	NA	NA			
			Pressurization	NA	NA	NA			
	D		o. of continuous staircases	01 no.	01 no.	MR			
			terrace	A					
			I' III - C - amidon	NA	NA ·	NA			
	E	V	idth of corridor		1.0 m	MR			
		V	oor size	1.0 m	1.0 III				
3	E F	V				12			
3	E F Con	V np	oor size artmentation: ire check door	NA	NA	NA			
3	E F	V np	oor size artmentation: ire check door			NA NA			
3	E F Con A B	mp:	oor size artmentation: ire check door ealing of electrical shafts	NA	NA				
3	E F Con A B	mp: F S	oor size artmentation: ire check door ealing of electrical shafts ire rating of shaft door	NA NA	NA NA	NA NA			
3	E F Cor A B C D	mp F S	poor size artmentation: ire check door ealing of electrical shafts ire rating of shaft door vater curtain	NA NA NA	NA NA NA	NA NA NA			
	E F Coo A B C D	F F V F	oor size artmentation: ire check door ealing of electrical shafts ire rating of shaft door vater curtain ire dampers	NA NA NA NA	NA NA NA NA	NA NA			
3	E F Coo A B C D	W II mps	poor size artmentation: ire check door ealing of electrical shafts ire rating of shaft door vater curtain	NA NA NA NA	NA NA NA NA	NA NA NA			

(M/s Hotel Metro Star located at 2405, Faiz Road, Karol Bagh, New Delhi - 110005)

5.	_	re Extinguisher:	10 nos.	10 nos.	MR		
	A	Total numbers	CO ₂ & ABC	CO ₂ & ABC	MR		
	В	Types	Required	Provided	MR		
	C	ISI marking	Required	Tiovided	MIK		
6	First-Aid-Hose Reels: A Total numbers of each floor 01 no. 01 no. MI						
	A	Total numbers of each floor	30 m	30 m	MR MR		
	В	Length of hose reel hose Nozzle diameter	05 mm	05 mm			
	C	ALMANA	55.05 (1.00m) (1.00m) (1.00m)	Liter entent	MR		
7	A Type of detectors (Co type) Required Provided MR						
	A	Type of detectors (Co type)	Ground floor	Provided	MR		
	B	Location of main panel Location of repeater panel	NA	NA	MR NA		
	D	Alternate source of power	Required	Provided	MR		
	E	Hooters	Required	Provided	MR		
8		DEFA:	NA	NA	NA		
9	Pul	blic Address System:	Required	Provided	MR		
10		tomatic Sprinkler System:	II II				
-Securi	A	Basement	Required	Provided	MR		
	В	Upper floor	NA	NA	NA		
	C	Sprinkler above false	NA	NA	NA		
11	Internal Hydrants:						
**	A	size of riser/down-comer	NA	NA	I NTA		
	B	Number of hydrants per	NA	NA NA	NA NA		
	-	floor	11/1	INA.	NA		
	C	Hose box	NA	NA ·	NA		
12	Yard Hydrants:						
	A	Total number of hydrants	NA	NA	NA		
	В	Hose box	NA	NA	NA		
3		ping Arrangements:		THE PERSON I	INA		
	A Ground level						
	a)	Discharge of main pump	NA	NA	1274		
ŀ	b)	Head of main pump			NA		
ŀ			NA	NA	NA		
-	c)	Number of main pumps	NA	NA	NA		
, 	d)	Jockey pump out put	NA	NA	NA		
-	e)	Jockey pump head	NA	NA	NA		
-	f)	Standby pump out put	NA	NA	NA		
	g)	Standby pump head	NA	NA	NA		
	h)	Auto starting /manual stopping	NA	NA	NA		
	i)	Pump house access	NA	NA	NA		
	В	Terrace level					
	a)	Discharge of pump	450 LPM	450 LPM	MR		
	b)	Head of the pump	30 m	30 m	MR		
	-1	Power supply	Required	Provided	MR		
Γ	c)	TOWER SUPPLY	Reduired	PIOVIDEAL	14884		

(M/s Hotel Metro Star located at 2405, Faiz Road, Karol Bagh, New Delhi - 110005)

	A	ptive Water Storage For Fire	Fighting:			
1	B	- Olider ground tank canacity	NA	NA	Tara	
- 1		Draw-off connection	NA	NA NA	NA NA	
- 1	C	Fire service inlet	NA NA	NA NA	NA	
2.11	D	Access to tank	NA	NA NA	NA	
_	E	Overhead tank capacity	2,500 ltrs.		NA NA	
15	Ex	it Signage:	Required	2,500 ltrs.	MR	
16		ovision of Lifts:	Required	Provided	MR	
	A	Pressurization of lift shaft	T	Α	T Selve	
	В	Programme Click Like	NA NA	NA	NA	
		Pressurization of lift lobby	NA	NA	NA	
		Communication in lift car	NA	NA	NA	
		Firemen's grounding switch	NA	NA	NA	
	E	Lift signage	NA	NA	NA	
17	Sta	andby Power Supply:	Required	Provided	MR	
18	Refuge Area:					
	A	Total area	NA	NA	NA	
	В	Location	NA	NA	NA	
19						
	A	Detector system panel	NA	NA	NA	
		Flow switch panel	NA	NA	NA	
	$\overline{}$	Pa system panel	NA	NA	NA	
		Battery backup	NA	NA	NA	
	E		NA	NA	NA	
20	Sp	pecial Fire Protection Systems Forcial Risks, If Any: 01 Co2 & 0 tinguishers provided near elect.	1 ABC fire	Provided	MR	

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspection.

The owner has submitted an affidavit on 27.10.2025 stating not to use any floor above third

floor for any purpose.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter No F6/DFS/MS/GH/2022/NDZ/480 dated 21.10.2022 is recommended to be renewed upto 3rd floor only, under Rule 35 of the Delhi Fire Service Rules 2010.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name Designation

Sumit Kumar ADO (HQrs)