

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001 No.F6/DFS/MS/GH/2025/ 22 Dated: 2)./.0.4./2025

## FIRE SAFETY CERTIFICATE

Certified that the M/s Hotel Blue Bell located at T-2526 Elahibaksh Road Naiwala Karol Bagh, New Delhi, in a building is comprised of basement + Ground + 03 Upper floors, Ground floor (Reception), 1st floor & 2nd floor (11 guest rooms at each floor) 3rd floor (08 guest rooms,). The FSC was earlier granted by this department vide letter No. F6/DFS/MS/GH/2022/423 dated 12/09/2022 for 30 guest room from ground to third floor only. Now, the premises was re-inspected by the officer concerned of this department on 04/04/25 in the presence of Manager and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, (Sub Division-A-1) Ground floor (Reception), 1st floor to 2nd floor (11 guest rooms at each floor) 3rd floor (08 guest rooms) total 30 guest rooms up to third floor with effect from ... 21.04.22... for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Atul Garg)
DIRECTOR
Delhi Fire Service

Copy to:-

1. The Commissioner, North MCD, Civic Centre, New Delhi: kindly to ensure the occupancy including as detailed above.

2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. Online id no.2025032404453 dated 24.03.2025.

3. The Manager, Hotel Blue Bell T-2526 Elahibaksh Road, Naiwala Karol Bagh, New Delhi.

## Condition for the validity of fire safety certificate

All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
 This FSC is valid for guest house ground to third floor only.

2. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

- 4. The compliance with regards to electrical installation, structural stability, set back area, occupancy and any deviation in construction etc. shall be verified from authority concerned.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
  6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi

Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
7. The means of escape such as staircase evits apprint a declaration every year in form 'K' provided in the first schedule of Delhi Pire Service Rules 2010. The means of escape such as staircase evits apprint a declaration every year in form 'K' provided in the first schedule of Delhi Pire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>

7. The means of escape such as staircase, exits, corridor, etc shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.

8. The Basement shall be used strictly as per BBL concerned.

9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

10. Any flammable material for interior decoration is prohibited.

INSPECTION REPORT 1. Name & address of the building Hotel Blue Bell located T-2526 Elahibaksh Road Naiwala Karol Bagh, New Delhi. 2. Type of Occupancy:-Residential, Sub Division-A-1 B+G+03 Upper floors (total 30 Guest rooms) Gr.- reception, 1st floor to 2nd floor (11 guest rooms at each floor) 3rd floor (08 guest rooms at each floor) Type of case:-Renewal 4. Details of previous FSC:-No.F6/DFS/MS/GH/2022/423 dated 12/09/2022. 5. Fire safety directives No.-N/A 6. Date of inspection:-04/04/2025 7. Name of the inspecting officer:-Sh. Ravinder Singh (ADO/CC) 8. Name & designation of officer from the building side:-Manager 9. Year of construction:-2002 10. Applicant's letter No:-Online id no.2025032404453 dated 24.03.2025. Old Case (renewal) S.No. Minimum Standards on fire Requirement/ Provided at site Remarks Prevention and fire safety MR/NMR Existing fire U/R 33 safety arrangements 1. Access to Building N/A 18 mtr. N/A 1) Road width N/A N/A N/A 2) Gate width N/A N/A N/A 3) Width of internal road Number, Width Type & Arrangement of Exits 2. A. Number of staircases MR 01 No. 01 No. 1. Upper floors N/A N/A N/A 2. Basements B. Width of staircase MR 1.25 mtrs.to 1.25 mtrs. 1. Upper floors 1.30 mtrs N/A N/A N/A 2. Basements C. Protection of exits MR provided Required 1. Fire check door N/A N/A N/A 2. Pressurization MR 01 No. 01 No. D. No. of continuous staircase to terrace MR 1.48, 1.45 mtr. 1.0 mtr. E. Width of corridor MR( old case) 0.79 x 2.08 Mtr. 01 mtr. F. Door size Compartmentation 3. N/A N/A N/A 1) Fire check door N/A sealed 2) Sealing of electrical shafts N/A N/A N/A 3) Fire rating of shaft door N/A N/A N/A N/A 4) Water curtain N/A N/A N/A 5) Fire Dampers Smoke Management System N/A 4. N/A N/A 1) Basements MR provided Required 2) Upper floors Fire Extinguishers 5. MR 10 1) Total numbers 10 MR ABC & CO2 ABC & CO2 2) Types MR Provided Required 3) ISI marking First-Aid Hose Reel

6.

N)32

	101					
	floor	01	Provided	MR		
	2) Deligar of hoos ree. hees	30 mtr.	30 mtr.	MR		
	J) NOZZIC GIGINETO	05 mm	05 mm	MR 🦠		
7.	Automatic Fire Detection & A					
		Required	Provided	MR		
	/	Required	Provided	MR		
	2) 200000000000000000000000000000000000	N/A	N/A	N/A		
	U SERVICE POR SECURIOR DE LA COMPANION DE LA C	Required	Provided	MR		
	5) Hooter's Location	Required	Provided	MR		
8.	MOEFA	Required	Provided	MR		
9.	Public Address System	Required	Provided	MR		
10.	Automatic Sprinkler System					
		N/A	N/A	N/A		
		N/A	N/A	5 NO. 20 PERSON NO. 10 PERSON		
		N/A	N/A	N/A		
	ceiling	. 4/4 L	IV/A	N/A		
11.	Internal Hydrants					
-	1) Size of riser/down-comer	N/A	NI/A			
	2) Number of hydrants per	N/A	N/A	N/A		
	floor	IN/A	N/A	N/A		
	3) Hose box	NI/A				
12.	Yard Hydrants	N/A	N/A	N/A		
		27/4				
	Total number of hydrants     Hose box	N/A	N/A	N/A		
13.		N/A	N/A	N/A		
13.	Pumping Arrangement					
	1) Ground level	N/A	N/A	N/A		
	a) Discharge of main	N/A	N/A	N/A		
	pump	-				
	b) Head of main pump	N/A	N/A	N/A		
	c) Number of main pump	N/A	N/A	N/A		
	d) Jockey pump out put	N/A	N/A	N/A		
	e) Jockey pump head	N/A	N/A	N/A		
	f) Stand by pump output	N/A	N/A	N/A		
	g) Stand by pump head	N/A	N/A	N/A		
	h) Auto starting/Manual	N/A	N/A	N/A		
	stopping	120,000,000	1	IVA		
	2) Terrace level					
	a) Discharge of pump	450 LPM	450 LPM	MR		
	b) Head of pump	30 mtr.	30 mtr.	MR		
	c) Power supply	Required	Provided Provided	MR		
	d) Auto starting of pump	N/A	N/A			
14.	Captive Water Storage for F	ire Fighting	IVA	N/A		
	Under ground tank	N/A	N/A	NI/A		
	capacity		IVA	N/A		
	a) Draw-off connection	N/A	N/A	NT/A		
	b) Fire service inlet	N/A	N/A	N/A		
	c) Access to tank	N/A		N/A		
	d) Over head tank	7500 ltr.	N/A	N/A		
	capacity	/300 Itr.	7500 ltr.	MR		
15.	Exit Signage.	Required	Provided	100		
	LAIL DIEHAPE.	Reduited	I Provided	MR		

20/12

-				
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	Required	Provided	MR
	d) Fireman's switch	Required	Descrit. 1	
	e) Lift signage		Provided	MR
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	Required	Provided	MR
		N/A	N/A	N/A
17	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system     panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Syste Risk, if any:	N/A		

The fire protection systems provided in the guest house building were randomly tested, checked and found functional at the time of inspection. Basement is not checked as it is not a part of guest house.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2022/423 dated 12/09/2022, under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval up to third floor.

Signature of the Inspecting Officer

Name: Ravinder Singh Designation: ADO (CC)

8412

كالمرض (مدوج

Siv Jamps

Director