



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

F.6/DFS/MS/GH/2025/SZ/303 No.

Dated: 02.../0.5./2025

FIRE SAFETY CERTIFICATE

Certified that the M/s Hotel Corporate Park at B-5, Greater Kailash Enclave-I, New Delhi-110048 comprised of Basement (Closed by the management), Ground plus three upper floors owned/occupied by Mr. Aman Marwah was issued Fire Safety Certificate by this department vide letter No. F6/MS/DFS/GH/2022/SZ/418 dated 09-09-2022. The premise was re-inspected by the officer concerned of this department on 29/04/2025 in the presence of Mr. Rohit Kumar (Manager) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for (GF:- 05 G/Rooms, 1st Floor:- 07 G/Rooms, 2nd Floor: 07 G/Rooms & 3rd Floor: 07 G/Rooms, Total 26 G/Rooms) occupancy class "Residential & Lodging", Group-A, and Validity upto 31/03/2028 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on <u>02 05 2025</u>/2025 at New Delhi by

Copy to: -

1. The Addl. Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-110049. (Ref. MCD Portal 2025041706616 dated 17-04-2025)

Conditions for the validity of Fire Safety Certificate: -

All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting

The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-

2016), if any.

"The owner/occupier shall apply for renewal of this Fire Safety Certificate to the 6. Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

Basement is closed with brick wall by the managements.



N-24

		4-89		41	
`	INSPECTIO	N REPORT			
10.	Name & Address of the Building	M/s Hotel Corporate Park at B-5, Greater Kailash Enclave-I, New Delhi-110048			
2	Type of Occupancy	Residential Grove A (C. 177			
3	Building Comprised of	Residential, Group-A (Guest House) Basement (closed by the management) Ground + 3			
4	T	Upper floors (wit	pper floors (with 26 Guest Rooms)		
5	Type of Case	Renewal			
6	Details of Previous NOC	F6/MS/DFS/GH/2022/SZ/418 dated 09-09-2022			
7	Fire Safety Directives Letter No	Nil			
8	Date of Inspection	29-04-2025			
9	Name of the Inspecting Officers	Sh. Suman Kuma	r ADO		
	Name & Designation of Officers from the building side	Mr. Rohit Kumar (Manager)			
10	Year of construction	Ground floor (Rec. & 05 G/Rooms), 1 st Floor (07 G/Rooms), 2 nd Floor (07 G/Rooms) & 3 rd Floor (07 G/Rooms) Total= 26 Guest Rooms.			
11	Applicant letter No.	MCD Portal 202	5041706616 dated 17-	-04-2025	
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Requirements Rule 35(6) Provided at Site Remarks MR/NMR			
1	Access to Building.	219	2-113-11-0.L01		
	Road width	12 mtr	Provided	MR	
	Gate width	N/A	N/A	N/A	
	Width of internal road	N/A	N/A	N/A	
2	Number, width, type & arrangement of exits.		1011 0 4		
	a) Number of Staircase	S in a	21-51-2		
	> Upper floors.	2 Nos	2 Nos	MR	
	Basement floor.	2 Nos	2 Nos	MR	
			133.00 1-300 V 13.0		
	4	1.25 mtr	1.25m & 0.90m	MR (old case	
	Upper floors Basement floor	1.25 mtr	1.25m & 0.90m	MR (old case	
			The same of the same of		
	c) Protection of exits > Fire check door as per clause 7.31	Required	Provided	MR	
	> Pressurization	N/A	N/A	N/A	
	> Pressurization	01 No	Provided	MR	
	d) No. of continuous staircase to terrace	N/A	N/A	N/A	
	e) Width of corridor	1m	1m (final exit)	MR	
	f) Door size	****	and the second		
3	Compartmentation.	N/A	N/A	N/A	
9100	Fire check door.	N/A	N/A	N/A	
	Sealing of electrical shafts.	N/A	N/A	N/A	
	Fire rating of shaft door.	N/A	N/A	N/A	
	Water curtain	N/A	N/A	N/A	
	Fire dampers.	IN/A	As per clause 7.31 of the UBBL-2016		
4	Smoke Management system.	As per clause /	Exhaust fan	MR	
	Basement	30 ACPH	Exhaust fan	MR	
	Upper floors	12 ACPH	Extraust ran		
	Fire Extinguishers.		12 No.	MR	
5	Total numbers	12 Nos	12 Nos	MR	
		ISI marked	ABC & CO ₂	MR	
	Types ISI Marking	IOI IIIMINOG	Provided	MIK	
	• ISI Watking			MR	
6	First Aid Hose Reels. Total numbers on each floor.	Hose-reel	One	MR	
	• Total numbers on each noce		30m		
	Length of hose-reel hose.		5mm	MR	
	Nozzle Diameter Nozzle Diameter Selerming system.	As per clause 7.31 of the UBBL-2016			
7	Nozzie Diameter Automatic fire detection & alarming system.	Co.Mo. Type	Provided	MK	
•	Type of detectors	Required	Provided	MR	
	Location of Main Panel	and the second s	Provided	MR	
	Location of Repeater Panel	Required	Provided	MR	
		Deguired	Provided	TATIC	
	Alternate source of power	Required Required	Provided	MR	



11.25

M/s Hotel Corporate Park at B-5, Greater Kailash Enclave-I, New Delhi-110048 MR Provided **MOEFA** Required 9 MR Public Address System Provided Required 10 Automatic Sprinkler System MR Provided Basement Required N/A N/A Upper floors N/A N/A N/A Sprinkler above false ceiling N/A 11 Internal Hydrants. N/A N/A Size of Riser/Down-comer N/A N/A N/A Number of Hydrant per floor N/A N/A Hose box. N/A N/A 12 Yard Hydrants. Total number of hydrants. N/A N/A N/A N/A Hose box. N/A N/A 13 Pumping arrangements. **Ground Level** Discharge of main pump. N/A N/A N/A Head of main pump. N/A N/A N/A Number of main pumps. N/A N/A N/A Jockey Pump output. N/A N/A N/A Jockey Pump head. N/A N/A N/A Standby Pump output. N/A N/A N/A Standby Pump head. N/A N/A N/A Auto Starting/Manual Stopping. N/A N/A N/A Pump house access. N/A N/A N/A Terrace Level Discharge of pump. Boosting pump 280 LPM MR Head of pump. Required 35m MR Power supply. Required Provided MR Auto starting of pump. Required Provided MR 14 Captive water storage for fire fighting. Underground tank capacity. N/A N/A N/A Draw-off connection. N/A N/A N/A Fire Service Inlet. Required Provided MR Access to tank. N/A N/A N/A Overhead tank capacity. 5,000 Lts 5,000 Lts MR 15 Exit Signage. Required Provided MR 16 Provision of Lifts. Pressurization of lift shaft. N/A N/A N/A N/A N/A Pressurization of lift lobby. N/A Communication in lift car. N/A N/A N/A Fireman's switch. N/A N/A N/A N/A Lift signage. N/A N/A 17 Standby Power Supply Required. Provided MR 18 Refuge Area Total area N/A N/A N/A Location N/A N/A N/A 19 Fire Control Room. Detector system panel. N/A N/A N/A N/A Flow switch panel. N/A N/A N/A PA system panel. N/A N/A N/A Battery backup. N/A N/A N/A Building floor plan. N/A N/A 20 Special Fire Protection System for the N/A N/A N/A Protection of special Risk, if any.



M/s Hotel Corporate Park at B-5, Greater Kailash Enclave-I, New Delhi-110048

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and safety measures as required under the rules, the FSC issued vide letter no F6/MS/DFS/GH/2022/SZ/418 dated 09-09-2022, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of Inspecting Officer Name: Sh. Suman Kumar Design: ADO

DO (South)

And/sh

F.T. letter is but us for synchere My