

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001



No F 6/DFS/MS/GH/2025/NDZ/ 426

Dated: 23/06/2025

## FIRE SAFETY CERTIFICATE

Certified that the Hotel Mandakini Palace located at 8/29, W.E.A., Abdul Aziz Road, Karol Bagh, New Delhi-110005 comprised of Basement (Other Property), Ground Floor (02 Guest Rooms), 1st floor to 3rd floor (08 Guest rooms at each floor) was issued FSC by this department vide letter No F6/DFS/MS/GH/SZ/2022/242 dated 23.05.2022. The premise was re-inspected by the officer concerned of this department on 12.06.2025 in the presence of Sh. Sumit Anand and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have therefore complied with fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premise 31.03.2028 in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40, subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on . 23 06 2025... at New Delhi, by

Copy to: -

1. The Commissioner, MCD, Civic Centre, New Delhi- to ensure the occupancy as detailed above.

2. M/s Hotel Mandakini Palace located at 8/29, W.E.A., Abdul Aziz Road, Karol Bagh, New Delhi-110005.

MCD Portal, ID No. 2025060209482.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.

2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

5. This certificate cannot be treated in any case for regularizations of unauthorized construction.

6. The owner/occupier shall apply for renewal of this Fire Safety Certificate through MCD portal (https://www.mcdonline.nic.in) along with a copy of this Certificate, six months prior to its expiry.

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

8. This FSC is only for total 26 guest rooms from Ground floor to 3<sup>rd</sup> floor only.

9. The basement is separate from guest house shall be used strictly as per BBL.

N. 27 1. Name & address of the building: Hotel Mandakini Palace located at 8/29, W.E.A., Abdul Aziz Road, Karol Bagh, Delhi- 110005. 3. Building Comprised of Residential (A-1) (Total 26 Guest Rooms) : Basement (Other Property), Ground Floor (02 Guest Rooms ), Type of Case 1st Floor to 3rd floor (08 Guest Rooms at each floor) 5. Details of Previous NOC 6. Fire Safety directives letter No F6/DFS/MS/GH/SZ/2022/242 Dated 23/05/2022 7. Date of inspection Nil 8. Name of Inspecting Officer 12/06/2025 9. Name and designation of officers R.K.Sinha, ADO (BW) 10. From the building side Sh. Sumit Anand 11. Year of Construction 12. Applicant's letter No. 1990 as per MCD Portal MCD Application ID No. 2025060209482 dated 02/06/2025 Minimum Standards on fire Old case Remarks prevention and fire safety U/R 33 Requirement No. Provided at site **Existing fire safety** MR/NMR arrangements Access to building Road width MR Accessible 7 m Gate width NA Directly accessible NA Width of internal road NA NA NA Number, Width, Type & Arrangement of Exits Number of staircases Upper Floors MR (old case) 01 01 Basements MR (old case) 01 01 Width of staircases Upper Floor 1.25 m MR(old case) 1.26 m Basements 1.25 m MR(old case) 1.15 m Protection of exits Fire check door Required Provided MR Pressurization NA NA NA No. of continuous staircases to 01 01 MR terrace Width of Corridor 1 m 1.55 m MR Old case 1.02 m & 2.06 m MR(old case) Door Size Compartmentation Fire check door Required Provided MR Required Sealing of electrical shafts Sealed MR Fire Rating of shaft door NA NA NA Water Curtain NA NA NA Fire Dampers NA NA NA Smoke Management System Basements NA NA NA Required Upper floors Exhaust fan provided MR Fire Extinguishers Total numbers 02 Nos. at each floor Provided MR Types ABC/Co2 Type Provided MR IS marking Required Provided MR First-Aid Hose Reels Total numbers on each floor 01 Provided NA Length of hose reel hose 30 m 30 m MR Nozzle diameter 5 mm 5 mm MR Automatic fire detection and alarming system Type of detectors CO

S.

1.

2.

3.

4.

5.

6.

7.

or

Provided

MR

		× 100	Provided	MIK
	Location of Main Panel	Ground Floor	NA	NA
	Location of Repeater Panel	NA NA	Provided	MR
	Alternate source of power	Required	Provided	MR
	II	Each Floor		100
0	Hooters' Location MOEFA	Required	Provided	MR
8. 9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
10.			Provided	MR
	Basement	Required	NA	NA
	Upper Floor	NA NA	NA NA	NA
	Sprinkler above false ceiling	NA	NA months	1
11.	Internal Hydrants		NA	· NA
	Size of riser/down-comer	NA	NA NA	NA NA
	Number of hydrants per floor	NA NA	NA NA	NA
	Hose Box	NA NA	NA	1 La
12.	Yard Hydrants	374	NA	NA
	Total number of hydrants	NA NA	NA NA	NA
	Hose Box	NA	1.77.	
13.	Pumping Arrangements			
	Ground Level			
	Discharge of main Pump	NA	NA	NA NA
	Head of Main pump	NA	NA	NA NA
	1 1	NA	NA	NA
	Number of main pumps	NA NA	NA	, NA
	Jockey Pump out put Jockey pump head	NA NA	NA	NA
	Standby Pump out put	NA NA	NA .	NA NA
	Standby Pump Head	NA	NA	NA NA
	Auto Starting/Manual Stopping	NA	NA	NA NA
	Pump House Access	NA	NA	NA
				1
	Terrace level	900 lpm	Provided	MR
	Discharge of pump	40 m	Provided	MR
	Head of the pump	Required	Provided	MR
	Power Supply Auto Starting of pump	Required	Provided	MR
14.	Captive Water Storage for fire figh			er er
	Captive water storage as		341	NA
	Underground tank capacity	NA	NA	
	Draw-off connection	NA	NA	TAA
	Fire service inlet	NA	Provided	NA NA
	Access to tank	NA	NA	The state of the s
	Overhead Tank capacity	10,000 ltrs	Provided	MR MR
15.	Exit Signage.	Required	Provided	IVIK
16.	Provision of Lifts.			
	- CL'O CL-A	NA	NA	NA
	Pressurization of Lift Shaft	NA NA	NA	NA
	Pressurization of Lift lobby	NA NA	NA	NA
	Communication In lift Car		Provided	MR
	Fireman's Grounding Switch	Required	Provided	MR
	Lift Signage	Required		MR
17.	Standby power supply	Required	Provided	IVIK
18.	Refuge Area.		<u> </u>	
	Total Area	NA	NA	NA
	Location	NA	NA	NA
19.	Fire Control Room			4
		NA	NA	NA
	Detector System Panel	NA NA	NA NA	NA NA
	Flow Switch Panel	NA NA	NA NA	NA NA
	PA System Panel			
	Battery backup	NA NA	NA	NA
		ON	B	

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The management had rectified the shortcomings issued vide letter no. F6/DFS/MS/GH/NDZ/2025/254 dated 23/05/2025.

Keeping in view of compliance of the minimum standards of fire prevention and fire safety measures as required under rules it is recommended to renew the fire safety certificate issued vide letter no. F6/DFS/MS/GH/SZ/2022/242 dated 23/05/2022 under rule 37 of the Delhi Fire Service Rules, 2010 if agreed. Accordingly DFA is placed on file, please.

Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W.

Docodi 17/6/25 CPO/ Nundament Deneetay Deneetay Deneetay Sw. ft les

Dweltox Ofs

ten ripreso to you

24/1/25 Qu/1/25