

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001



No. F.6/DFS/MS/GH/NDZ/2025/ 269

Dated: 28/04/2025

FIRE SAFETY CERTIFICATE

Issued 28 64 120 at New Delhi by.

(Att) Garg)
Director
elhi Fire Service

Copy to:-

- 1. The Commissioner, MCD, Civic Centre, New Delhi: with a request to ensure the occupancy as detailed above.
- The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. Online id no. 2025040205388 dated 02.04.2025
- 3. The Manager, Hotel Palm Grand (Grand Affairs Hospitality Pvt. Ltd.) at A-1, Naraina Vihar, Ring Road, New Delhi-110028.

Condition for the validity of Fire Safety Certificate

- 1. No occupancy used above third floor, basement use for only storage purpose & lift sealed in basement shall be strictly adhered by Owner/Occupier.
- All the means of escape shall be kept free of all type of obstruction all the time.
- All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the fire fighting equipment shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, amangement shall be responsible.
- 5. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified by the concerned building sanctioning authority.
- 6. The fire safety certificate may not be treated in any case for regularization of unauthorized construction/unauthorized use of land, if any.
- 7. All comments/directions of licensing department shall always be permitted and followed.
- 8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six month prior to its expiry.
- 10. Any flammable material for interior decoration is prohibited.

			N-17		,e			
1	Name & address of the M/s Hotel Polm Count (Count A String Hospitality)							
	100000	ilding	Pvt. Ltd.) at A-1, Naraina Vihar, Ring Road, New					
2	Bu	ilding is comprised of	Delhi-110028 Building comprised of basement, stilt, ground plus three upper floors using basement as incidental storage, stilt as parking, ground floor (vacant), first & second floor each having 13 guest rooms respectively					
3	Tv	pe of occupancy	rooms only)					
4		pe of case	Lodging House					
2/81			Renewal					
5	_	tails of previous FSC	No. F.6/DFS/MS	/GH/SZ/2022/144 da	ted 10.03.2022			
6		e safety directive letter no.	Nil	do do	F 5 - 1			
7	Da	te of inspection	22.04.2025					
8	5-7-11-1	me of the inspecting icers	Suman Kumar, ADO					
9		me of the designation of icer from the building side	-					
10		ar of construction	1993-94					
11	Ap	plicant's letter no.	Online ID No. 20	25040205388 dated (02.04.2025			
S. No	Pr	nimum standard of Fire evention and Fire Safety R 33	Fire safety requirements as per FSC dt. 10.03.2022	Provided at site	Remarks MR/NMR			
1	Ac	cess to Building	a Male		David III			
	A	Road width	06 m	Provided	MR			
	В	Gate width	4.5 m	Directly accessible	MR			
	C	Width of internal roads	NA	NA	NA			
2	A	mber, Width, Type & Arr No. of staircase:	angement of Exits					
	A	a) Upper floor	02 nos.	02 nos.	MR			
		b) Basements	02 nos.	02 nos.	MR			
	В	Width of the staircase:			10			
	1	a) Upper floors	1.50 m & 1.0 m	1.50 m &1.42 m (iron made)	MR being old			
		b) Basements	1.50 m & 1.0 m	1.38 m, 1.30 m	MR being old			
	C	Protection of Exits		I B	T 1 (D)			
		Fire check door Pressurization	Required NA	Provided NA	MR NA			
	D	No. of continuous staircase to terrace:	01 no.	01 no.	MR			
	E	Width of the corridor	1.50 m	1.80 m	MR			
	F	Door size	1.0 m	1.0 m	MR			
3	Co	npartmentation:			1232			
	A	Fire check doors	Required	Provided	MR			
	В	Sealing of horizontal & vertical opening	Required	Sealed	MR			
	C	Fire rating of shaft doors Water curtain	N/A N/A	N/A N/A	N/A			
	D E	Fire dampers	N/A N/A	N/A N/A	N/A N/A			
4		oke Management System:		AMAX	INA			
	A	Basements	12 ACPH	Exhaust Fan	MR			
	В	Upper floors	12 ACPH	Exhaust Fan	MR			
	-	-5.45			4			
5		Extinguishers						
5		Extinguishers Total numbers	15 nos.	Provided	MR			
5	Fire		15 nos. CO ₂ & ABC	Provided Provided	MR MR			

6	F	irst Aid Hose Reel	01 nos.	Provided	MR		
	A		30 mtrs	Provided	MR		
		Length of hose reel	5 mm	Provided	MR		
	C	Nozzle diameter					
7	A	utomatic Fire Detection and Alarm	Carbon	Provided	MR		
	A		Monoxide				
			Required	Provided near	MR		
	В	Location of main Panel	Requires	reception	1		
			N/A	N/A	N/A		
		Location of repeater panel	N/A	N/A	N/A		
	D		N/A	N/A	N/A		
	E		Required	Provided	MR		
8		OEFA	Required	Provided	MR		
9	Pı	Public Address System Required					
10		utomatic Sprinkler System	Required	Provided	MR		
	A		N/A	Provided at each	N/A		
	В	Upper floor	1 1 1 1	floor	2.27.		
		O Languilling	N/A	N/A	N/A		
	C		1471				
11	In	ternal Hydrants	N/A	100 mm	N/A		
	A	Size of the riser/down comer	N/A	Provided	N/A		
	В		N/A	Provided	N/A		
	C	Hose box	IWA				
12	Ya	rd Hydrants	NA	NA	NA		
	A	Total no. of hydrants	NA NA	NA	NA		
	B	Hose box	INA				
13	Pu	mping Arrangements	22. 1				
	A	Cround Level	N/A	N/A	N/A		
	1	 Discharge of main pump 	N/A N/A	N/A	N/A		
		> Head of main pump		120 a 20 a 2	N/A		
		> Number of main pump	N/A	N/A	N/A		
		Discharge of jockey pump	N/A	N/A	N/A		
		Head of jockey pump	N/A	N/A	N/A		
		Discharge of Standby pump	N/A	N/A	1 3800		
		250	N/A	N/A	N/A		
		➤ Head of Standby pump	N/A	N/A	N/A		
		> Auto starting/ manual stopping	N/A	N/A	N/A		
		> Pump house access	14474	- NI			
	В	Terrace Level	450 I DM = 2	900 LPM	MR		
		Discharge of terrace pump	450 LPM x 2	Provided	MR		
		Head of terrace pump	40 m	THE REPORT OF THE PARTY OF THE	MR		
		> Alternate power supply	Required	Provided	MR		
		> Auto starting of pump	Required	Provided	IATIC		
4	Ca	ptive Water Storage for Fire Fightin	g	244	NI/A		
	A	Underground tank capacity	N/A	N/A	N/A		
	B	Draw off connection	N/A	N/A	N/A		
	C	Fire Service Inlet	N/A	N/A	N/A		
	E	Access to tank	Required	Provided	MR		
	D	Overhead tank capacity	10,000 Ltrs.	10,000 Ltrs.	MR		
_		t Signage	Required	Provided	MR		
5	Dravision of lift						
6_	-	Pressurization of lift shaft	NA	NA	NA		
	A	Pressurization of lift lobby	NA	NA	NA		
			Required	Provided	MR		
	_	Communication in lift car	Required	Provided	MR		
		Fireman switch		Provided	MR		
		Lift signage	Required		MR		
7	Star	ndby Power Supply	Required	Provided	INIL		

41

18	Refuge Area						
	A	location	NA	NA	NA		
	В	Total area	NA	NA	NA		
19	Fire Control Room						
	A	Fire detection system panel	NA	Provided	NA		
	В	Flow switch panel	NA	Provided	NA		
	C	P A system panel	NA	Provided	NA		
	D	Battery backup	Required	Provided	MR		
	E	Building floor plan	NA	NA	NA		
20	Special Fire Protection for special risk if any						
	Special fire protection system for protection of special risk, if any:		NA	N/A	NA		

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

Keeping in view the substantial Compliance of the minimum standards on fire prevention and fire safety required under the rules, the FSC vide letter no. F.6/DFS/MS/GH/SZ/2022/144 dated 10.03.2022 renewal under the Rule 37 of the Delhi Fire Service Rules 2010 is recommended for approval up to third floor.

Signature of the Inspecting Officer

Name Suman Kumar Designation ADO

70 (cs)

CRO Muga

Dergetar/

Any Syme

7.7. letter i hut up for signalure let

10 25/04/25

Valorded of alulis