

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No.F6/DFS/MS/2025/GH/ 277

## FIRE SAFETY CERTIFICATE

Dated 29/04/2025

Certified that the Hotel Picasso Prive located at A-14, Naraina Vihar, Delhi-110028, was granted FSC for building comprised of basement, stilt, ground & 03 upper floors, using basement as incidental storage, stilt floor as parking & lobby, Ground floor as parking & office, first & second floor each having front side 04 guest rooms & thirds floor having 13 guest rooms respectively (total 21 guest rooms) was granted FSC by this department vide letter no. F6/DFS/MS/GH/SZ/2022/246 dated 25.05.2022. The guest house was inspected by the officer concerned of this department on 21.04.2025 in the presence of Sh. Kawaljeet Singh (Owner) and found that the owner/occupier have deemed complied with the requirement under rule 33 of Delhi Fire Service Rules, 2010 and the building is fit for occupancy "Class Residential Group A-1" (guest house) for basement as incidental storage, stilt floor as parking & lobby, Ground floor as parking & office, first & second floor each having front side 04 guest rooms & third floor having 12 guest rooms respectively (total 20 guest rooms only) with effect from 29 of 2225 for a period of 03 (Three) years, in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on .29/04/2025. at New Delhi by

Pb. 011-23414000

Copy to:-

1. The Commissioner, Municipal Corporation of Delhi, with a request to ensure the occupancy as detailed above deviation and if any.

2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defense Colony New Delhi. ID no. No-22025040505640 dated: 05.04.2025.

3. The Owner, Hotel Picasso Prive located at A-14, Naraina Vihar, Delhi-110028.

## Conditions for the validity of Fire Safety Certificate:

 No occupancy used above third floor and basement used for storage purpose only shall be strictly adhered by Owner/occupier.

2. All the means of escape shall be kept free from any type of obstruction all the time.

3. All the employees shall be acquainted with the use and maintenance of all fire equipment and method of smooth and speedy safe evacuation of occupants in case of emergency

4. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seem during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

5. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities. This Fire Safety Certificate is valid only for permanent building structure as per plan.

6. This fire safety certificate may not be treated in any case of regularizations of unauthorized construction/unauthorized use of land or activities, if any.

7. The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on the official website of Delhi Fire Service i.e. www.dfs.delhigovt.nic.in.

8. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the MCD portal

along with a copy of this Certificate, six months prior to its expiry".

9. The Fire Safety Certificate is valid only for 13 guest rooms up to 3<sup>rd</sup> floor. In case of any violation, this FSC will be treated as null & void.

## INSPECTION REPORT

Name & address of the building : M/s Hotel Picasso Prive at A-14, Naraina Vihar, Delhi-110028.

2. Type of Occupancy : Residential, Sub Division A-1 (20 Guar Rooms)

Composition of building : Basement, Stilt, Ground & 03 Upper floors, said guest house is running on

Partial first floor having -04, guest rooms, partial second floor having 04 guest

Rooms & third floor having 12 guest rooms in a building comprised of

Basement use as storage, stilt using as parking & lobby, upper ground using as Parking, office, partial first & partial second floor using as owner residence,

Partial first, partial second floor and third floor using as guest house.

4. Type of Case : Renewal

5. Details of previous NOC : F6/DFS/MS/GH/SZ/2022/246 dated 25.05.2022

6. Fire Safety directives letter No : Nil

7. Date of inspection : 21.04.2025
8. Name of the Inspecting Officers : ADO (RN)

9. Name and designation of officers

from the building side : Sh. Kawaljeet Singh (Owner)

10. Year of Construction : 2014-15

	Minimum Standards on fire prevention and fire safety U/R 33	Fire safety Requirement as per NBC/BBL	Provided at site	Remarks MR/NMR				
	Access to building							
	Road width	Accessible	06m	NA				
	Gate width	NA	Directly accessible from road	NA NA				
	Width of internal road	- NA	NA	NA				
	Number, Width, Type & Arrangement of Exits							
	a. Number of staircases							
	Upper Floors	02	01	MR (being old case 0) stair case is up to GF)				
	Basements	02	02	MR				
	b. Width of staircases							
	Upper Floors	1.50m	1.52m	MR				
	Basements	1.50m	1.53m & 1.10m	MR				
	c. Protection of exits							
	Fire check door	Required	Provided	MR				
	Pressurization	NA	NA	NA				
	d. No. of continuous staircases to terrace	01	01	MR (being old case)				
	e. Width of Corridor		1.45m	MR (being old case				
	f. Door Size	-	80cm x 205cm	MR (being old case				
	Compartmentation.							
	Fire check door	Required	Provided	MR				
	Sealing of electrical shafts	NA	NA	NA				
	Fire Rating of shaft door	NA	NA	NA				
	Water Curtain	NA	NA	NA				
	Fire Dampers	NA	NA	NA				
	Smoke Management System.							
	Basements	Required	Provided	MR				
	Upper floors	Required	Provided	MR				
5	Fire Extinguishers		400					

		N 33		1			
	Total numbers	03 at each floor	Provided	MR			
	Types	W. 2 (100) - C. (100) - C. (100) - C. (100) - C. (100)	Provided	MR			
	ISI marking	ABC & Co2	Provided	MR			
5	First-Aid Hose Reels.						
			01	MR			
	Total numbers on each floor	01		NA			
	Length of hose reel hose	30m	30m	NA			
	Nozzle diameter	05mm	05mm	NA .			
7	Automatic Constitution and all automatics are all automatics and all automatics are all automatics and all automatics and all automatics are all automatics are all automatics and all automatics are all a						
	Type of detectors	Carbon Monoxide	Provided	MR			
	Location of Main Panel	Required	Provided	NA			
	Location of Repeater Panel	NA .	NA	NA			
	Alternate source of power	NA	NA	NA NA			
		NA	NA	4			
12	Hooters' Location	Required	Provided	MR			
8	MOEFA	Required	Provided	MR			
9	Public Address System.						
10	Automatic Sprinkler System.	10.00	Provided	MR			
	Basement	Required		NA			
	Upper Floor	NA	Provided				
	Sprinkler above false ceiling	NA	NA	NA			
				NA			
11	Internal Hydrants  • Size of riser/down-comer	NA NA	NA	NA NA			
	St. Market Sciences	NA	NA				
	Number of hydrants per floor	NA	NA	NA			
	Hose Box			NIA			
12	Yard Hydrants.  Total number of hydrants	NA .	NA	NA			
	Hose Box	NA	NA	NA			
	Pumping Arrangements.						
13	Ground Level		5,1				
	Discharge of main Pump	N/A	N/A	N/A			
	➤ Head of Main pump	N/A	N/A	N/A			
	> Number of main pumps	N/A	N/A	N/A			
	<ul> <li>Jockey Pump out put</li> <li>Jockey pump head</li> </ul>	N/A	N/A	N/A			
	Standby Pump out put	N/A	N/A	N/A			
	> Standby Pump Head	N/A N/A	N/A N/A	N/A N/A			
	<ul> <li>Auto Starting/ Manual stopping</li> <li>Pump House Access</li> </ul>	N/A N/A	NI/A	N/A			
	Terrace level	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1					
	> Discharge of pump	02 nos. of 450 LPM	Provided	MR			
	➤ Head of the pump	30m	Provided	MR			
				The state of the s			
	> Power Supply	Required	Provided	MR			
	Auto Starting of pump	Required	Provided	MR			
4	Captive Water Storage for firefighting.						
1	Underground tank capacity	NA	NA	NA			
	> Draw-off connection	NA	NA				
	1	NA NA	441100,445	NA			
- 1	No.	5000 DO	Provided	NA			
	Access to tank	NA	NA	NA			

_	Overhead Tank capacity	10,000 ltrs	Provided	MR		
		Required	Provided	MR		
5	Exit Signage.		7 P -941			
6	Provision of Lifts.	N/A	N/A	N/A		
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby     Communication In lift Car	N/A	N/A	N/A		
		Required	Provided	MR		
	Fireman's Grounding Switch		Provided	MR		
	Lift Signage	Required		MR		
7	Standby power supply	Required	Provided			
000	. WA					
8	Refuge Area.	N/A	N/A	N/A		
	> Location	N/A	N/A	1971		
9	Fire Control Room					
	Detector System Panel	N/A	Method III	N/A		
	Flow Switch Panel	N/A	N/A	-		
	PA System Panel	N/A	N/A	N/A		
	Batter backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
20	Special Fire Protection Systems for	N/A	N/A	N/A		
20	Protection of special Risks, if any:					

The fire protection systems provided in the building were tested/ checked and found in working order at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to renew Fire Safety Certificate issued vide this department letter of even no. F6/DFS/MS/GH/SZ/2022/246 dated 25.05.2022, under rule 37 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name: - C.L. Meena

Designation: Asst. Div. Officer (RN)

22/4/25

cso

Dheeter

Anykay

Conf -. P.T.O -