

Dated: 02 05 202

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No.F.6/DFS/MS/GH/2025/NDZ/ 304

FIRE SAFETY CERTIFICATE

Certified that the M/s Hotel Picasso (Guest House)located at Property No. B-374, Meera Bagh, Pachim Vihar, New Delhi 110063, comprised of Basement, ground plus three upper floors, Basement - storage, Ground floor- 03 guest rooms, First floor - 05 guest rooms, Second floor - 05 guest rooms & Third floor -05 guest rooms, (total 18 guest rooms only) owned/occupied by Hotel Picasso (Guest House) was earlier granted FSC by this department vide letter no. F.6/DFS/MS/WZ/GH/2022WZ/302 dated 23/06/2022. The premises was re-inspected by the officer concerned of this department on 28/04/2025 in the presence of Mr. Gurjeet Singh Chona and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rule, 2010 and that the premises is fit for occupancy Residential Building, Group A, Sub Division-A-1, (Basement - storage, Ground floor- 03 guest rooms, First floor - 05 guest rooms, Second floor - 05 guest rooms & Third floor -05 guest rooms) total 18 guest rooms up to third floor only with effect from 02 55 2025 and valid up to 31/03/2028 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010 & also conditions printed below.

DELHI FIRE SERVICE

To:-

1. The Joint. Commissioner of Police (Lic.) 1st floor Police Station Defence Colony, New Delhi

2. The Dy. Health Officer, Keshav Puram Zone, NDMC, Public Health Department, A-1, Block Keshav Puram Zone, Delhi

MCD ID No. 2025040505642 dated 05/04/2025

Conditions for the validity of Fire Safety Certificate

1. All the means of escape shall be kept free of all type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipment shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.

4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.

5. The basement shall be used for storage purpose only.

This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.

7. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry.

The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

	Name & address of the building Building is comprised of rooms, 1 st - 05 guest rooms, 2 nd floor	: M/s Hotel Picasso (Guest House), Property No. B-374, MeeraBagh, PachimVihar, New Delhi :Basement, ground plus three upper floors, using basement - storage, ground floor-03 guest r -05 guest rooms & 3 rd floor -05 guest rooms (total18 guest rooms only)	-
5 6 7 8 9 1	Type of Occupancy Type of Case Details of Previous NOC letter Tire Safety directive letter No Date of Inspection Name of the Inspecting officers Name and designation of Officer From the building side Year of Construction Applicant's letter No	:Lodging House : Renewal :F.6/DFS/MS/WZ/GH/2022WZ/302 dated 23/06/2022 : Nil :28/04/2025 :ADO Shahdara Mr. Gurjeet Singh Chona :Before 2009 : ID 2025040505642 dated 05/04/2025	
Sr	Minimum Standards on fire	Requirement Provided at Site Remarks MR/NMR	

Sr.	Minimum Standards on fire prevention and fire safety U/R33	Requirement as per FSC dt23/06/2022 Provided at Site		Remarks MR/NMR			
01	Access to building.						
	Road width	06 mtr	Provided (on Road)	MR			
	Gate width	4.50 mtr	Provided (on Road)	MR			
	Width of internal road	N/A	N/A	N/A			
02	Number, Width, Type and Arrange						
1	a. Number of Staircases						
	Upper Floor	01 nos.	Provided.	MR			
	Basement	02 nos.	Provided.	MR			
	B. Width of Staircases						
	Upper Floor	1.50mtrs	1.35 mtrs to 1.50mtrs	MR old accepted			
	Basement C. Protection of exits	1.50mtrs	1.35 mtrs to 1.50mtrs x 02 nos.	MR old accepted			
	Fire check door		Domidad	MD			
	 Pressurization 	Required	Provided	MR			
1	d. No. of continuous staircases	N/A	N/A	N/A			
	toterrace e. Width of Corridor	01 nos	01 nos	MR			
	f. Door Size	1.50mtrs	1.58 mtrs	MR			
		N/A	N/A	N/A			
03	Compartmentation.						
	Fire check door	Required	Provided	MR			
	Sealing of electrical shafts	N/A	N/A	N/A			
	 Fire rating of shaft door 	N/A	N/A	N/A			
1	Water curtain	N/A	N/A	N/A			
-	Fire Dampers	N/A	N/A	N/A			
04	Smoke Management System.						
	 Basement 	12 a/c per hour	Provided	MR			
05	Upper floor	12 a/c per hour	Natural Ventilation	MR			
05.	Fire Extinguishers.						
	 Total numbers 	12nos.	12 nos.	MR			
+	• types	ABC /CO ₂	ABC /CO ₂	MR			
+	 IS marking 	Required	Provided	MR			

3	First-aid-Hose Reels.		Provided	MR			
	Total numbers on each floor	01 No.	Provided	MR			
	 Length of hose reel hose 	30 mtr.	Provided	MR			
	 Nozzle diameter 	05 mm	Provided				
7	Automatic fire detection and alarming syste	em.					
		Carbon Monoxide	Provided	MR			
	Type of detectors	Required	Provided	MR			
	 Location of main panel 	near SC		21/0			
	Location of repeater panel	N/A	N/A	N/A			
	Alternate source of power	Required	Provided	MR			
	Hooter's location	Required	Provided	MR			
08	MOEFA	N/A	N/A	N/A			
09	Public address System.	N/A	N/A	N/A			
10	r done address system.						
			Provided	MR			
	Basement	Required	Provided	1411.5			
	upper floor	N/A	N/A	N/A			
×	sprinkler above false ceiling	N/A	N/A	N/A			
11	Sprinker above raise ceiling						
	•	NI/A	N/A	N/A			
	size of riser/down-comer	N/A	N/A N/A	N/A			
À	Number of hydrants per floor	N/A	N/A N/A	N/A			
12	Hose Box Vard Undergate	N/A	IN/A	14//			
12	Yard Hydrants.	*					
	Total number of hydrants	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
13	Pumping Arrangements.						
	Crown d I avail	NI/A	N/A	N/A			
	Ground Level Discharge of main Pump	N/A	W 10.70 SA.	N/A			
	Discharge of main PumpHead of Main Pump	N/A N/A	N/A N/A	N/A N/A			
	Number of main pumps	N/A	N/A N/A	N/A			
	> Jockey pump out put	N/A	N/A	N/A			
	> Jockey pump head	N/A	N/A	N/A			
	> Standby pump out put	N/A	N/A	N/A			
	> Standby pump Head	N/A	N/A	N/A			
	Auto Starting /Manual stopping	N/A	N/A	N/A			
	Pump House Access	N/A	N/A	N/A			
	Terrace Level			14//			
	Discharge of pump	900 Lpm.	Provided	MR			
	Head of the Pump	30 mtr	Provided	MR			
	> Power supply	Required	Provided	MR			
	Auto Starting of pump	Required	Provided	MR			
14	Captive Water Storage for Fire Fighting.						
	Underground tank capacity	N/A	N/A	N/A			
	> Draw-off connection	N/A	N/A	N/A			
	Fire service inlet	N/A	N/A	N/A			
	> Access to tank	N/A	N/A	N/A			
	Overhead Tank capacity	10,000 Ltr.	Provided	MR			
15	Exit Signage.	Required	Provided	MR			
16	Provision of Lifts.			IVIIX			
	Pressurization of Lift Shaft	N/A	N/A	N/A			
	Pressurization of Lift lobby	N/A	N/A	N/A			
	Communication in lift car	Required	Provided	MR			
				-			
	 Firemen's grounding switch 	Required	Provided	MR			

_

+1/24

	Standby power supply	Required	Provided	MR
17 18	Refuge Area.			
	Total area	N/A	N/A	N/A
	Location	N/A	N/A	N/A
19	Fire Control Room			
19	Detector system panel	N/A	N/A	N/A
	Flow switch panel	N/A	N/A	N/A
	PA system panel	N/A	N/A	N/A
	B-ttony backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection systems for protection of special Risks, if	N/A	N/A	N/A
	any:			

The fire protection systems provided in the building/premises were checked, tested at random and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the Fire Safety Certificate issued vide letter no. F.6/DFS/MS/WZ/GH/2022WZ/302 dated 23/06/2022, renewal under Rule 37 of the Delhi Fire Service Rules 2010, is recommended.

Signature of the Inspecting Officer

Name Designation : Deepak Kumar : ADO (Shd.)

N/A N/A OFFORM 25 PANASSE N/A N/A N/A N/A

Provided

provided Provided

N

N/

N/

N/A N/A

Provided Provided N/A ovideo

MF