## OVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2025/489

Dated 06 /0 /2025

## FIRE SAFETY CERTIFICATE

Issued 66/09/2025 at New Delhi by.

Virendra Singh Chief Fire Officer Delhi Fire Service

Copy to:-

1. The Commissioner, Municipal Corporation of Delhi, with a request to ensure the occupancy detailed above. Online id no. 2025080812379 dated 08/08/2025.

2. The Manager, Hotel President located at 4/23-B, Asaf Ali Road, Darya Ganj Delhi-110002.

## Condition for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.

4. The compliance with regards to electrical installation, structural stability, set back area, occupancy and any deviation in construction etc. shall be verified from authority concerned.

- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.
- 7. The basement shall be used as per the provisions of BBL /NBC Part- IV.

8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.

9. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the MCD portal along with a copy of this Certificate, six months prior to its expiry".

 The Fire Safety Certificate is valid for 18 guest rooms up to second floor only. In case of any violation, this FSC will be treated as null & void.

11. Any flammable material for interior decoration is prohibited.

INSPECTION REPORT 1. Name & address of the building M/s Hotel President at 4/23-B, Asaf Ali Road, New Delhi. 2. Type of occupancy:-Residential, Sub Division-A-1 B + Gr. + Mezz. + 02 Upper floors (total 18 Guest rooms) Ground floor (reception), Mezzanine floor (03 rooms for store purpose), 1st floor (09 guest rooms) 2<sup>nd</sup> floor (09 guest rooms) 3. Type of case:-Renewal 4. Details of previous FSC:-No. F6/DFS/MS/GH/NDZ/2022/508 dated 11/11/2022 5. Fire safety directives No .-N/A 6. Date of inspection:-26/08/2025 7. Name of the inspecting officer:-ADO (RN) 8. Name & designation of officer From the building side:-Sh. Ramesh 9. Year of construction:-Prior to 1984 10. Applicant's letter No:-2025080812379 dated 08/08/2025. Old Case S.No. Minimum Standards on fire Remarks Requirement Provided at site Existing fire MR/NMR Prevention and fire safety safety U/R 33 arrangements 1. Access to Building NA 18 mtr. 1) Road width N/A N/A 2) Gate width N/A N/A N/A N/A 3) Width of internal road N/A Number, Width Type & Arrangement of Exits 2. A. Number of staircases MR 02 Nos. 02 Nos. 1. Upper floors MR 02 Nos. 2. Basements 02 Nos. B. Width of staircase 1.17 to 1.21 mtr. MR 0.80 mtr. 1. Upper floors Iron s/c 1.27 1.25 & 1.05 Mtr. MR 0.80 mtr. 2. Basements C. Protection of exits MR Provided Required 1. Fire check door N/A N/A N/A 2. Pressurization N/A N/A N/A D. No. of continuous staircase to terrace N/A N/A N/A E. Width of corridor 1 mtr. MR 1 mtr. F. Door size Compartmentation 3. N/A N/A N/A 1) Fire check door N/A N/A 2) Sealing of electrical shafts N/A N/A N/A 3) Fire rating of shaft door N/A 4) Water curtain N/A N/A N/A N/A N/A N/A 5) Fire Dampers Smoke Management System 4. Exhaust fan MR 1) Basements Required Natural MR 2) Upper floors Required 5. Fire Extinguishers MR 10 Nos. 10 Nos. 1) Total numbers ABC & CO2 MR 2) Types ABC & CO2 MR Provided 3) ISI marking Required First-Aid Hose Reel 6. 01 MR 1) Total number of eachfloor 01 30 mtr. MR 2) Length of hose reel hose 30 mtr. 3) Nozzle diameter 05 mm 05 mm MR 7. Automatic Fire Detection & Alarming System Provided 1) Type of detectors Co type Required MR 2) Location of main panel Ground floor Provided MR 3) Location of repeater panel N/A N/A N/A Required Provided 4) Alternate source of power MR 5) Hooter's Location Each floor Provided MR 2

		H 72		100
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
10.	1) Basement	Required	Provided	MR
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	N/A
	ceiling	1	CHOINESSED.	
11.	Internal Hydrants			
	1) Size of riser/down-comer	100 mm	100 mm	MR
	2) Number of hydrants per	01	01	MR
	floor			
	3) Hose box	01	01	MR
12.	Yard Hydrants	en e		
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	<b>Pumping Arrangement</b>			
	Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	N/A	N/A
	pump			
	b) Head of main pump	N/A	N/A	N/A
14.	c) Number of main	N/A	N/A	N/A
	pump			
	d) Jockey pump out put	N/A	N/A	N/A
	<ul> <li>e) Jockey pump head</li> </ul>	N/A	N/A	N/A
	f) Stand by pump	N/A	N/A	N/A
	output			
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto	N/A	N/A	N/A
	starting/Manual			
	stopping			
	2) Terrace level			
	a) Discharge of pump	450 & 180	450 & 180 LPM	MR
	b) Head of	LPM		
	b) Head of pump c) Power supply	40 mtr.	40 mtr.	MR
	c) Power supply d) Auto starting of	Required	Provided	MR
	pump	Required	Provided	MR
	Captive Water Storage for			
14.	1) Under ground tank		D	TV6
	capacity	21,000 ltr.	Provided	MR
	a) Draw-off connection	N/A	NI/A	N//
	b) Fire service inlet	N/A N/A	N/A	N/A
	c) Access to tank	N/A N/A	N/A	N/A
	d) Over head tank	2-00-01-01-02-02-02-02-02-02-02-02-02-02-02-02-02-	N/A	N/A
	capacity	10,000 ltr.	Provided	MR
15.	Exit Signage.	Daguirad	Denvided	MD
16.	Provision of Lifts.	Required	Provided	MR
		14.47.	1	
	a) Pressurization of lift	N/A	N/A	N/A
	shaft b) Programination of 1:0	27/4	27/4	
	b) Pressurization of lift	N/A	N/A	N/A
	c) Communication in lif	3 37/4	27/4	
		t N/A	N/A	N/A
	d) Fireman's switch	27/4	27/4	
		N/A	N/A	N/A
17.	e) Lift signage	N/A	N/A	N/A
	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
	A CONTRACT OF THE CONTRACT AND A CONTRACT OF THE CONTRACT OF T	- 000 miles		13/74

N	73
w.e.	

20.	Special Fire Protection System for Protection of special Risk, if any:			N/A NA
	e) Building floor plan	N/A	N/A	NI/A
	d) Battery backup	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
9.	Fire Control Room	N/A	N/A	N/A

The fire protection systems provided in the guest house building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if approved, we may **renew the Fire Safety Certificate** issued vide letter no. F6/DFS/MS/GH/NDZ/2022/508 dated 11/11/2022. Up to second floor only under rule 37 of the Delhi Fire Service rules 2010.

Signature of the Inspecting Officer
Name: - C.L.Meena

Designation: - ADO (RN)

1/2/25 Dycho (202)

RIV POPE

Principal Director

eta CFO to Sts

(at

- 10 M - 02/09/25

ADO(QN)

Ac approved F.T. letter is know for your signature Place. \_\_\_\_

CFO | Mugh 6/91 2005 56 19 2025 A DO (A)

Ms willanded (se