



Dated:- 22 04 2025

## FIRE SAFETY CERTIFICATE

Certified that the M/s. Hotel Southern Residency, located at 18/5, Arya Samaj Road, Karol Bagh New Delhi-110005, comprised of Basement + Ground + 04 Upper Floors, was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/GH/SZ/2022/285 dated 14/06/2022, for ground floor as office, first floor as reception, store & 07 guest rooms, second & third floor each having 07 guest rooms & 01 store respectively (total 21 guest rooms) having given an affidavit dated 22.04.2025 regarding not to use any floor above 3<sup>rd</sup> floor. The guest house was re-inspected by the officer concerned of this department on 15/04/2025 in the presence of Sh. Surya Rao (Manager) and found that the guest house management have deemed complied with the fire prevention and fire safety requirements in accordance with the Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises/building is fit for occupancy class "Residential" (guest house) first, second & third floor each having 07 guest rooms (Total 21 guest rooms only) with effect from 22 04 2025 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010 printed below.

Issued on 22 04 2025 at New Delhi by

Tel. No. 011-23414000

## Copy to:-

- 1. The Commissioner, Municipal Corporation of Delhi, Civic Centre, Minto Road, New Delhi-110002: in r/o computer id no. 2025032304345 dated 24/03/2025
- 2. The Joint Commissioner of Police (Lic), 1<sup>st</sup> Floor, Licensing Unit, Police Station, Defence Colony, New Delhi.
- 3. The Authorized Signatory, Hotel Southern Residency, 18/5, Arya Samaj Road, Karol Bagh, New Delhi-110005.

## Conditions for the validity of fire safety certificate:-

- No occupancy used above third floor and basement are separate from guest house shall be strictly adhered by Owner/Occupier.
- 2. All the means of escape shall be kept free of all type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.
- 5. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 6. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 7. All comments / directions of licensing Department shall always be permitted and followed.
- 8. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 9. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

ETION REPORT

Name & address of the building: M/s Southern Residency Guest House, located at 18/5, Arya Samaj Road, Karol Bagh, New Delhi-5

2. Type of Occupancy

: Lodging House, the said guest house building is comprised of basement + Ground + 04 Upper Floors, basement (other property), ground floor as office and 1st, floor as reception & 07 guest rooms,  $2^{nd}$  floor &  $3^{rd}$  floor each having 07 guest rooms & 01 store respectively (total 21 guest rooms only) given an affident de 13.10.18

3. Type of Case

: Renewal regarding bust to use any floor above 300 floor.

4. Details of previous NOC

: F6/DFS/MS/GH/SZ/2022/285 dated 14/06/2022

5. Fire Safety directives Letter No.

: N/A

Date of inspection

: 15/04/2025

7. Name of the Inspecting Officer

: Aman Kumar Lathar, ADO (JWP)

8. Name and designation of Officer

from the building side

: Sh. Surya Rao (Manager)

9. Year of Construction

: 2009

10. Applicant's online application no. : 2025032304345 dated 24/03/2025

S No	Minimum standards on fire prevention and fire safety U/R 33	Requirements Provided Existing fire safety site		Provided a site	at Remarks MR/NMR		
		arrangements					
1.	Access of building						
	Road width	06 m	N/A Directly accessible N/A N/A		MR		
	<ul> <li>Gate width</li> </ul>						
	<ul> <li>Width of internal road</li> </ul>				N/A		
2.	Number, width, Type & Arrangem						
1	a. Number of staircases						
	<ul> <li>Upper floors</li> </ul>	Old Case			MR being old cas		
	Basements	0110		l no.	MR being old case		
	b. Width of staircases				) (D		
		Upper floors Old Case 1.25 m				IR being old case	
	Basements			.0 m	MR being old cas		
	c. Protection of exits						
	Fire check door	Required	Provided		MR N/A		
	Pressurization	N/A N		V/A			
	d. No of continuous	01		01		MR	
	staircase to terrace	2.0 m	2.	10 m		MR	
	e. Width Of Corridor	1.0 m		.0 m		MR	
	f. Door Size	1.0 111					
3.	Compartmentation	Required	Pro	Provided		MR	
	Fire check door	Required	Se	ealed		MR	
	Sealing of electrical shafts	N/A	1	N/A		N/A	
	Fire Rating of shaft door	N/A	N	N/A		N/A	
	Water Curtain	N/A	N	N/A		N/A	
_	• Fire Dampers						
4.	Smoke managements System	Required	Exhaust Fan			MR	
	<ul><li>Basements</li><li>Upper floors</li></ul>	Required	Natur	ral Ventilation MR		MR	
5.	Fire Extinguishers						
1	Total numbers	10 nos.				MR MP	
	Types	ABC & CO <sub>2</sub>		Provided MR			
	IS marking	Required	Pro	vided		MR	

Total numbers on each of					
ools on each	1 00				
6 First Aller B	First All War D. I				
6. First – Aid Hose Reels	loor 01 n	Pro Pro	vided M		
• Total numbers on each f	20	10.	vided MR		
• Length of hose reel hose	05 m		vided MR		
<ul> <li>Nozzle diameter</li> <li>Automatic fire detection and ala</li> </ul>		110			
		me Provi	ded MR		
<ul><li>Type of detectors</li><li>Location of Main Panel</li></ul>	CO ty	F			
Location of Main Panel     Location of Repeater Panel	Requir				
Alternate source of power	1 1/1 1				
Hooters' Location	requi				
	N/A				
8. MOEFA 9. Public Address System	Requir				
Jacob System	Requir	red Provid	ed MR		
Sprinkler System			1 10		
Basements     University	Require				
• Upper Floor	N/A	N/A	N/A		
• Sprinkler above false ceiling	N/A	N/A	N/A		
11. Internal Hydrants:					
Size of riser/down-comer	37/4		37/4		
Number of hydronta par		N/A	N/A		
Number of hydrants per floor	N/A	N/A	N/A		
Hose Box	N/A	N/A	N/A		
12. Yard Hydrants	IVA	IV/A	IN/A		
Total number of hydrants	N/A	N/A	N/A		
<ul> <li>Hose Box</li> </ul>	N/A	N/A	N/A		
13. Pumping Arrangements:	1,111	11/11	IV/A		
Ground Level					
Discharge of main pump	N/A	N/A	N/A		
Head of main pump	N/A	N/A	N/A		
Number of main pumps	N/A	N/A	N/A		
Jockey pump out put	N/A	N/A	N/A		
<ul><li>Jockey pump head</li><li>Standby Pump out put</li></ul>	N/A	N/A	N/A		
Standby Pump Head	N/A	N/A	N/A		
> Auto Staring/Manual	N/A	N/A	N/A		
stopping	N/A	N/A	N/A		
➤ Pump House Access	N/A	77/4			
Terrace level	IN/A	N/A	N/A		
Discharge of pump	450 lpm	Descrided	1.00		
➤ Head of the pump	430 ipin 40 m	Provided	MR		
➤ Power supply	Required	Provided	MR		
➤ Auto starting of pump	Required	Provided Provided	MR		
14. Captive water Storage for fire fighting		1 Tovided	MR		
Under ground tank	N/A	N/A	N/A		
capacity	-		IV/A		
> Draw off connection	N/A	N/A	N/A		
➤ Fire service inlet	N/A	N/A	N/A		
> Access to tank	N/A	N/A	N/A		
Overhead Tank capacity	Old Case	6000 ltrs.	MR being old		
		T p	case		
15 Exit Signage	Required	Provided	MR		
16. Provision of Lifts		27/4	N.		
> Pressurization of Lift Shaft	N/A	N/A	N/A		
> Pressurization of lift lobby	N/A	N/A	N/A		
Communication in lift Car	N/A	N/A	N/A		
Fireman's Grounding	N/A	N/A	N/A		
Switch	NI/A	N/A	N/A		
➤ Lift Signage	N/A Paguired	Provided	MR		
17. Standby power supply	Required	Frovided	IVIK		
Tr. Standey			8		

N 13 18. Refuge Area N/A Total area N/A N/A N/A Location N/A N/A Fire control room Detector system panel N/A N/A N/A M Flow Switch Panel N/A N/A N/A M PA System Panel N/A N/A N/A M Battery backup N/A N/A N/A **Building Floor Plans** N/A N/A N/A MF Special Fire Protection Systems One ABC type MR Required for Protection of special Risks, if fire extinguisher N/A found provided any; MI near electrical N/. panel The fire protection systems provided in the building were checked and found M M functional at the time of inspection. Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no. F6/DFS/MS/GH/SZ/2022/285 dated 14/06/2022, renewal under rule 37 of the Delhi Fire Service Rule 2010, is recommended. Accordingly, DFA is put up for approval & signature please. Aman Kumar Lath ADO (JWP) Alt 1/00 x 11 + 1/37/ Director by management placed at C-41.

hy management placed at C-41.

Accordingly, for letter is find-up for approval a signaline, as case disposal date is 21.04.25.

Take a fish Afra

med male this in Aproval.

P.F.O. PS ( BIX AMERICAN)