



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/EH/2025/SZ/ 146

Dated: 24/04/2025

FIRE SAFETY CERTIFICATE

Certified that M/s **Hungry Heart Dinner** located at 40, Community Centre, Basant Lok, Vasant Vihar, New Delhi–110057, in a building comprised of Ground, Mezzanine & 03 upper floors but the restaurant running at mezzanine & first floor only, was issued fire safety Certificate by this department vide letter No. F.6/DFS/MS/EH/2022/SZ/124 dated 12/05/2022. The premises was re-inspected by the officer concerned of this department on dated 15/04/2025 in the presence of Sh. Uday Pandey and found that said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and found that the said premises is fit for occupancy class "Assembly Group—D" (Restaurant at Ground & Mezzanine floor only) with effect from 24/64/2025 for a period upto 31/03/2028 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

OTUL GARG)
DIRECTOR
Ph. 011-23414000

Copy to: -

- The Joint Commissioner of Police (Lic.), First Floor, Police Station Defence Colony, New Delhi–110049 (w.r.t. online Id. No. 2025040205383 dated 04/04/2025)
- 2. Authorized Signatory, M/s Hungry Heart Dinner located at 40, Community Centre, Basant Lok, Vasant Vihar, New Delhi–110057

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working conditions at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 5. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry.

N-31

	10	1			
	INSPECTIO	N REPORT			
1.	Name & address of the building	M/s Hungry Heart Dinner situated at 40, Community Centre, Basant Lok, Vasant			
	Tyma of Occumency	v mar, New De	elhi-110057		
2.	Type of Occupancy	Assembly, Group D (Eating House)			
3.	Building Comprised of	Ground + Mezzanine+ 03 upper floors only			
	Type of Case	out EH at Mez	zanine & 1st Floor	only.	
4.	• •	Renewal			
5.	Details of previous NOC No.	F6/DFS/MS/EH/2022/SZ/124 Dated 12/05/2022			
6.	Fire Safety directives Letter No.	F.6/DFS/EH/MS/2005/718 Dt. 04/04/2005			
7.	Date of inspection	15/04/2025			
8.	Name of the Inspecting Officer	ADO (SJ) As per direction			
9.	Name and designation of Officer	Sh. Uday Pandey			
10	from the building side Year of Construction				
10.		1990 (As per CAF)			
11.	Applicant's letter No./Online Appl	No. 2025040205383 dated 04/04/2025			
S. No.	Minimum standards on fire prevention and fire safety U/R 33	Requirement/ Existing Fire Safety Measures	Provided at site	Remarks MR/NMR	
1.	Access of building	Sarety Measures			
	Road width	4.5 mtr	Provided	MR	
	Gate width	N/A	N/A	N/A	
	Width of internal road	N/A	N/A	N/A	
2.	Number, width, Type & Arrangements	s of exits			
	a. Number of staircases				
	Upper floors	02 Nos	02 Nos	MR	
	Basements	N/A	N/A	N/A	
	b. Width of staircases				
	Upper floors	1.25m each	1.25m & 1m	MR (Old case	
	Basements	N/A	N/A	N/A	
	c. Protection of exits		,		
	Fire check door.	N/A	N/A	N/A	
	 Pressurization 	N/A	N/A	N/A	
	d. No of continuous staircase to terrace	Required	One	MR	
	e. Width of Corridor	N/A	N/A	N/A	
	f. Door Size	2 Nos	1.10m & 1m	MR (Old case	
3.	Compartmentation	N. 7. 1			
	Fire check door	N/A	N/A	N/A	
	Sealing of electrical shafts	N/A	N/A	N/A	
	Fire Rating of shaft door When Contains	N/A N/A	N/A N/A	N/A N/A	
	Water CurtainFire Dampers	N/A N/A	N/A N/A	N/A N/A	
4.	Smoke Managements System	- 1111	11/11	11/21	
7.	Basements	N/A	N/A	N/A	
	Upper floors	12 ACPH	Exh. fan provide		
5.	Fire Extinguishers				
J.	Total numbers	04 Nos	Provided	MR	
	• Types	ABC/CO ₂	ABC & CO ₂	MR	
	ISI marking	Required	Provided	MR	
6.	First-Aid Hose Reels	7	11011404	IVIK	
0.	Total numbers on each floor	One	Provided	M	
	 Length of hose reel hose 	30m	Provided	MR	
	Nozzle diameter	5mm		MR	
	TIOLES GIGINGO	Jiiiii	Provided	MR	

N-32

7.	Automatic fire detection and alarming sy	rstem.	N/A	N/A
	Type of detector	N/A		N/A
	 Location of Main Panel 	N/A	N/A	N/A
	 Location of Repeater Panel 	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A N/A
	Hooters' Location	N/A	N/A	
8.	MOEFA	Required	Provided	MR
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			
	Basements	N/A	N/A	N/A
	Ground/ Upper Floor	Required	Provided	MR
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants	•		
	Size of riser/down- comer	100 mm	Provided	MR
	Number of hydrants per floor	01 Nos	Provided	MR
	Hose Box	01 Nos	Provided	MR
12.	Yard Hydrants			
	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements			
	Ground Level			
	Discharge of main pump	N/A	N/A	N/A
	Head of main pump	N/A	N/A	N/A
	Number of main pumps Jockey pump out put	N/A	N/A	N/A
	Jockey pump out putJockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	➤ Auto Staring/Manual stopping	N/A N/A	N/A	N/A
	> Pump House Access	N/A	N/A N/A	N/A
	Terrace level	1771	IN/A	N/A
	Discharge of pump	450 LPM	Provided) (D
	Head of the pump	30m	Provided	MR
	Power supply	Required	Provided	MR
	Auto starting of pump	Required		MR
14.	Captive water Storage for fire fighting	required	Provided	MR
	Underground tank capacity	N/A	NI/A	
	> Draw of connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	> Access to tank	N/A	N/A	N/A
	Overhead Tank capacity		N/A	N/A
15	Exit Signage	5,000 ltrs	Provided	MR
16.	Provision of Lifts	Required	Provided	MR
	> Pressurization of Lift Shaft	N/A	37/	
	> Pressurization of lift lobby	N/A	N/A	N/A
	Communication in lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch		N/A	N/A
	Lift Signage	N/A	N/A	N/A
17.	Standby Power Supply	N/A	N/A	N/A
18.	Refuge Area	Required	Provided	MR
	> Total area	3. 77.4		
	> Location	N/A	N/A	N/A
	Location	N/A	N/A	N/A



Fire Control Room 19. Detector system panel N/A N/A N/A Flow Switch Panel N/A N/A N/A PA System Panel N/A N/A N/A Battery backup N/A N/A N/A Building Floor Plans N/A N/A N/A Special Fire Protection Systems for 20. N/A N/A N/A Protection of Special Risks, if any;

The fire protection systems provided in the building/premises were checked, tested at random and found functional at the time of inspection. In view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the fire safety certificate issued vide letter No. F.6/DFS/MS/EH/2022/SZ/124 dated 12/05/2022, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA/FT letter is put up for approval and signature please.

Earlier Isli's isqued for Merr. & Bignature of the Inspecting Officer
Name: Santosh Kumar
Designation: ADO (SJ)

Sir, Rechelled, cross regulared amended le Resulomitted please.