GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/EH/SZ/2025/380

Dated: 18 11 2025

FIRE SAFETY CERTIFICATE

Certified that the M/s In the Punjab (Unit of World of Shalom Restaurants Pvt. Ltd.) located at Plot No. 2, Ambience Mall, Nelson Mandela Marg, Vasant Kunj, New Delhi- 110070, running at third floor only in a building comprised of three tier basement, ground plus three upper floors, owned/occupied by a unit of World of Shalom Restaurants Pvt. Ltd. have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on dated 10.11.2025 in presence of Mr. Vikas (Manager), and the building/premises (third floor only) is fit for occupancy class "Assembly" (Restaurant) w.e.f 18/11/2025 for a period of three years, in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued on 18 11 2025 at New Delhi by.

Dy. Chief Fire Officer

Online Application id 2025092313663 dated 17.10.2025

Copy to: - The Executive Engineer (Building), MCD, Civic Centre, Minto Road, New Delhi. :- for information regarding use of basement.

Conditions for the validity of fire safety certificate: -

1. This FSC is valid only for third floor.

2. All the means of escape shall be kept free of all type of obstruction all the time.

3. All the employees shall be acquainted with the use and maintenance of all fire equipment's and method of smooth and speedy safe evacuation of occupants in case of emergency.

4. All the firefighting equipment's shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.

5. Any deviation, with regards to construction, ventilation, occupancy, electric installation

etc. may be got verified from the concerned authorities.

6. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.

7. Basement strictly shall be used as per BBL.

8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

9. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, six months prior

to its expiry.

INSPECTION REPORT

1. Name & address of the building

M/s In The Punjab unit of World of Shalom Restaurants Pvt.

Ltd. Located at 3rd floor Plot No. 02, Ambience Mall, Nelson

Mandela Marg, Vasant Kunj, New Delhi- 110070.

Building is comprised of Three tier basement, ground plus three upper floors (Restaurant

running third floor only)

3. Type of Occupancy Group D (Assembly) 4. Type of Case

New Case 5. Details of Previous NOC Nil

Fire Safety directives letter No Nil Date of inspection

10.11.2025 8. Name of Inspecting Officers A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side Sh. Vikas (Manager)

10. Year of Construction 2009 :

0.	Minimum Standards on fire prevention and fire safety U/R 33	Requirements	Provided at site	Remarks MR/NMR		
	Access to building FSC No. F6/DFS/MS/Mall/2023/SZ/35 dated 25.01.2023 of Ambiance mall					
	Road width	09 mtrs.	Provided	M/R		
	Gate width	5.0 mtrs.	Provided	M/R		
	Width of internal road	6.0 mtrs.	Provided	M/R		
	Number, Width, Type & Arrangement of Exits Provided & Maintained by Ambiance Mall					
	a. Number of staircases					
	Upper Floors	02 nos.	17 nos. provided	MR		
	Basements	N/A	As Above	N/A		
	b. Width of staircases	T. Benedictier of				
	Upper Floor	1.50 m	1.38 & 1.50 m	MR, old cas		
	Basements	N/A	As Above	N/A		
		Required	Provided	MR		
	c. Protection of exits	Required	Provided	MR		
	Fire check door Pressurization	Required	Tiovided	NAC.		
-	• Fressurization	n eligetara y eligi	Provided	MR		
	d. No. of continuous staircases to	Required N/A	N/A	N/A		
	e. Width of Corridor	1.50 m (2 no's)	Provided	MR		
	f. Door Size	Provided & Maintained by Ambiance Mall				
3.	Compartmentation Provided & Maintained by Amounte Main					
-	Fire check door	Required	Provided	MR		
	Sealing of electrical shafts Fire Rating of shaft door	Required	Provided	MR		
47		N/A	N/A	N/A		
5.	Water Curtain	N/A	N/A	N/A		
	Fire Dampers	N/A	N/A	N/A		
4.	Smoke Management System Provided & Maintained by Ambiance Mal					
	Basements	N/A	As Above	N/A		
	Upper floors	Required	Exhaust fans Provided	MR		
5.	Fire Extinguishers					
15	Table numbers in rectaurant	06 no.'s	Provided	M/R		
1	Total numbers in restaurant	ABC/CO ₂	Provided	M/R		
	Types IS marking	ISI marked	Provided	M/R		
	First-Aid Hose Reels		Provided & Maintained by	mbiance Mall		

N/G

		1 Nos.	Provided	M/R	
	Total numbers for restaurant	30 mtrs	Provided	M/R	
	Length of hose reel hose Nozzle diameter	5 mm	Provided	M/R	
	Automatic fire detection and alarming sys	tem in restaurant	(Provided & Maintained by A	mbiance Mall)	
7.		Heat & smoke	Provided	M/R	
	Type of detectors Smoke/Heat	Required	Provided	M/R	
	Location of Main Panel Location of Repeater Panel	N/A	N/A	N/A	
	Location of Repeater 1 and Alternate source of power	Required	Provided	M/R	
	Hooters' Location	Required	Provided	M/R	
		Required	Provided	M/R	
8.	MOEFA with talk back system	Required	Provided	M/R	
9.	Public Address System	Requires	Provided & Maintained by		
10.	Automatic Sprinkler System	F. 17			
	Basement	N/A	As Above Provided	N/A	
	Ground Floor at restaurant	Required		M/R	
	Sprinkler above false ceiling	Required	Provided	M/R	
11.	Internal Hydrants		Provided & Maintained by	Ambiance Mall	
	Size of riser/down-comer	150 mm	Provided	M/R	
	Number of hydrants	01	Provided	M/R	
	Hose Box	Required	Provided	M/R	
12.	Yard Hydrants Provided & Maintained by Ambiance M				
14.	Total number of hydrants	N/A	As Above	N/A	
	Hose Box	N/A	As Above	N/A	
13.	Pumping Arrangements		Provided & Maintained by	Ambiance Ma	
	Ground Level	700			
	➤ Discharge of main Pump	2280 LPM	4500 LPM	M/R	
	> Head of Main pump	70 mtrs	70 mtrs	M/R	
	> Number of main pumps	01nos	two	M/R	
	➢ Jockey Pump out put	180 LPM	450 LPM	M/R	
	➢ Jockey pump head	70 mtrs	70 mtrs	M/R	
		2280 LPM	4500 LPM	M/R	
	➤ Standby Pump out put ➤ Standby Pump Head	70 mtrs	70 mtrs	M/R	
	➤ Water curtain Pump	Required	Provided	M/R	
	> Auto Starting/Manual Stopping	Required	Provided	M/R	
	18 1.2	Required	Provided	M/R	
	▶ Pump House Access	-	1		
	Terrace level	Required	As Above	MR	
	Discharge of pump	450LPM	As Above	MR	
	➤ Head of the pump➤ Power Supply	40m	As Above	MR	
	➤ Auto Starting of pump	Required	As Above		
14.		Required	As Above	MR	
14.	Captive Water Storage for fire-fighting	Provid	ed & Maintained by Ambiance	Mall	
	Underground tank capacity for entire bldg.	1,00,000 ltrs	5,00,000liter	M/R	
	> Draw-off connection	Required	Provided	M/R	
	Fire service inlet	Required	Provided	M/R	
	Access to tank	Required	Provided	M/R	
7/1	Overhead Tank capacity	10,000 ltrs	20,000liter	M/R	
5.	Exit Signage.	Required	Provided		
6.	Provision of Lifts			MR	
-	Pressurization of Lift Shaft	1975	Provided & Maintained by A	mbiance Mall	
-	- Tressuitzation of Lift Snatt	N/A	As Above	N/A	

-	Pressurization of Lift lobby	N/A	As Above	N/A	
U/A	Communication In lift Car	N/A	As Above	N/A	
	Fireman's Grounding Switch	N/A	As Above	N/A	
	Lift Signage	N/A	As Above	N/A	
7.	Standby power supply	Required	Provided (DG set)	M/R	
8.	Refuge Area. Provided & Maintained by Ambiance Mall				
	> Total Area	N/A	As Above	N/A	
	> Location	N/A	As Above	N/A	
	Fire Control Room Provided & Maintained by Ambiance Mal				
9.	Fire Control Room		Provided & Maintained by A	mbiance Ma	
9.		N/A	Provided & Maintained by A As Above	mbiance Ma	
9.	Detector System Panel ,	N/A N/A			
9.		N/A	As Above	N/A	
9.	 Detector System Panel Flow Switch Panel PA System Panel Battery backup 	N/A N/A	As Above As Above	N/A N/A	
19.	 Detector System Panel . Flow Switch Panel PA System Panel 	N/A N/A N/A	As Above As Above	N/A N/A N/A	
20.	 Detector System Panel Flow Switch Panel PA System Panel Battery backup 	N/A N/A	As Above As Above As Above	N/A N/A N/A N/A	

The fire protection systems provided in the building were test/checked at random and found functional at the time of inspection.

Note: - Restaurant running at third floor only of a building comprised of three tier basements, ground plus three upper floors. Earlier, Ambiance Mall having separate FSC issued by this department vide letter No. F6/DFS/MS/Mall/2023/SZ/35 dated 25.01.2023.

If agreed in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the Rules, it is recommended to grant fire safety certificate under Rule 35 of Delhi Fire Service Act- 2007 & Rules- 2010.

Accordingly, DFA is put up for approval & signature please.

Signature of the Inspecting Officer

Name- R.K. Yadav Designation- ADO

DO (\$D) 18 37 - 14 11/25

Decity

frincipal Dington

my, cto

THIN SECTION