

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELIII FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/School/2025/NDZ/644

Dated: 14 /08/2025

To,

The Principal, Indal Memorial Public School, Main Road Kondli, Delhi - 110096.

Subject: - Regarding issuance of Fire Safety Certificate in r/o Indal Memorial Public School located at Main Road Kondli, Delhi - 110096.

Sir,

Please refer to your outdoor dairy No.3799 dated 16/07/2025 on the subject cited above. In this connection, it is to inform you that the site was visited by officer concerned of this department on dated 24/07/2025 in the presence of Mrs. Roshni Bhati (Principal) and observed that the shortcoming has still not complied with as issued by this department vide letter no. F6/DFS/MS/School/NDZ/2024/380 dated 04/07/2024 (copy overleaf).

In view of above, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,

VIRENDRA SINGH
CHIEF FIRE OFFICER
OCCUPATION

Enclosed: as above

Copy to: -

1. The Director of Education, MCD Civic Centre, Jawahar Lal Nehru Marg, New Delhi-110002.



Dated: 04/07/2024

To,

Mr. Deepak Singh (Manager), Indal Memorial Public School, Main Road, Kondli, Delhi - 110096.

Subject: - Regarding grant of Fire Safety Certificate in r/o Indal Memorial Public School located at Main Road, Kondli, Delhi - 110096.

Sir,

This has a reference to your outdoor dairy no. 2790 dated 11/06/2024, on the subject cited above. In this connection, it is to inform you that premises was inspected by the officer concerned of this department on 24/06/2024 in the presence of Mr. Deepak Singh (Manager), and observed that building comprised of ground plus two upper floors only.

## Following shortcomings were observed during time of inspection:

- 1. The Premises in not accessible to fire engines.
- 2. One staircases of width 1.10 meter are provided against the requirement of width 1.50 meter each.
- 3. The width of corridor is 1.40 meter against the requirement of 1.50 meters.
- 4. The class room door size is 0.90 meter against the requirement of 1.0 meter.
- 5. Fire Extinguisher not provided.
- First-Aid-Hose Reel not provided.
- 7. Fire pump of 450 LPM not provided.
- 8. Overhead tank not provided.
- 9. Exit signage's not provided in strategic location in the building.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully.

(ATVL GARG)
DIRECTOR
O/DELHI FIRE SERVICE

Copy to:1. The Dy. Director of Education, MCD, Udyog Sadan, Plot No. 419, FIE, Patparganj, Delhi - 110092.