



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No.F6/DFS/MS/2025/026

Dated 14/01/2025

FIRE SAFETY CERTIFICATE

Certified that the M/s India International Centre located at 40 Max Mueller, New Delhi-110003 comprised of Basement (Services only). Ground floor (reception + 28 rooms & eating house), 1st floor (35 rooms + eating house), 2nd floor (16 rooms) total 79 guest rooms only owned/ occupied by M/s India International Centre was issued fire safety certificate vide letter no. F6/DFS/MS/SZ/2021/636 dated 27.12.2021. The premises was inspected by the officer concerned of this department on 06.01.2025 in the presence of Sh. Naresh Aggarwal (JE. Civil) and observed that all the fire prevention and fire safety requirements provided in the premises found good working condition. The premises have therefore, deemed complied with Rules 33 of the Delhi Fire Service Rules, 2010 and building premises is fit for occupancy class "Mixed (Guest House & Eating House) with effect from 14/01/2025 and valid up to 31/03/2028, in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ... 14/01/2025 ... at New Delhi by

Ph: 011-23414000

Copy to:-

- 1. The Commissioner, Municipal Corporation of Delhi, to ensure the occupancy as detailed above deviation and if any.
- 2. Online ID No- 2023040304989 dated 01.01.2025.
- 3. M/s India International Centre located at 40 Max Mueller, New Delhi-110003.

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape shall be kept free from any type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipment and method of smooth and speedy safe evacuation of occupants in case of emergency

3. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seem during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities. This Fire Safety Certificate is valid only for permanent building structure as per plan.

5. This fire safety certificate may not be treated in any case of regularizations of unauthorized construction/unauthorized use of land or activities, if any.

6. The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on the official website of Delhi Fire Service i.e. www.dfs.delhigovt.nic.in.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the MHA portal along with a copy of this Certificate, six months prior to its expiry".



1			1/20	आ त् उ	गादी का समृत महोत्सर		
	Na	me & Address of the Building	TION REPORT				
1		Type of Occupancy M/s India International Centre at 40 Max M Marg, New Delhi 110002					
2	Ty	elbi 110002	Max Muelle				
$\frac{2}{3}$	Bu	pe of Occupancy ilding Comprised of	Marg, New Delhi 110003. Mixed Occupancy (Rooming or Lodging & Eating Ho				
,	1	and combitsed of	02 Interconne	cted blank Bulleting &	Eating House)		
	T	pe of Case	Floors,	cted block, B+G+01 &	B+G+02 upp		
4	D	tails of Previous NOC	Renewal				
5	E	Sefet Di	F6/DFS/MS/SZ/2021/636 dated 27.12.2021				
6_	P	e Safety Directives Letter No	F6/DFS/MS/BP/04/1059 dated 27.12.2021				
7_	Da	te of Inspection	F6/DFS/MS/BP/94/1058 dated 19.07.1994 06.01.2025				
8	Name of the Inspecting Officers		ADO (RN)				
9	Name & Designation of Officers		Mr. Naresh Aggarwal (JE. Civil)				
	from the building side		THE PROPERTY AND ASSESSED ASSESSEDA				
10	Year of construction 1960 [Admin BK: Basement (Cafeteria), GF(Library &Office FF (Kitchen & Dining Hall) & Hostel BK: Basement (Service GF (Reception+28 rooms & Eating house), FF (35 rooms+ eating house), SF (16 rooms). Total 79 Guest Rooms						
11	Applicant letter online ID. MHA Portal ID No- 2023040304989 dated 01.01.						
S. No.	Mi	nimum standards on Fire Prevention	Requirement		Remarks		
0194	and Fire Safety U/R 33		per Rules 35	(6) Site	MR/NMR		
1	Ac	cess to Building.		1 00	1/D		
1		Road width	Required	08m	MR NA		
(-	Gate width	NA	NA NA	NA NA		
		Width of internal road	NA	NA	INA		
2		mber, width, type & arrangement of e	xits.		0 -		
1	a)	Number of Staircase					
1 .=	1	> Upper floors.	Required	Admin BL, 02+01 ramp	MR		
3	1	Opper fields.		Hostel BK, 04	MR		
1	1 (M)	> Basement floor.	Required	02 nos	IVIIC		
n William	b)	Width of Staircase		*	5m MR		
	Admin BI, 150m, 1.25m & 1.35m						
	111	Upper floors	1.25m	Hostel BK, 1.37m each, 1.15m o	82		
	101	> Basement floor	1.25-	1.50m & 1.25m	MR		
	···		1.25m	110 0.11			
	c)	Protection of exits	57/4	N/A	N/A		
	1.3	> Fire check door	N/A	N/A	N/A		
	1151	> Pressurization	N/A	Provided	MR		
	d)	No. of continuous staircase to terrace	Required	N/A	N/A		
	e)	Width of corridor	N/A	N/A	N/A		
	f)	Door size	N/A	N/A	1		
					MR		
3	Co	partmentation.	Required	Provided			
1	1.27	Fire check door.	N/A	N/A	N/A		
- 5		Sealing of electrical shafts.	N/A	N/A	N/A		
	1	Fire rating of shaft door.	N/A	N/A	N/A		
	1 4	• Water curtain	N/A	N/A	N/A		
	13	Fire dampers.	IN/A	- Commence			
4	Ç,	oke Management system.		i i jeli	1 100		
	311	INVO MININGS	Required	Exhaust fan	MR		
		Basement	Required	Natural Ventilation	MR		
	, V	• Upper floors	Required				
5	Fir	e Extinguishers.		20Nos	MR		
	- 1	Total numbers	Required	Provided	MR		
	110	Types	ABC/W.Co ₂	Provided	MR		
	1	ISI Marking	Required	FIOVIDE			
6	E	rst Aid Hose Reels.	V.	- monarcal - 1	MR		
-	Ę.L	The state of the s	02nos.	Provided	MR		
3	- 1	Total numbers on each floor.	30m	Provided	MR		
	(a)	Length of hose-reel hose.	5mm	Provided	IVIN		
7		Nozzle Diameter	<i>y</i>		181 12		
4	A	natic fire detection & alarming system.		a market	MR		
	1 1	T. C.	Required	Smoke/Heat	MR		
		Type of detectors	Required	Ground Floor	N/A		
	100	Location of Main Panel		N/A			
2		And the same of th	· N/A		100		
1	31	Location of Repeater Panel	N/A Required	Provided	MR		
1	- 31	And the same of th	N/A Required All floor		MR MR		

				10	
	and Saulik	MRI			
8	MOEFA			10	
9	Dublic All	Required	Provided	MR	
111	Public Address System	Required	Provided	MR	
10	Automatic Sprinkler System	- aquirou	Flovided		
	Basement			3.00	
	Upper floors	Required	Provided	MR	
		N/A	N/A	N/A	
11	Sprinkler above false ceiling Internal Hydrants.	N/A	N/A	N/A	
::::::::::::::::::::::::::::::::::::::				The second	
	 Size of Riser/Down-comer 	Required	Provided	MR	
	 Number of Hydrant per floor 	02 Nos	Provided	MR	
	 Hose box. 	02 Nos	Provided	MR	
12	Yard Hydrants.	- 1103	Flovided	11 11	
	Total number of hydrants.			MR	
	Hose box.	Required	04 Nos	MR	
13	Pumping arrangements.	Required	04 Nos	IVIK	
W.				1 31 11	
	Ground Level Discharge of main nump	Fire fighting sys	tem is common for	entire complex	
	Discharge of main pump.Head of main pump.	2280 LPM	Provided	MR MR	
	Number of main pumps.	75m	Provided	MR	
	> Jockey Pump output.	02 180 LPM	Provided	MR	
	Jockey Pump head.	75m	Provided Provided	MR	
	Standby Pump output.	2280 LPM	Provided	MR	
	> Standby Pump head.	75m	Provided	MR	
	Auto Starting/Manual Stopping. Pump house access	Required	Provided	MR	
	amp nouse access.	Required	Provided	MR	
	Terrace Level		em is common for o	entire complex	
	Discharge of pump.	900 LPM	Provided	MR	
	Head of pump.Power supply.	35m	Provided	MR MR	
	Auto starting of pump.	Required Required	Provided Provided	MR	
14	Captive water storage for fire fighting.				
#320 					
	 Underground tank capacity. Draw-off connection. 	50,000 Ltrs Required	Provided	MR	
	> Fire Service Inlet.	Required	Provided	MR	
	> Access to tank.	Required	Provided	MR	
	Overhead tank capacity.	20,000 Ltr	Provided	MR	
15	Exit Signage.	Required	Provided	MR	
6	Provision of Lifts.			The Reserve	
U	The state of the s	NT/A	NI/A	27/4	
	Pressurization of lift shaft.	N/A	N/A	N/A	
	Pressurization of lift lobby.	N/A	N/A	N/A	
	Communication in lift car.	N/A	N/A	N/A	
- 10	Fireman's switch.	Required	Provided	MR	
-	Lift signage.	N/A	N/A	N/A	
7	Standby Power Supply	Required	Provided	MR	
8	Refuge Area				
	Total area	N/A	N/A	N/A	
	Location	N/A	N/A	N/A	
-	• Location Fire Control Room.			ISTA	
9	FIIE CORE OF KOOM.			1.	
-	Detector system panel.	N/A	N/A	N/A	
N	Flow switch panel.	N/A	· N/A	N/A	
		N/A	N/A	N/A	
	PA system panel.	N/A	N/A	N/A	
	Battery backup.	N/A	N/A	N/A	
	Building floor plan.			IVA	
-+	ocial Fire Protection System for the N/A			N/A	
)	Protection of special Risk, if any.				



The fire protection systems provided in the building were tested/ checked and found in working order at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to renew Fire issued vide department letter of even no. this F6/DFS/MS/SZ/2021/636 dated 27.12.2021 under rule 37 of the Delhi Fire Service

> Signature of the Inspecting Officer Name: - C.L. Meena

Designation: Asst. Div. Officer (RN)

As appeared, f. E. Stetter is put up for signature
please.

Discutor, DFSMh

Discutor, DFSMh