



No. F6 /DFS/MS/Mixed/SZ/2026/ 222

Dated: 01/10/2026

FIRE SAFETY CERTIFICATE

Certified that the M/s Sharada Institute of Indian Management Research Foundation of Jagadguru S.M.S at 7, Institutional Area, Phase-II, Vasant Kunj, New Delhi, was granted Fire Safety Certificate by this department vide letter no. F6/DFS/MS/2025/SZ/87 dated 19/02/2025 for Education Block- Ground + 02 upper floors in the building comprised of Basement + Ground + 05 upper floors. The building was re-inspected by officer concerned of this department on 09/09/2026 in the presence of manager and found that the Institute is now running on Basement + Ground + 05 upper floors and the building has complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises/building is fit for occupancy of Group- B (Educational) with effect from 01/10/2026 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire Service Rules, 2010 printed below.

Issued on 01/10/2026 at New Delhi by


(A.K. Malik)
Chief Fire Officer
Delhi Fire Service

Copy to:-

1. The Joint Director, (L &I) DDA, Building Section, Vikas Sadan, INA, New Delhi.
2. Sharada Institute of Indian Management Research Foundation of Jagadguru S.M.S at 7, Institutional Area, Phase-II, Vasant Kunj, New Delhi

Conditions for the validity of Fire Safety Certificate

1. All the means of escape shall be kept free of all the type of obstruction all the time.
2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
5. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.
7. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

INSPECTION REPORT					
1	Name & address of the building		Sri Sharada Institute of Indian Management Research Foundation of Jagadguru S.M.S located at 7, Institutional Area, Phase-II, Vasant Kunj, New Delhi.		
2	Building is comprised of		Education Block- Basement + Ground + 05 upper floors		
3	Type of occupancy		Educational		
4	Type of case		Fresh (FSC already issued B, G + 2 upper floor)		
5	Details of previous FSC		F6/DFS/MS/2025/SZ/87 dated 19/02/2025 for Ground + 02 upper floors		
6	Fire safety direction letter no.		F6/MS/DFS/BP/2022/86 dated 14/01/2002		
7	Date of inspection		09/09/2026		
8	Name of the inspecting officers		Rajesh Kumar Shukla, ADO (Jangpura)		
9	Name of the designation of officer From the building side		Manager		
10	Year of construction		2001 & 2017		
11	Applicant's letter no.		DFS online portal application ID no. 52026081705078		
S. No	Minimum standard of Fire Prevention and Fire Safety U/R 33		Requirements	Provide at site	Remarks MR/NMR
1	Access to Building				
	A	Road width	9.0 m	Provided	MR
	B	Gate width	6.0 m	Provided	MR
	C	Width of internal roads	6.0 m	Provided	MR
2	Number, Width, Type & Arrangement of Exits				
	A	No. of staircase:			
		a) Upper floor	01 SC G to FF 02 Nos. Gr to Terrace	Provided	MR
		b) Basements	2 Nos. + 2 Ramp	Provided	MR
	B	Width of the staircase:			
		a) Upper floors	1.50 m	Provided	MR
		b) Basements	1.50 m & 2.0 m	Provided	MR
	C	Protection of Exits			
		a) Fire check door	Required	Provided	MR
		b) Pressurization	NA	NA	NA
	D	No. of continuous staircase to terrace:	02 Nos.	Provided	MR
	E	Width of the corridor	1.50 m	Provided	MR
	F	Door size	1.0 m	Provided	MR
3	Compartmentation:				
	A	Fire Check doors	Required	Provided	MR
	B	Sealing of horizontal & vertical opening	Required	Provided	MR
	C	Fire rating of shaft doors	Required	Provided	MR
	D	Water curtain	NA	NA	NA
	E	Fire dampers	NA	NA	NA
4	Smoke Management System:				
	A	Basements	Required	Provided	MR
	B	Upper floors	Required	Provided	MR
5	Fire Extinguishers				
	A	Total numbers	25 no.	25 no.	MR
	B	Types	CO ₂ , ABC	CO ₂ , ABC	MR
	C	ISI marking	Required	Provided	MR

✓ 

6	First Aid Hose Reel			
	A	Total no. at each floor	02 nos. at Basement, Ground and 1 st floor. 01 No. required at other upper floors	Provided MR
	B	Length of hose reel	30 mtrs	Provided MR
	C	Nozzle diameter	5 mm	Provided MR
7	Automatic Fire Detection and Alarm System (ADAS)			
	A	Type of detectors	Smoke & Heat	Provided MR
	B	Location of main Panel	At ground	Provided MR
	C	Location of repeater panel	NA	NA NA
	D	Alternate power source	Required	Provided MR
	E	Hooter's location	Should be audible in entire building	Provided MR
8	MOEFA		Required	Provided MR
9	Public Address System		Required	Provided MR
10	Automatic Sprinkler System			
	A	Basement	Required	Provided MR
	B	Upper floor	NA	Provided NA
	C	Sprinklers above false ceiling	NA	NA NA
11	Internal Hydrants			
	A	Size of the riser/down comer	100 mm	Provided MR
	B	No. of hydrants per floor	02 nos.	Provided MR
	C	Hose box	02 nos.	Provided MR
12	Yard Hydrants			
	A	Total no. of hydrants	Required	Provided MR
	B	Hose box	Required	Provided MR
13	Pumping Arrangements			
	A	Ground Level		
		a) Discharge & head of main pump	1620 LPM & 70 m	1620 LPM & 70 m MR
		b) Number of main pumps	02 Nos.	01 No. MR
		c) Discharge & head of jockey pump	180 LPM & 70 m	Provided MR
		d) Discharge & head of Standby pump	1620 LPM & 70 m	1620 LPM & 70 m MR
		e) Auto starting/ manual stopping	Required	Provided MR
	B	Terrace Level		
		a) Discharge of terrace pump	Required	900 LPM MR
		b) Head of terrace pump	Required	Provided MR
		c) Alternate power supply	Required	Provided MR
		d) Auto starting of pump	Required	Provided MR
14	Captive Water Storage for Fire Fighting			
	A	Underground tank capacity	50,000 Ltrs	Provided MR
	B	Draw off connection	Required	Provided MR
	C	Fire Service Inlet	Required	Provided MR
	E	Access to tank	Required	Provided MR
	D	Overhead tank capacity	20,000 Ltrs	20,000 ltrs MR
15	Exit Signage		Required	Provided MR

la

16	Provision of lift			
	A	Pressurization of lift shaft	NA	NA
	B	Pressurization of lift lobby	NA	NA
	C	Communication in lift car	Required	Provided
	D	Fireman switch	Required	Provided
	E	Lift signage	Required	Provided
17	Standby Power Supply		Required	Provided
				MR

18	Refuge Area			
	A	location	NA	NA
	B	Total area	NA	NA

19	Fire Control Room			
	A	Fire Detection System panel	Required	Provided
	B	Flow switch panel	Required	Provided
	C	P A system panel	Required	Provided
	D	Battery backup	Required	Provided
	E	Building floor plan		Provided
				MR

20	Special Fire Protection for special risk if any			
	A	Special Fire Protection system for Protection of Special Risk, if any:	Required for HT/LT panels	Provided CO ₂ flooding system provided
				MR

LEGENDS:- Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided but Not Functional (PNF), Not Provided (NP).

Note: Previous Fire Safety Certificate was issued vide letter no F6/DFS/MS/2025/SZ/87 dated 19.02.2025 to Building/Institute for Basement + Ground + 02 upper floors in the building comprised of Education Block Basement + Ground + 05 upper floors but the now the Institute is running on the existing building of comprised of Basement + Ground + 05 upper floors and fire safety arrangements i.e Sprinklers, pumping arrangements and water tank have been provided as per approval at N/5 & 6. Further, FSC issued vide letter no. F6/DFS/MS/2025/SZ/87 dated 19/02/2025 (B+G+2 upper floor) shall stand null and void.

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

If agreed to the note above & in view of the substantial compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC is recommended to be issued under Rule 35 of the Delhi Fire Service Rules 2010.

15/9/22

Signature of the Inspecting Officer
Name Rajesh Kumar Shukla
Designation ADO (Jangpura)

DO (SD) *15/9/22*

Ravinder Singh

15/9/22

16/9/22

Go to three. 10/2/218

fr. Dr.

Go to three

24/9/22
A.K. MALIK
20/9/22