C-67



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. F6/DFS/MS/Hospital/2025/NDZ/ 39

Dated: 20/01/2025

FIRE SAFETY CERTIFICATE

Certified that the Jain Hospital located at 177-178, Jagriti Enclave, Vikas Marg Extn. Delhi-110092, comprised of basement, ground plus three upper floors, owned/occupied by Jain Hospital was inspected by the officers concerned of fire service on 13/01/2025 in the presence of Dr. Sangeeta Jain (Director) and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have complied with rule 33 of Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class 'Institutional. (Class "C") with effect from 2.9/01/2025... for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010 & also conditions printed below.

Issued on 20/01/2025... at New Delhi by

DIRECTOR DELHAFIRE SERVICE

To.

Dr. Sangeeta Jain (Director)
M/s Jain Hospital at 177-178, Jagriti Enclave, Vikas Marg Extn. Delhi-110092

Copy:-

 The Directorate of Health Service, M.O. I/C Nursing Home Cell, Govt. of NCT of Delhi atF-17, Karkardooma, Delhi-i 10032

2. The Executive Engineer (Bldg.), Municipal Corporation of Delhi, Plot no. 419, Patparganj Ind. Area, Delhi-110092. :- for information & use of building including basement at their end.

Conditions for the validity of Fire Safety Certificate

1. All the means of escape shall be kept free of all type of obstruction all the time.

All the employees shall be acquainted with the use and maintenance of all fire equipment and method of smooth and speedy safe evacuation of occupants in case of emergency.

 All the fire fighting equipment shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.

4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.

5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.

 The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

7 The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry.
 8. Presently basement is being used for OPD/Lab. Etc. purposes.

1. Name & address of the building

: Jain Hospital,

177-178, Jagriti Enclave, Vikas Marg Extn. Delhi-92

2. Building is comprised of

: Basement + Ground plus three upper floors

(two separate building only connected in the basement)

Type of Occupancy

: Institutional Building

3. Type of Case

: New

4. Details of Previous FSC letter

: Nil

5. Fire Safety directive letter No

: Delhi Fire Service Act, 2007 and Rules 2010

6. Date of Inspection

: 13/01/2025

7. Name of the Inspecting officers

: ADO (Shah.), Deepak Kumar

8. Name and designation of officer

from the building side

: Dr. Sangeeta Jain (Director)

9. Year of construction

: 2000

10. Applicant's letter No

: outdoor diary No. 11079 dated 06/01/2025

Sr. No.	Minimum Standards on Fire Prevention and Fire Safety U/R3	Requirement as per inspection report dt 25/04/2016	Provided at Site	Remarks MR/NMF				
01	1 Access to Building.							
	Road width	12 mtr.	18 mtr.	MR				
	Gate width	N/A	N/A	N/A				
	Width of internal road	N/A	• N/A	N/A				
02	Number, Width, Type and Arrangement of Exits.							
	a. Number of Staircases		(Property no. 178)					
	Upper floor	02 nos.	02 nos.	MR				
2	Basement	02 nos.	02 nos.	MR				
	B. Width of Staircases							
	Upper floor	02 mtr.	02 mtr 1.50 mtr	MR				
	Basement	02 mtr.	02 mtr 1.50 mtr	MR				
	c. Protection of Exits							
	Fire check door	Required	Provided	MR				
	Pressurization	N/A	N/A	N/A				
	d. No. of Continuous Staircases to Terrace	01 no.	01 no.	MR				
	e. Width of Corridor	N/A	N/A	N/A				
_	f. Door Size	02 mtr.	, 02 mtr.	MR				
03-	f. Door Size 02 mtr 02 mtr. MR Compartmentation							
	Fire check door	Required	Provided	MR				
	 Sealing of electrical shafts 	N/A	N/A	N/A				
	 Fire rating of shaft door 	N/A	N/A	N/A				
- 1	 Water curtain 	N/A	N/A	N/A				
	 Fire dampers 	N/A	N/A	N/A				
)4	Smoke Management System.							
	Basement	30 a/c per hour	Provided	MR				
	Upper floor	12 a/c per hour	Ventilated	MR				
)5.	Fire Extinguishers.							
	Total numbers	10 nos.	12 nos.	MR				
	 Types 	ABC /CO ₂	ABC /CO ₂	MR				
	 IS marking 	ISI marked	ISI marked	MR				

	Total numbers on each floor	01 No.	01No.	MR			
	Length of hose reel hose	30 mtr.	30 mtr.	MR			
	Nozzle diameter	05 mm	05 mm	MR			
7	Automatic Fire Detection and Alarming Sys		10 10 10				
	Type of detectors	Smoke/Heat	Provided	MR			
	Location of main panel	Near Staircase	Provided	MR			
	Location of repeater panel	Required	Provided	MR			
	Alternate source of power	N/A	N/A	N/A			
	Hooter's location	N/A	N/A	N/A			
08	MOEFA	Required	Provided	MR			
09	Public Address System.	Required	Provided	MR			
10	Automatic Sprinkler System.						
		5 - 1 - 4	Provided	MR			
	Basement	Required	N/A	N/A			
	upper floor prinklar above false sailing	N/A N/A	N/A	N/A			
11	sprinkler above false ceiling Internal Hydrants	N/A	IN/A	13//3			
	size of riser/down-comer	100 mm	100 mm	MR			
	Number of hydrants per floor	01 no.	01 no.	MR			
	Hose box	01 no.	01 no.	MR			
12	Yard Hydrants.	31,110		- 0			
	Total number of hydrants	N/A	N/A	N/A			
	Hose box	N/A	N/A	N/A			
13	Pumping Arrangements.						
	> Ground Level	81 A VI. I					
	Discharge of main pump	N/A	1620 lpm	MR			
	Head of main pump	N/A	70 mtr	MR			
	Number of main pumps	N/A	01 no.	MR			
	Jockey pump out put	N/A	180 lpm	MR			
	Jockey pump head	N/A	70 mtr	MR			
	Standby pump out put	N/A	N/A	N/A			
	Standby pump head	N/A	N/A	N/A			
	Auto starting /manual stopping	N/A	Provided	MR			
	Pump house access	N/A	N/A	N/A			
	> Terrace Level						
	Discharge of pump	900 lpm	900 lpm	MR			
	Head of the pump	40 M	40 M	MR			
	Power supply	Required	Provided	MR			
	Auto starting of pump	Required	Provided	MR			
	Captive Water Storage for Fire Fighting.						
14	Captive Water Storage for Fire Fighting.			1			
14	Captive Water Storage for Fire Fighting. Underground tank capacity	N/A	70,000 ltr.	MR			
14		N/A	N/A	MR N/A			
14	Underground tank capacity	N/A N/A	N/A N/A	N/A			
14	Underground tank capacity Draw-off connection	N/A N/A N/A	N/A N/A N/A				
14	 Underground tank capacity Draw-off connection Fire service inlet 	N/A N/A	N/A N/A	N/A N/A			





123,

16	Provision of Lifts.	(Property no. 178)				
10 —	Pressurization of lift shaft Pressurization of lift lobby	Required N/A	Provided	MR		
		100000000000000000000000000000000000000	N/A	N/A		
	Communication in lift car	Required	Provided	MR		
	 Firemen's grounding switch 	Required	Provided	MR		
	 Lift signage 	Required	Provided	MR		
17	Standby Power Supply	Required	Provided	MR		
18	Refuge Area.					
	Total area	N/A	N/A	N/A		
	 Location 	N/A	N/A	N/A		
19	Fire Control Room					
	Detector system panel	N/A	N/A	N/A		
	Flow switch panel	N/A	N/A	N/A		
	PA system panel	N/A	N/A	N/A		
	Battery backup	N/A	N/A	N/A		
	Building floor plans	N/A ·	N/A	N/A		
20	Special Fire Protection systems for protection of special Risks, if Any:	N/A	N/A	N/A		

Note:- Property no. 177 under renovation, due to which the inspection could not carried or & owner gives an undertaking that we will inform the department after the renovation work.

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection. The shortcoming issue vide letter no. F.6/DFS/MS/Hospital/NDZ/2025/13 dated 06/01/2025 has been rectified now.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rule. It is recommended to grant Fire Safety Certificat under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name

:- Deepak Kumar

Designation

:- ADO (Shah.)

15/01/2025

Dy 040 (102)

C.F.O. | Mugh

ined the Line

Orrings

RIVE

ADO (ghal.) mscell