

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No: F.6/DFS/MS/Buisness/2025/SZ/ 332

Dated: 09/07/2025

To,

S.S. Sharma (President),  
Jaina Tower- I, Plot No. 3,  
District Centre, Janakpuri, New Delhi- 58.

Sub:- Regarding renewal of FSC in r/o M/s Jaina Tower- 1 at Plot No. 3, District Centre, Janak Puri, New Delhi- 110058

Sir,

This has reference to your letter No. Nil, dated 13.06.2025, on the subject cited above. In this connection this is to inform you that officer concerned of this department inspected the premises/building on dated 28.06.2025 to verify the fire safety arrangements in accordance with the rules. At the time of inspection Sh. S.S. Sharma (President), was present and it was observed that the building comprised of basement, ground plus eight upper floors, and have following shortcomings were observed:

1. First aid hose reel provided but found not functional.
2. Hydrant system provided but found not functional.
3. Underground pumps provided as per requirements but found not in working condition.
4. Overhead tank found in damage condition and it needs repair.
5. The electric wires are found not fixed properly and its going through passage.

In view of above shortcomings, the application for renewal of Fire Safety Certificate is rejected. You are requested to rectify the above-mentioned shortcomings under intimation to this department for taking further necessary action in this matter.

Yours faithfully,

(Atul Garg)  
Director  
Delhi Fire Service

Copy to: -

- 1 The Chairman, DDA, Vikas Sadan, INA, New Delhi- 110003.
- 2 The Executive Engineer (Bldg.), MCD, Civic Centre, Minto Road, New Delhi.