

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001



No F 6/DFS/MS/2025/EH/WZ/ 399

Dated: 28/11/2025

FIRE SAFETY CERTIFICATE

Certified that the M/s Januar The Heaven (A Unit of Shree Shyam Enterprises) located at Unit No. 202 to 217, 2nd floor, Manglam Place Manglam Paradise Mall, Sector 3, Rohini, Delhi-110085 is running in the Mall 2nd floor comprised of Basement, Ground plus Five upper floors was issued FSC by this department vide letter No F6/DFS/MS/2023/WZ/EH/53 dated 07.02.2023. The premise was re-inspected by the officer concerned of this department on 15.11.2025 in the presence of Mr. Rajbir Singh and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have therefore deemed complied with fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premise is fit for occupancy class "Assembly" (Group D) Eating House for Unit No. 202 to 217, 2nd floor with effect from ... 28(11/202).... for a period of three years in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40, subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ... 28. 1. 2025...... at New Delhi, by

Dy. Chief Fire Officer West Zone

our

Copy to: -

- 1. The Commissioner, MCD, Delhi:- to ensure the occupancy as detailed above and deviation if any.
- 2. M/s Jannat The Heaven (A Unit of Shree Shyam Enterprises) located at Unit No. 202 to 217. 2nd floor, Manglam Place Manglam Paradise Mall, Sector 3, Rohini, Delhi- 110085.
- 3. MCD Portal, ID No. 2025103014490.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate through MCD portal (https://www.mcdonline.nic.in) along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

	-		11111	N-16	7				
Г	Nama &	addraga of the 1 11 11	INSPECTION	REPORT	v.				
	1. Name &	address of the building : N	VI/S Jannat The Hear	ton / A TT			T. 14 N.T.		
			202 to 217, 2 nd Floo	r, Mangla	nit of Shree Shyam Enterp am Palace, Manglam Para	orises) U	Init No.		
100	2. Type of	pecupaticy .	Rohini, Delhi- 1100	85.	, mangiam rara	uisc ivia	11, 366. 3,		
	Building	Comprised of .	Manglam Day 1	ly Buildin	g (Eating House).				
I.	Type of 0	Case :		VIAILIRA	101111111111111111111111111111111111111	upper f	loors)		
	 Details o Fire Safe 	Previous NOC			ing at 2 nd floor only) /53 Dated- 07/02/2023				
1	7 Date of i	ty directives letter No	F6/DFS/MS/BP/2	2008/1100	Dated- 16/04/2008				
	7. Date of in	Inchest' Oca	13/11/2025						
Ç	9. Name an	d designation of officers	R.K.Sinha, ADO	(Jawala P	'uri)				
	From the	building side . Mr. Baiking in 1							
9	Year of C	Construction 2011 as per MCD Postel							
	Applican	t's letter No.	MCD Application	ID No. 2	025103014490 dated 30	/10/202	5		
S.	Minimum	Standards on fire	Requirements as	s per	Provided at site		marks		
No.	prevention	and fire safety U/R 33	Rule 35 (6) of DF	SAct		MI	R/NMR		
1.	Access to	,	Paradise Mall, Man	glam Pla	ce, Distt. Centre Rohini,	Sec-3,	FSC issued		
	Road widtl	Vide Letter	no. F6/DFS/MS/202	5/WZ/36	7 Dated 03/07/2025)				
	Gate width		Accessib		Accessible		MR		
-		nternal road	Accessib	e	Accessible NA		MR NA		
2.		Width, Type & Arrangen	NA NA	l katikua	nd maintained by Mall 1	nanage	AIDSTANS 4		
	in the same same	Arrangen	ient of Exits (Fi	ovided al	nd maintained by Man	nanage	шенту		
	Number of	staircases							
	Upper Floo	ors	02 s/c	Provid	ded (as per mall inspection note)		MR		
	Basements		NA		NA	*	NA		
	Width of st								
	Upper Floo		1.5 m ea	ch	Provided		MR		
	Basements		NA		NA NA		NA		
	Protection		WCMAN, III						
	Fire check	200000000000000000000000000000000000000	Require	d	Provided		MR		
	Pressurizat				-		-		
		tinuous staircases to			As per mall				
	terrace		Commence Co.		e chideni Strin - 4 M - 1		128		
	Width of C		2 m		2 m × 1 & 1.5 m × 1		MR		
	Door Size		1 200						
3.	Compartm	entation	IN THE RESERVE TO THE						
500	Fire check	door	Required		Provided		MR		
		lectrical shafts	Required	lj.	Provided		MR		
	Sealing of C	of shaft door	Required	-	As per mall		MR		
	Water Curta	ain	Suul	u k					
	Eiro Damne	rs	1		il e a comita a la				
4.	Smoke Ma	nagement System	(Provided and maintained		by Mall management)				
77.1	Basements		30 a/c per hour		As per mall		MR		
	Upper floor	\$	12 a/c per h	our	As per mall		MR		
	Fire Exting	uishers	T = 223		1 /3				
5.	Total numb	ers	06 Nos.		06 Nos.		MR		
	Types		ABC/Co2 Type	2	04-ABC & 2 Co2		MR		
	IC marking		Required (Provided and maintained)		Provided		MR		
6.	m: - Aid H	ose Reels	02	intained	by Mall management)				
<u>U.</u>	Total numbers on each Hoor		30 m		Provided with mall		MR		
	Length of hose reel hose		5 mm		Provided		MR		
	Nozzle dian	eter fire detection and alarmin		ed and -	Provided		MR		
7.	Automatic	ectors	Smoke/ Hea	it and n	naintained by Mall man Provided in restaurant	ageme			
	Type of detectors Location of Main Panel						MR		
	Location of Repeater Panel				As per mall				
	Alternate so	urce of power	Required		As per mall				
	Hooters' Lo	cation	Required		Provided Provided		MR		
8.	MOEFA		Required		Provided in restaurant Provided	-	MR		
			ar		Trovided		MR		

		F						
		Required	As per mall	MR				
	Public Address System	(Available with mall)						
).	Automatic Sprinkler System	(Avanable						
0.	Basement	Required	Provided in restaurant	MR				
	Upper Floor	Required	Provided in restaurant	MR				
	Sprinkler above false ceiling							
	Internal Hydrants							
11.		4'	Provided with mall	MR				
	Size of riser/down-comer	01	As per mall	MR				
	Number of hydrants per floor	01	As per mall	MR				
	Hose Box							
2.	Yard Hydrants							
	Total number of hydrants	NA	As per mall	MR				
	Hose Box	NA	As per mall	MR				
3.	Hose Box Pumping Arrangements (Provided and maintained by Mall management)							
_	Ground Level							
	Discharge of main Pump	NA	NA					
		NA	NA NA	NA				
	Head of Main pump			NA				
	Number of main pumps	NA	NA	NIA				
	Jockey Pump out put	NA	NA	NA				
	Jockey pump head	NA	NA	NA				
	Standby Pump out put	NA	NA	NA				
	Standby Pump Head	NA	NA	NA				
	Auto Starting/Manual Stopping	NA	NA	NA				
	Pump House Access	NA	NA	NA NA				
	Terrace level							
	Discharge of pump 450 lpm As power!							
	Head of the pump	35 m	As per mall	MR				
	NAME OF THE PARTY	23 III	As per mall					
	Power Supply	Required	Λο == 11					
1.	Auto Starting of pump	Required	As per mall					
Ϊ.	Captive Water Storage for fire fighting (Provided and maintained by Mall management)							
	Indonesia I I							
	Draw-off connection	1,50,000 ltrs						
	Fire service inlet	NA						
	Access to tank	NA						
15.	Overhead Tank capacity	NA	As above	NA				
	Exit Signage.	NA	As above	MR				
i	n e	Required	As above	MR				
•	Provision of Lifts. (Provided and maintained by Mall management)							
	Pressurization of Lift Shaft							
	Pressurization of Lift lobby	NA	NA	NA				
	Communication In lift Car	NA	NA	NA				
	Fireman's Grounding Switch	NA	NA	NA				
	Lift Signage	NA	NA	NA				
1.	Standby power supply	NA	NA	NA				
18.	power supply	Required	As above	MR				
	Refuge Area							
	Total Area		(Provided and maintained by Mall management)					
	Location	NA NA	NA	NA				
19.	Fire Control Room	NA (Provided and mainta	NA	NA				
	(Frovided and maintained by Mail management)							
	Detector System Panel	NΛ	NA	NA				
	Flow Switch Panel	NA	NA	NA				
	DA Caret							
	PA System Panel Battery backup	NA	NA	NA NA				

N

4

The fire protection systems provided in the building were tested, checked and found functional at the

Keeping in view of deemed compliance of the minimum standards of fire prevention and fire safety measures as required under rules it is **recommended to renew** the Fire Safety Certificate Service Rules, 2010.

Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/Jawala Puri.

Dy Cholips