GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

No. F.6/DFS/MS/EH/2025/SZ/ 356

Dated:

24/10/2025

FIRE SAFETY CERTIFICATE

Certified that the M/s Kali Ghata Mishthan Bhandar Private Limited located at Property No. A-1/163A, GF, Pankha Road, Janakpuri, New Delhi-110058, running at ground floor only in a building comprised of basement (closed) and ground floor (restaurant), owned/occupied by Kali Ghata Mishthan Bhandar Private Limited, have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010. and verified by the officer concerned of this department on dated 10.10.2025 in the presence of Sh. Naveen Gupta, and found that the building is fit for occupancy Class "D" "Assembly Building" (for ground floor only) w.e.f. 24110 2025 with a period of three years, in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on _______ 24/10/2025_ at New Delhi.

O(A.K. Malik)
Dy. Chief Fire Officer

South Zone

Online application Id 2025092213643 dated 24.09.2025.

Copy to: - The Executive Engineer (Building), MCD, Civic Centre, Minto Road, New Delhi. : - for information regarding use of basement and a request to ensure the occupancy as detailed above and deviation, if any.

Conditions for validity of Fire Safety Certificate:-

- All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement shall be used as per BBL/UBBL.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building

M/s Kali Ghata Misthan Bhandar Private Limited at A-1/163A, GF

Pankha Road, New Delhi- 110058

Building is comprised of 2.

: Basement (closed) and ground floor (restaurant) only.

Type of Occupancy 3.

Group D (Assembly) Restaurant running at ground floor only.

4. Type of Case

New Case (Eating House)

5. Details of Previous NOC

N/A

6. Fire Safety directives letter No

N/A

7. Date of inspection

8. Name of Inspecting Officers

08.10.2025

A.D.O. R.K. Yadav (JKP)

9. Name and designation of officers

From the building side

Sh. Naveen Gupta

10. Year of Construction

1984 (As per online application)

11 Applicant's letter No.

MHA Portal ID 2025092213643 dated 24.09.2025

0.	Minimum Standards on fire prevention and fire safety U/R 33	UBBL/NBC- 2016 Requirement	Provided at site	Remarks MR/NMR			
•	Access to building						
	Road width	06 m	Provided	MR			
	Gate width	4.5 m	Provided	. MR			
	Width of internal road	N/A	N/A	N/A			
Ĺ	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases Restaurant at Ground floor only						
	Upper Floors	N/A	N/A	GF only			
	Basements	N/A	N/A	N/A			
	b. Width of staircases		French Co.				
	Upper Floor	N/A	N/A	GF only			
	Basements	N/A	N/A	N/A			
	B. d. diam - Familia	11/41	Section 2017				
	c. Protection of exits • Fire check door	N/A	N/A	N/A			
	Pressurization	N/A	N/A	N/A			
		IV/A	1971	5 70 745			
	d. No. of continuous staircases to	N/A	N/A	N/A			
	terrace	N/A	N/A	N/A			
	e. Width of Corridor		2000/20	MR			
	f. Door Size	1.50 m (02 nos.)	2.0, 1.50, 1.0 & 1.0 m	MIK			
3.	Compartmentation						
	Fire check door	N/A	N/A	N/A			
	 Sealing of electrical shafts 	N/A	N/A	N/A			
	 Fire Rating of shaft door 	N/A	N/A	N/A			
	Water Curtain	N/A	N/A	N/A			
	Fire Dampers	N/A	N/A	N/A			
4.	Smoke Management System						
	Basements	N/A	N/A	N/A			
	Upper floors	Required	Provided	MR			
5.	Fire Extinguishers						
	Total numbers in restaurant	08 no.'s	Provided	M/R			
	• Types	ABC/CO ₂	ABC- 04 & Co2- 04	M/R			
	IS marking	ISI marked	Provided	M/R			
6.	First-Aid Hose Reels						
	Total numbers at each floor	1 Nos.	Provided	M/R			
	 Length of hose reel hose 	30 mtrs	Provided	M/R			
	Nozzle diameter	5 mm	Provided	M/R			

7.	Automatic fire detection and alayming	matic fire detection and alarming system in restaurant				
-	Type of detectors S			12.0		
	 Type of detectors Smoke/Heat Location of Main Panel 	N/A	N/A	N/A		
	Location of Repeater Panel	N/A	N/A	N/A		
	 Alternate source of power 	N/A	N/A	N/A		
	Hooters' Location	N/A N/A	N/A	N/A		
8.	MOEFA		N/A	N/A		
9.		Required	Provided	M/R		
	Public Address System	N/A	N/A	N/A		
10.	Automatic Sprinkler System					
	Basement	N/A	N/A	3174		
	Upper floors	N/A	N/A	N/A N/A		
	Sprinkler above false ceiling	N/A	N/A	N/A		
11.	Internal Hydrants					
	Size of riser/down-comer	100 mm				
	Number of hydrants	01 no's	Provided	M/R		
	Hose Box	01 no's	Provided	M/R		
12.	Yard Hydrants	01 110 \$	Provided	M/R		
		1,00	Y .			
	Total number of hydrants Hose Box	N/A	N/A	N/A		
12		N/A	N/A	N/A		
13.	Pumping Arrangements					
	Ground Level					
	Discharge of main Pump	N/A	N/A	N/A		
	➤ Head of Main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	 Jockey Pump out put Jockey pump head 	N/A	N/A	N/A		
	Jockey pump nead	N/A	N/A	N/A		
	➤ Standby Pump out put	N/A	N/A	N/A		
	> Standby Pump Head	N/A	N/A	N/A		
	➤ Water curtain Pump	N/A	N/A	N/A		
	➤ Auto Starting/Manual Stopping	N/A	N/A	N/A		
	> Pump House Access	N/A	N/A	N/A		
	Terrace level	900 LPM	900 LPM	M/D		
	Discharge of pump	40 m	40 m	M/R M/R		
	➢ Head of the pump➢ Power Supply	Required	Provided	M/R		
	> Auto Starting of pump	Required	Provided	M/R		
14.		an N	** Windowski visit (1		
14.	Captive Water Storage for fire-fighting					
	Underground tank capacity	N/A	N/A	N/A		
	Draw-off connection	N/A	N/A	N/A		
	Fire service inlet	N/A	N/A	N/A N/A		
	Access to tank	N/A	N/A	M/R		
	Overhead Tank capacity	20,000 ltrs	Provided	M/R M/R		
15.	Exit Signage.	Required	Provided	IVI/K		
16.	Provision of Lifts					
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A N/A		
	Communication In lift Car	N/A	N/A	N/A N/A		
	Fireman's Grounding Switch	N/A	N/A	N/A		
	Lift Signage	N/A	N/A	723		

47.	Standby	y power supply	Required	Provided	M/R	
18.	Refuge	Aṛea.	w .57 m			
	4	Total Area	N/A	· N/A	N/A	
	1,000	Location	N/A	N/A	N/A	
19.	Fire Control Room					
	<u> </u>	N/A	N/A	N/A		
		Detector System Panel Flow Switch Panel	N/A	N/A	N/A	
	PA System Panel Battery backup Building Floor Plans	WAS PARTIES.	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	100000	N/A		
20.		Fire Protection System for on of special Risks, if any:	N/A	N/A	IN/A	

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Note: - The restaurant running at ground floor in a building comprised of basement (closed), ground floor (restaurant).

Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under Rule 35 of the Delhi Fire Service Rule 2010.

Signature of the Inspecting Officer
Name- R.K. Yadav

Designation: - ADO

17/x/35
RAJINDER ATWAL

Kincifal Director

Dp. C89 (52)

13/10/25

00(5/10)

A.K. MAL

POD