

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/EH/2025/WZ/246

Dated: 24/06/2025

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of M/s KFC Restaurant (A Unit of Sapphire Foods India Ltd) located at Ground Floor, G-5, Pushkar Enclave, Pachim Vihar, Delhi 110063 in the building comprised of Basement, Ground plus three upper floor owner/occupied by A Unit of Sapphire Foods India Ltd was issued FSC by this department vide letter F6/DFS/MS/WZ/EH/2022/149 dated 31/05/2022. The restaurant premise was re-inspected by the officer concerned of this department on 16/06/2025 in the presence of Mr. Gautam (Manager) and found that the said restaurant premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the building/premises is fit for occupancy Class-D "Assembly Building" and validity upto 31/03/2028 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on $\frac{\cancel{8}\cancel{4}/\cancel{0}\cancel{6}}{\cancel{2025}}$ at New Delhi by

(ATU), GARG) DIRECTOR ELHI FIRE SERVICE

Copy to: -

1. The Addl. Commissioner of Police (Lic./Branch), 1st Floor, P.S. Defence Colony, New Delhi-110049. (Ref. MHA Portal ID 2025060309516 dated 03/06/2025)

Conditions for the validity of Fire Safety Certificate: -

- 1. The FSC is Valid for Ground floor only.
- 2. All the means of escape/entry/exit shall be kept free from any obstruction.
- 3. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 4. All the staff members must know the correct method of operation of fire-fighting system.
- 5. Basement shall be used as per BBL.
- 6. The owner/occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

a recorded	
~	- 0

		INSPECTION REPORT		आज़ादीका अमृत महोत्स्व + + C-5 Pishkar Enclave,	
1	Name & Address of the Building	M/s KFC Restaurant at G-5, Pushkar Enter			
2	Type of Occupancy	Cours D Assembly Duilding.			
3	Building Comprised of	Basement, Ground plus 03 upper floors			
4	Type of Case	Renewal F6/DFS/MS/WZ/EH/2022/149 dated 31/05/2022			
5	Details of Previous NOC				
6	Fire Safety Directives Letter No	NBC Part-IV		7	
7	Date of Inspection	16/06/2025	4DO		
8	Name of the Inspecting Officers	Sh. Suman Kumar ADO			
9	Name & Designation of Officers	The Contest (VISITABLE)			
	from the building side	2000			
10	Year of construction	2000 MHA Portal ID 2025060309516 dated 03/06/2025			
11	Applicant letter No.			Remarks	
S. No.	Minimum standards on Fire Prevention	UBBL/NBC Requirement	Provided at Site	MR/NMR	
0 H	and Fire Safety U/R 33	-	malgaold A	MR	
1	Access to Building.	06 mtr	Provided	MR	
	Road width	4.5 mtr	Direct accessible	N/A	
	Gate width	N/A	N/A	N/A	
6/12	Width of internal road		Organ Days Hall Sci.		
2	Number, width, type & arrangement of ex	silvand imag	Still County of	27/4	
V.R.	a) Number of Staircase	N/A	N/A	N/A	
	> Upper floors.	N/A	N/A	N/A	
	> Basement floor.	*ijawa-suts	of administration		
	b) Width of Staircase	N/A	N/A	N/A	
	> Upper floors	N/A	N/A	N/A	
	> Basement floor	10/1	Tentre Live		
	c) Protection of exits	N/A	N/A	N/A	
	> Fire check door	N/A	N/A	N/A	
	> Pressurization	No. of the last of	N/A	N/A	
	d) No. of continuous staircase to terrace	N/A	N/A	N/A	
	e) Width of corridor	1.50 mtr x 2	1.50 mtr each	MR	
	f) Door size	1.50 ma A 2	Figure 6 retail 8	el n	
3	Compartmentation.	N/A	N/A	N/A	
4.10	Fire check door.	N/A	N/A	N/A	
14	 Sealing of electrical shafts. 	N/A	N/A	N/A	
A	 Fire rating of shaft door. 	N/A	N/A	N/A	
	Water curtain		N/A	N/A	
607	Fire dampers.	N/A	interface massiven	and the second	
4	Smoke Management system.				
	Basement	30 ACPH	N/A	N/A	
	Upper floors	12 ACPH	Provided in restt.	MR	
_	Fire Extinguishers.	77	Pine male		
5		04 No	Provided	MR	
	Total numbers	ABC/CO ₂	ABC & CO ₂	MR	
	• Types	ISI marked	Provided	MR	
	ISI Marking	131 Harkon			
6	First Aid Hose Reels.	One	Provided	MR	
	Total numbers on each floor.	30m	Provided	MR	
	 Length of hose-reel hose. 			MR	
	Nozzle Diameter	5mm	Provided	IVIK	
7	Automatic fire detection & alarming system	em.	ed towermed) a	-(
	Type of detectors	N/A	N/A	N/A	
	Location of Main Panel	N/A	N/A	N/A	
1			The second secon	The state of the s	

7/	
आज़ा	री का
अमृ	त महोत्सव

			7	
	N-	6	आज़ अ	गदीका मृत महोत
_	Alternate source of power	N/A	N/A	N/
	Hooter's location	N/A	N/A	N/
8	MOEFA	Required	Provided	M
9		N/A	NA	
	Public Address System		IM	N/
10	Automatic Sprinkler System	N/A	N/A	N
	Basement	N/A	Provided	N/A
	Ground floor. Classifies.	N/A	N/A	N/A
	Sprinkler above false ceiling	1021	IVA	N/A
11	Internal Hydrants.	100 mm	Provided	100
	Size of Riser/Down-comer	One	Provided	MR
	Number of Hydrant per floor	TO THE	N 10500 10	MR
	Hose box.	One	Provided	MR
12	Yard Hydrants.		1	
THE	Total number of hydrants.	N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
13	Pumping arrangements.			
H	Ground Level	27/4	77/4	1 377
	Discharge of main pump.	N/A	N/A	N/A
	➤ Head of main pump.	N/A	N/A	N/A
	Number of main pumps.	N/A	N/A	N/A
	Jockey Pump output.Jockey Pump head.	N/A	N/A	N/A
	> Standby Pump output.	N/A	N/A	N/A
	> Standby Pump head.	N/A	N/A	N/A
	Auto Starting/Manual Stopping.	N/A	N/A	N/A
+ 1	Pump house access.	N/A	N/A	N/A
	Terrace Level		in Vir ion III ad	7
	Discharge of pump.	450 LPM	Provided	MR
	➤ Head of pump.	40 m	Provided	MR
- 1	Power supply.	Required	Provided	MR
	Auto starting of pump.	Required	Provided	MR
14	Captive water storage for fire fighting.		resik = 1	
	 Underground tank capacity. 	N/A	N/A	N/A
	Draw-off connection.	N/A	N/A	N/A
	Fire Service Inlet.	N/A	N/A	N/A
	Access to tank.	N/A	N/A	N/A
- }	Overhead tank capacity.	20,000 Ltrs	Provided	MR
5	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	70/29/	manife and a sound	
	Pressurization of lift shaft.	N/A	N/A	N/A
	 Pressurization of lift lobby. 	N/A	N/A	N/A
	Communication in lift car.	N/A	N/A	N/A N/A
	Fireman's switch.	N/A	N/A	N/A N/A
	Lift signage.	N/A	N/A	2//2/21
_	Standby Power Supply	N/A	N/A	N/A
8	Refuge Area			
	Total area	N/A	N/A	N/A
	Location	N/A	N/A	N/A
9 1	Fire Control Room.		27/4	N/A
	Detector system panel.	N/A	N/A	N/A N/A
	Flow switch panel.	N/A	N/A	
	PA system panel. Battery backup	N/A	N/A	N/A
1	 Battery backup. 	N/A	N/A	N/A



	Building floor plan.	N/A	N/A	N/A
	Special Fire Protection System for the	N/A	N/A	N/A
	Protection of special Risk, if any.			

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/WZ/EH/2022/149 dated 31/05/2022, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

19/18/06/2025

Signature of the Inspecting Officer Name: Sh. Suman Kumar Design: ADO

DCFO(WZ) - On Leave

Defor AW -

1818 hr

19 19 30x

Déneeta Mil of 8

Andre

F.T. letter is but up for egg li

Go 25/06/20

Pirector

5/11/30 1/1/9/9/3/

4