



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No.F6/DFS/MS/School/SZ/2025/ 821

Dated: 24/06/2025

**FIRE SAFETY CERTIFICATE**

Certified that the Khadijatul Kubra Girls Public School located at 8/1, Joga Bai, Jamia Nagar, New Delhi-25, was granted Fire Safety Certificate by this department vide letter no. F6/DFS/MS/School/2021/SZ/1016 dated 16.12.2021. The school building was re-inspected by Assistant Divisional Officer (M. Road) from this department on 17.06.2025 in the presence of Mr. Talha (Manager) and found that the school building is comprised of two block namely:- **Sr. Block** - Basement (found closed) + Ground + 03 upper floors & **Jr. Block** - Sunken Ground+ Lower Ground + Ground + 03 upper floors, both blocks are interconnected at each floor level. The school building have deemed complied with the fire prevention and fire safety requirements in accordance with the circular no. 262-362 Dated-17/01/2005 issued by the Director of Education and the building is fit for occupancy of Group B "**Educational Building**" with effect from 24/06/2025 renewed for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire Service Rules, 2010 printed below.

Issued on...24/06/2025.....at New Delhi by

(Atul Garg)  
Director  
Delhi Fire Service

**Copy to:-**

1. The Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi.
2. The Principal, Khadijatul Kubra Girls Public School located at 8/1, Joga Bai, Jamia Nagar, New Delhi-25.

**Conditions for the validity of Fire Safety Certificate**

1. All the means of escape shall be kept free of all the type of obstruction all the time.
2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
5. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in).
7. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub Rule (1) of Rule 37] along with a copy of this certificate, six months prior to its expiry.



PIL 2/18

## INSPECTION REPORT

1	Name & address of the building	Khadijatul Kubra Girls Public School located at 8/1, Joga Bai, Jamia Nagar, New Delhi-25.		
2	Building is comprised of	<b>Comprised of 02 blocks Namely:</b> <b>Sr. Block</b> – Basement (found closed) + Ground + 03 upper floors <b>Jr. Block</b> - Sunken Ground+ Lower Ground + Ground + 03 upper floors <b>Both blocks are interconnected at each floor level</b>		
3	Type of occupancy	Group B- Educational Building (School)		
4	Type of case	Renewal		
5	Details of previous FSC	F6/DFS/MS/School/2021/SZ/1016 dated 16.12.2021		
6	Fire safety direction letter no.	DOE circular dated 17.01.2005		
7	Date of inspection	17.06.205		
8	Name of the inspecting officers	Rajesh Kumar Shukla, ADO (M.Road)		
9	Name of the designation of officer from the building side	Mr. Talha (Manager)		
10	Year of construction	2009-10		
11	Applicant's letter no.	Outdoor diary no. 2524 dated 06.06.2025		
S.No	Minimum standard of fire prevention and fire safety U/R 33	Requirement as per Rule 35 (6)	Provided at site	Remarks MR/NMR
1.	<b>Access to Building:</b>			
	A	Road width	Required	Accessible to fire engine
	B	Gate width	NA	NA
	C	Width of internal road	NA	NA
2.	<b>Number, Width, Type and Arrangement of Exits:</b>			
	A	Number of staircases		
	a	Upper floor	03 nos.	03 nos.
	b	Basement	NA	(found closed)
	B	Width of staircases		
	a	Upper floor	Required	1.50 m, 1.0 m & 1.10 m
	b	Basement	NA	NA
	C	Protection of exits		
	a	Fire check door	NA	NA
	b	Pressurization	NA	NA
	D	No. of continuous staircases to terrace	02 nos.	Provided
	E	Width of corridor	1.50 m	Provided
	F	Door size	1.0 mtrs (for class room)	Provided
3.	<b>Compartmentation:</b>			
	A	Fire check door	NA	NA
	B	Sealing of electrical shafts	NA	NA
	C	Fire rating of shaft door	NA	NA
	D	Water curtain	NA	NA
	E	Fire dampers	NA	NA
4.	<b>Smoke Management System:</b>			
	A	Basement	NA	NA
	B	Upper floor	NA	NA
5.	<b>Fire Extinguisher:</b>			
	A	Total numbers	26 nos.	Provided
	B	Types	CO <sub>2</sub> & ABC	Provided
	C	ISI marking	Required	Provided

20/19

<b>6</b>	<b>First-Aid-Hose Reel:</b>			
<b>A</b>	Total numbers of each floor	01 no. in both block	Provided	MR
<b>B</b>	Length of hose reel hose	30 mtrs in both block	Provided	MR
<b>C</b>	Nozzle diameter	5 mm in both block	Provided	MR
<b>7</b>	<b>Automatic Fire Detection and Alarming System:</b>			
<b>A</b>	Type of detectors	NA	NA	NA
<b>B</b>	Location of main panel	NA	NA	NA
<b>C</b>	Location of repeater panel	NA	NA	NA
<b>D</b>	Alternate source of power	NA	NA	NA
<b>E</b>	Hooters	NA	NA	NA
<b>8</b>	<b>MOEFA:</b>	NA	NA	NA
<b>9</b>	<b>Public Address System:</b>	NA	NA	NA
<b>10</b>	<b>Automatic Sprinkler System:</b>			
<b>A</b>	Basement	NA	NA	NA
<b>B</b>	Upper floor	NA	NA	NA
<b>C</b>	Sprinkler above false ceiling	NA	NA	NA
<b>11</b>	<b>Internal Hydrants:</b>			
<b>A</b>	Size of riser/down-comer	NA	NA	NA
<b>B</b>	Number of hydrants per floor	NA	NA	NA
<b>C</b>	Hose box	NA	NA	NA
<b>12</b>	<b>Yard Hydrants:</b>			
<b>A</b>	Total number of hydrants	NA	NA	NA
<b>B</b>	Hose box	NA	NA	NA
<b>13</b>	<b>Pumping Arrangements:</b>			
<b>A</b>	<b>Ground level</b>			
<b>a</b>	Discharge of main pump	NA	NA	NA
<b>b</b>	Head of main pump	NA	NA	NA
<b>c</b>	Number of main pumps	NA	NA	NA
<b>d</b>	Jockey pump out put	NA	NA	NA
<b>e</b>	Jockey pump head	NA	NA	NA
<b>f</b>	Standby pump out put	NA	NA	NA
<b>g</b>	Standby pump head	NA	NA	NA
<b>h</b>	Auto starting /manual stopping	NA	NA	NA
<b>i</b>	Pump house access	NA	NA	NA
<b>B</b>	<b>Terrace Level</b>			
<b>a</b>	Discharge of pump	450 + 180 LPM	450+450+180LPM	MR
<b>b</b>	Head of the pump	40 mtrs	Provided	MR
<b>c</b>	Power supply	Required	Provided	MR
<b>d</b>	Auto starting of pump	Required	Provided	MR
<b>14</b>	<b>Captive Water Storage for Fire Fighting:</b>			
<b>A</b>	Underground tank capacity	NA	NA	NA
<b>B</b>	Draw-off connection	NA	NA	NA
<b>C</b>	Fire service inlet	NA	NA	NA
<b>D</b>	Access to tank	NA	NA	NA
<b>E</b>	Overhead tank capacity	5 KL	38 KL	MR
<b>15</b>	<b>Exit Signage:</b>	Required	Provided	MR



<b>16</b>	<b>Provision of Lifts:</b>			
	<b>A</b>	Pressurization of lift shaft	NA	NA
	<b>B</b>	Pressurization of lift lobby	NA	NA
	<b>C</b>	Communication in lift car	NA	NA
	<b>D</b>	Firemen's grounding switch	NA	NA
	<b>E</b>	Lift signage	NA	NA
<b>17</b>	<b>Standby Power Supply:</b>		NA	NA
<b>18</b>	<b>Refuge Area:</b>			
	<b>A</b>	Total area	NA	NA
	<b>B</b>	Location	NA	NA
<b>19</b>	<b>Fire Control Room:</b>			
	<b>A</b>	Detector system panel	NA	NA
	<b>B</b>	Flow switch panel	NA	NA
	<b>C</b>	PA system panel	NA	NA
	<b>D</b>	Battery backup	NA	NA
	<b>E</b>	Building floor plans	NA	NA
<b>20</b>	<b>Special Fire Protection systems for protection of special Risks, if any:</b>		NA	NA

**LEGENDS: Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided but Not Functional (PNF), Not Provided (NP).**

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

The shortcomings issued to the school by this department vide letter no. F6/DFS/MS/School/SZ/2025/448 dated 26.05.2025 has been rectified by the school management.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required in Directorate of Education Circular no. 262-362 dated 17.01.2005, the FSC issued vide letter no. F6/DFS/MS/School/2021/SZ/1016 dated 16.12.2021 is recommended to be renewed.

18/6/2025.

Signature of the Inspecting Officer  
Name Rajesh Kumar Shukla  
Designation ADO (M. Road)

DO (SD) 18/6/2025

CPO 20/6/2025

Director 27/6/25

ms-