## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001



DFS/MS/GH/2025/NDZ/ 340

## FIRE SAFETY CERTIFICATE

Dated: 15/05/202

Certified that the Kingston Park Guest House located at 8/5, W.E.A., Karol Bagh, New Delhi-110005 comprised of Basement (Incidental Storage), Ground Floor (Reception & 03 Guest Rooms), 1st floor to 3rd floor (07 Guest rooms at each floor) was issued FSC by this department vide letter No F6/DFS/MS/GH/SZ/2022/259 dated 06.06.2022. The premise was re-inspected by the officer concerned of this department on 03.05.2025 in the presence of Sh. Gurpreet Singh and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have therefore complied with fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premise is fit for occupancy "Class A, Residential (Guest House for, total 24 Guest Rooms from Ground floor to 3rd floor only)" with effect from ... 15. 25. 2025. and valid up to 31.03.2028 in accordance with the Puls 26. with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40, subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010

Issued on .... 15 05 2025 at New Delhi, by

Delhi Fire Service see a

Copy to: -

- 1. The Commissioner, MCD, Civic Centre, New Delhi- to ensure the occupancy as
- 2. M/s Kingston Park Guest House located at 8/5, W.E.A., Karol Bagh, New Delhi-110005.
- 3. MCD Portal, ID No. 2025041906744

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned
- This certificate cannot be treated in any case for regularizations of unauthorized
- The owner/occupier shall apply for renewal of this Fire Safety Certificate through MCD portal (https://www.mcdonline.nic.in) along with a copy of this Certificate, six
- The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on
- 8. This FSC is only for total 24 guest rooms from Ground floor to 3<sup>rd</sup> floor only.
- The basement shall be used strictly as per BBL. Basement shall be used for incidental storage only.

& address of the building: Kingston Park Guest House located at 8/5, W.E.A., Karol Bagh, INSPECTION REPORT Delhi- 110005. Type of Occupancy Residential (A-1) (Total 24 Guest Rooms) Building Comprised of Basement (Incidental Storage), Ground Floor (Reception & 03 Guest Rooms), 1st Floor to 3rd floor (07 Guest Rooms at each floor) Type of Case Details of Previous NOC F6/DFS/MS/GH/SZ/2022/259 Dated 06/06/2022 6. Fire Safety directives letter No 7. Date of inspection 8. Name of Inspecting Officer 03/05/2025 Name and designation of officers R.K.Sinha, ADO (BW) 10. From the building side Sh. Gurpreet Singh 11. Year of Construction 12. Applicant's letter No. Before 2009 MCD Application ID No. 2025041906744 dated 19/04/2025 Minimum Standards on fire S. Old case prevention and fire safety U/R 33 No. Requirement Remarks Provided at site Existing fire safety MR/NMR 1. Access to building arrangements Road width MR 6 m Provided Gate width NA Width of internal road NA Directly accessible NA 2. NA NA Number, Width, Type & Arrangement of Exits Number of staircases Upper Floors MR 01 01 Basements MR 02 02 Width of staircases Upper Floor MR(old case) 1.39 m Old case Basements MR(old case) Old case 1.28 m & 0.88 m Protection of exits Fire check door MR Provided Required Pressurization NA NA NA No. of continuous staircases to 01 MR 01 terrace Width of Corridor Old Case 1.50 m MR(old case) Old case 0.84 m & 2.15 m MR(old case) Door Size 3. Compartmentation Required Fire check door Provided MR Required Provided Sealing of electrical shafts MR NA Fire Rating of shaft door NA NA NA Water Curtain NA NA Fire Dampers NA NA NA **Smoke Management System** 4. Basements Required Exhaust fan provided MR Upper floors Required Provided MR 5. Fire Extinguishers Total numbers 02 Nos. at each floor Provided MR **Types** ABC/Co2 Type Provided MR IS marking Required Provided MR First-Aid Hose Reels 6. Total numbers on each floor 01 Provided NA Length of hose reel hose 30 m 30 m Nozzle diameter MR 5 mm 5 mm Automatic fire detection and alarming system 7. MR Type of detectors CO Provided

	Location of Main Panel	p. 27		
	Location of Repeater Panel	Ground Floor	Provided	MR
	Alternate source of power	NA	NA NA	NA NA
	Thernate source of power	Required	Provided Provided	MR
	Hooters' Location	Each Floor	Provided	MR
	MOEFA	Required	Provided	MR
	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	Basement	Required	Provided	MR
	Upper Floor	NA	NA	NA
		NA NA	NA	NA NA
	Sprinkler above false ceiling	11		NA
11	Internal Hydrants Size of riser/down-comer	NA	NA	
	Number of hydrants per floor	NA NA	NA NA	NA
	Hose Box	NA	NA	NA
12.	Yard Hydrants		1111	NA
	Total number of hydrants	NA	NA	NIA
	Hose Box	NA	NA	NA NA
13.	Pumping Arrangements			INA
	Compliant			
	Ground Level			
	Discharge of main Pump	NA NA	NA	NA
	Head of Main pump	NA	NA	NA
	Number of main pumps	NA	NA	NA
	Jockey Pump out put	NA	NA	
	Jockey pump head	NA	NA	NA NA
	Standby Pump out put	NA	NA	NA NA
	Standby Pump Head	NA	NA	NA NA
	Auto Starting/Manual Stopping	NA	NA	NA NA
	Pump House Access	NA	NA	NA NA
	Terrace level			INA
	Discharge of pump	450 lpm	Provided	
	Head of the pump	40 m	Provided	MR
	Power Supply	Required	Provided	MR
	Auto Starting of pump	Required	Provided	MR
14.	Captive Water Storage for fire figh	iting	Tiovided	MR
	Underground tank capacity NA NA NA			
	Draw-off connection	NA	NA	NA
	50 (46, 487)(43)	NA	NA	NA
	Fire service inlet	NA	Provided	NA
	Access to tank	NA	NA	NA
15.	Overhead Tank capacity  Exit Signage.	Old case	5000 ltrs ·	MR( old case
16.	-	Required	Provided	MR
10.	Provision of Lifts.			
	Pressurization of Lift Shaft	NA	NA	NA
	Pressurization of Lift lobby	NA	NA	NA NA
	Communication In lift Car	NA NA	NA NA	NA NA
	Fireman's Grounding Switch	Required	Provided	MR
	Lift Signage		Provided	MR
17.	Standby power supply	Required Required	Provided	
18.	Refuge Area.	Required		MR
	Total Area	NA.	374	T
	Location	NA NA	NA NA	NA NA
19.	Fire Control Room	INA	INA	INA
	Detector Suntain Day			1
	Detector System Panel	NA NA	NA NA	NA
	Flow Switch Panel	NA NA	NA NA	NA
	PA System Panel			NA
	Battery backup	Required	Provided	MR

9/

NA wilding Floor Plans NA NA NA iding Fire Protection System for NA NA MR pecial Risks, if any: NA The fire protection systems provided in the building were tested, checked and found MR MR functional at the time of inspection. Keeping in view of compliance of the minimum standards of fire prevention and fire neasures as required with MR safety measures as required under rules it is recommended to renew the fire safety certificate issued vide letter no. FG/DESA College is the recommended to renew the fire safety certificate MR issued vide letter no. F6/DFS/MS/GH/SZ/2022/259 dated 06/06/2022 under rule 37 of the Delhi Fire Service Rules 2010/10 Delhi Fire Service Rules, 2010 if agreed. Accordingly DFA is placed on file, please. Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W.